Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20006328/KQF3E2

Date: 23/07/2020

REFERENCE

No:

Handling Insurer: China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00036012005

Claimant Vehicle

1t venicie _{SLN2882S}

Insured Vehicle No :

GBB5256L

Date of Loss: 1

15/06/2020 Nature of Claim:

Claim No:

SNM20D202119/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLN2882S

 Make & Model:
 HONDA VEZEL, 1.5 (A)
 Engine No:
 L15B4405191

 Reg. Date:
 04/05/2017 (Man. Year: 2016)
 Chassis No:
 RU11205190

 Colour:
 Metallic Blue
 Odometer:
 114604 km

TP

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Firenza 7 mm Rear Left Side: Firenza 7 mm
Front Right Side: Firenza 7 mm
Rear Right Side: Firenza 7 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts | 2,704.00 | 2,369.00 | 335.00 | 12.39 |
| Miscellaneous Items | 150.00 | 120.00 | 30.00 | 20.00 |
| Labour | 1,620.00 | 1,410.00 | 210.00 | 12.96 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 4,474.00 | 3,899.00 | 575.00 | 12.85 |
| Approved Total (Overridden) (S\$) | | 3,100.00 | | |
| (S\$) | 4,474.00 | 3,100.00 | 1,374.00 | 30.71 |
| + GST 7.00/7.00% (S\$) | 313.18 | 217.00 | 96.18 | 30.71 |
| Nett Amount (S\$) | 4,787.18 | 3,317.00 | 1,470.18 | 30.71 |

INSPECTION

Date of Assignment: 16/06/2020

Date Inspected: 16/06/2020 Inspected At: 10 ANG MO KIO IND PARK 2A #01-04

Repairer : Cheng Hoe Motor Pte Ltd

Estimated Period of Repair: 5.0 days

Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Jul 2020)

Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLN2882S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount | |
|-------|--------|----------|--|-------------------|------------|-----------|--|
| 1 | 1 | | *1 pc front RH fender | Bent | 190.00 F | *190.00 F | |
| 2 | 1 | | *1 pc front RH fender inner shield | Cracked | 80.00 F | *80.00 F | |
| 3 | 1 | | *6 pcs front RH fender inner shield clips @ \$2/pc | Necessary | 12.00 F | *12.00 F | |
| 4 | 1 | | *1 pc front RH fender wheel arch garnish | Bent | 55.00 F | *55.00 F | |
| 5 | 1 | | *1 pc RH headlamp | Mtg Cracked | 830.00 F | *830.00 F | |
| 6 | 1 | | *1 pc front RH door | Bent | 530.00 F | *530.00 F | |
| 7 | 1 | | *1 pc front RH door frame sticker | Necessary | 12.00 F | *12.00 F | |
| 8 | 1 | | *1 pc front RH door checker | Serviceable | 40.00 F | *- F | |
| 9 | 1 | | *1 pc front RH door top hinge | Distorted | 30.00 F | *30.00 F | |
| 10 | 1 | | *1 pc front RH door side mirror outer cover | Dented / Cut | 60.00 F | *60.00 F | |
| 11 | 1 | | *1 pc front RH rim | Dented | 350.00 F | *350.00 F | |
| 12 | 1 | | *1 pc front RH shock absorber | Bent | 220.00 F | *220.00 F | |
| 13 | 1 | | *1 pc front RH knuckle arm | Serviceable | 195.00 F | *- F | |
| 14 | 1 | | *1 pc front RH wheel bearing | Not Necessary | 100.00 F | *- F | |
| F=Fra | nchise | part. | | Total Parts (S\$) | 2,704.00 | 2,369.00 | |

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

| No | Qty | Particulars | | Repairer's | Amount | | |
|------|---------------------|--------------------------------|-----------------|------------|--------|--|--|
| Misc | Miscellaneous Items | | | | | | |
| 1 | 1 | 1 set sun shade (NECESSARY) | | 150.00 | 120.00 | | |
| | | | Sub Total (S\$) | 150.00 | 120.00 | | |

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|---|--------------|------------|----------|
| Lab | our Items | | | |
| 1 | Remove & refix front bumper & attachments,headlamps,frt RH fender,frt RH door & attachments;knocking & repair front RH fender inner panel & realign bonnet the same | New | 600.00 | 500.00 |
| 2 | Putty & respray front bumper,front RH fender & inner panel,frt RH door,RH side mirror & all affected areas | New | 700.00 | 650.00 |
| 3 | Remove & refix front RH door window glass & reset central locking | New | 50.00 | 50.00 |
| 4 | Remove & refix front RH wheel, undercarriage & realign the same | New | 150.00 | 90.00 |
| 5 | To conduct computer wheel alignment | New | 60.00 | 60.00 |
| 6 | Rustproofing | New | 60.00 | 60.00 |
| | Gross Labou | r Cost (S\$) | 1,620.00 | 1,410.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >