

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jun 2020 11:54 Edit Reg		16 Jun 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -									
Main Claimant: ENG HOU MONG									
Vehicle Reg. No.: SLN8843R		Date of Loss: 12/06/2020 08:00 - :59 [78 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SHC1042L		Policy No. (Claimant):							
		Excess:							
Repairer: H S Automotives Pte Ltd (HQ) BLK 2 KAKI BUKIT AVENUE 2 #01-15 KAKI BUKIT AUOTHUB, 417921 Kaki Bukit - Tel:									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 25/06/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN8843R
[SHC1042L]
TP
ENG HOU MONG
Jun 12 2020 8:00AM
[-]
H S Automotives Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Photos/Images					3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	16/06/20 17:12	General View		Load JPG	☒	
2	16/06/20 17:12	General View		Load JPG	☒	
3	16/06/20 17:12	Odometer Reading		Load JPG	☒	
4	16/06/20 17:12	General View		Load JPG	☒	
5	16/06/20 17:12	General View		Load JPG	☒	
6	16/06/20 17:12	Chassis Number		Load JPG	☒	
7	16/06/20 17:12	General View		Load JPG	☒	
8	16/06/20 17:12	General View		Load JPG	☒	
9	16/06/20 17:12	General View		Load JPG	☒	
10	16/06/20 17:12	General View		Load JPG	☒	
11	16/06/20 17:12	General View		Load JPG	☒	
12	16/06/20 17:12	General View		Load JPG	☒	
13	16/06/20 17:12	General View		Load JPG	☒	
14	16/06/20 17:12	General View		Load JPG	☒	
15	16/06/20 17:12	General View		Load JPG	☒	
16	16/06/20 17:12	General View		Load JPG	☒	
17	16/06/20 17:12	General View		Load JPG	☒	
18	16/06/20 17:12	General View		Load JPG	☒	
19	16/06/20 17:12	General View		Load JPG	☒	
20	16/06/20 17:12	General View		Load JPG	☒	
21	16/06/20 17:12	General View		Load JPG	☒	
22	16/06/20 17:12	General View		Load JPG	☒	
23	16/06/20 17:12	General View		Load JPG	☒	
24	16/06/20 17:12	General View		Load JPG	☒	
25	16/06/20 17:12	General View		Load JPG	☒	
26	16/06/20 17:12	General View		Load JPG	☒	
27	16/06/20 17:12	General View		Load JPG	☒	
28	16/06/20 17:12	General View		Load JPG	☒	
29	16/06/20 17:12	General View		Load JPG	☒	
30	16/06/20 17:12	General View		Load JPG	☒	
31	16/06/20 17:12	General View		Load JPG	☒	
32	16/06/20 17:12	General View		Load JPG	☒	
33	16/06/20 17:12	General View		Load JPG	☒	
34	17/06/20 18:00	Photographs of Damaged Parts		Load JPG	☒	
35	17/06/20 18:00	Photographs of Damaged Parts		Load JPG	☒	
36	17/06/20 18:00	Photographs of Damaged Parts		Load JPG	☒	
37	17/06/20 18:00	Photographs of Damaged Parts		Load JPG	☒	
38	17/06/20 18:00	Photographs of Damaged Parts		Load JPG	☒	
39	17/06/20 18:00	Photographs of Damaged Parts		Load JPG	☒	
40	17/06/20 18:00	Photographs of Damaged Parts		Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
41	17/06/20 18:00	Photographs of Damaged Parts		Load JPG ☒
42	17/06/20 18:00	Photographs of Damaged Parts		Load JPG ☒
43	17/06/20 18:00	Photographs of Damaged Parts		Load JPG ☒
44	17/06/20 18:00	Photographs of Damaged Parts		Load JPG ☒
45	17/06/20 18:00	Photographs of Damaged Parts		Load JPG ☒
46	17/06/20 18:00	Photographs of Damaged Parts		Load JPG ☒
47	17/06/20 18:00	Photographs of Damaged Parts		Load JPG ☒
48	17/06/20 18:00	Photographs of Damaged Parts		Load JPG ☒
49	17/06/20 18:00	Photographs of Damaged Parts		Load JPG ☒
50	17/06/20 18:00	Photographs of Damaged Parts		Load JPG ☒
51	17/06/20 18:00	Photographs of Damaged Parts		Load JPG ☒
52	17/06/20 18:00	Photographs of Damaged Parts		Load JPG ☒
53	17/06/20 18:00	Photographs of Damaged Parts		Load JPG ☒
54	17/06/20 18:00	Photographs of Damaged Parts		Load JPG ☒
55	17/06/20 18:00	Photographs of Damaged Parts		Load JPG ☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	16/06/20 13:37	ASSIGNMENT FROM III		Load PDF
2	17/06/20 15:49	SLN 8843R GIA.pdf		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
1	17/06/20 08:48	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III20006331/ESF3S2**Date:** 24/06/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SLN8843R**Insured Vehicle No :** SHC1042L

Date of Loss: 12/06/2020

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLN8843R**

Make & Model: TOYOTA LEXUS, 2.5 ES300H CVT (A)

Engine No: 2AR0996807

Reg. Date: 28/11/2013 (Man. Year: 2013)

Chassis No: JTHBW1GGX02046325

Colour: Grey

Odometer: 111865 km

Engine Capacity: 2494 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Rear Tyre Size: 225/50 R17

Front Left Side: Veuro 4 mm

Rear Left Side: Veuro 4 mm

Front Right Side: Veuro 4 mm

Rear Right Side: Veuro 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/06/2020

Date Inspected: 16/06/2020 Inspected At:

H S Automotives Pte Ltd (HQ)
BLK 2 KAKI BUKIT AVENUE 2 #01-15 KAKI
BUKIT AUOTHUB
Singapore 417921

Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jun 2020)
Parts:	143	TOYOTA LEXUS 2.5 ES300H CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN8843R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >