

NOV1900113



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

ALLIED WORLD ASSURANCE COMPANY LTD
(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON

SINGAPORE 079914

INV No. AC1903204
INV Date 12/04/2019
Reference CS/AWA19004033/T1td3e2
Code AWA



PROFESSIONAL SERVICE FEE

Vehicle No. SGR 9900R
Insured Veh.
Claim No.
Policy No. BVFPSB0006781907
Accident Date 25/02/2019
Inspection Date 05/03/2019

RECEIVED
18 APR 2019

Allied World Assurance Company, Ltd

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

[Signature]

ALLIED WORLD ASSURANCE COMPANY, LTD (Claims Payment Audit Checklist)									
Fraud	Leakage	Salvage	Recovery	XOL/RI	Co-Insce	Excess	Reserving		
PAID Claims Division								17 JUN 2019	
								Handler	Authorizer
								<i>[Signature]</i>	<i>[Signature]</i>

COPY

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

ALLIED WORLD ASSURANCE COMPANY LTD
(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON

SINGAPORE 079914

INV No. AC1903204
INV Date 12/04/2019
Reference CS/AWA19004033/T1td3e2
Code AWA

**PROFESSIONAL SERVICE FEE**

Vehicle No. SGR 9900R
Insured Veh.
Claim No.
Policy No. BVFPSB0006781907
Accident Date 25/02/2019
Inspection Date 05/03/2019

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA19004033/T1td3e2

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLE TREE ANSON
SINGAPORE 079914

Date : 12-04-2019



Code : AWA

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SGR 9900R
Policy No. BVFPSB0006781907	Coverage (\$)	0.00
Claim No.	Excess (\$)	500.00
Assign From BEN TANG	Assign Date	04/03/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C200	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDD2050422R277287	Colour	BLUE
Odometer	38971	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R18	PIRELLI	6 mm
L/H Front Tyre	225/45 R18	PIRELLI	6 mm
R/H Rear Tyre	225/45 R18	PIRELLI	6 mm
L/H Rear Tyre	225/45 R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/02/2019	Inspection Date	05/03/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 45 PANDAN ROAD SINGAPORE 609286		

5a. Remarks

A) THE MARKET VALUE IS S\$140,000.00 (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 9900R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET (WCP)	BENT	1,040.00	1,040.00
1	L/BONNET HINGE (WCP)	TO REPAIR SEE LABOUR	99.00	-
1	R/BONNET HINGE (WCP)	TO REPAIR SEE LABOUR	99.00	-
1	L/BONNET LOCK (WCP)	NOT NECESSARY	35.00	-
1	R/BONNET LOCK (WCP)	NOT NECESSARY	35.00	-
1	LOGO - BONNET (WCP)	NECESSARY	42.00	42.00
1	INSULATOR BONNET (WCP)	NOT NECESSARY	132.00	-
20	INSULATOR CLIP BONNET (WCP)	NOT NECESSARY	80.00	-
1	FR GRILLE (WCP) }	DAMAGED	72.00	450.00
1	FR GRILLE MOULDING BASE (WCP) }	CRACKED	105.00	-
1	R/CHROME MOULDING GRILLE (WCP) }	CUT	42.00	-
1	L/CHROME MOULDING GRILLE (WCP)	NOT NECESSARY	42.00	-
1	EMBLEM-STAR (WCP)	NOT NECESSARY	72.00	-
1	FR BUMPER (WCP)	DEFORMED	940.00	940.00
10	FR BUMPER CLIP (WCP)	NECESSARY	40.00	40.00
1	R/OUTER GUIDE RAIL (WCP)	DEFORMED	35.00	35.00
1	R/BUMPER CARRIER (WCP)	BENT	48.00	48.00
1	R/SIDE SENSOR BUMPER (WCP)	DISTORTED	93.00	93.00
1	R/OUT SENSOR BUMPER (WCP)	DISTORTED	93.00	93.00
1	R/INN SENSOR BUMPER (WCP)	NOT NECESSARY	93.00	-
1	R/GRILLE (WCP)	CUT	38.00	38.00
1	R/LOWER CHROME MOULDING (WCP)	NOT NECESSARY	85.00	-
1	CENTER LOWER CHROME MOULDING (WCP)	NOT NECESSARY	160.00	-
1	RIGHT HEAD LAMP	CRACKED	1,580.00	1,580.00
1	R/INNER CROSSMEMBER BRACKET (WCP)	BENT	48.00	48.00
1	R/BRACKET HEAD LAMP (WCP)	NOT NECESSARY	385.00	-
1	FR REINFORCEMENT (WCP)	NOT NECESSARY	225.00	-
1	R/FR SPONGE (WCP)	DEFORMED	110.00	110.00
1	CTR FR SPONGE (WCP)	NOT NECESSARY	88.00	-
1	L/ FR SPONGE (WCP)	NOT NECESSARY	62.00	-
1	R/FR FENDER (WCP)	TO REPAIR SEE LABOUR	460.00	-
1	R/FENDER LINER FR (WCP)	DEFORMED	65.00	65.00

Report Ref No. CS/AWA19004033/T1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	R/FENDER LINER REAR (WCP)	NOT NECESSARY	65.00	-
10	R/FENDER CLIPS (WCP)	NOT NECESSARY	40.00	-
1	UPPER GARNISH INNER BUMPER A205 886 11 65 (ADDITIONAL) (WCP)	DEFORMED	42.00	42.00
1	FR GRILLE INNER GARNISH A205 505 18 30 (ADDITIONAL) (WCP)	DEFORMED	72.00	72.00
1	TUBE (ADDITIONAL) (WCP)	DISTORTED	105.00	105.00
1	UPPER CTR BRACKET A205 620 41 01 (ADDITIONAL) (WCP)	DISTORTED	115.00	115.00
1	R/GRILLE INNER GARNISH A205 885 41 23 (ADDITIONAL) (WCP)	DEFORMED	38.00	38.00
10	RIVERT (ADDITIONAL) (WCP)	NECESSARY	30.00	30.00
	COST PLUS 10%		705.00	502.40
			7,755.00	5,526.40
	<u>SPECIAL NETT ITEMS</u>			
1	BODY SEALANT (SN)	NECESSARY	60.00	40.00
1	A/C GAS (SN)	NOT NECESSARY	60.00	-
1	FRONT NUMBER PLATE (SN)	BENT	35.00	35.00
			155.00	75.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE ALL DAMAGE PARTS, FRT RHS FENDER, BONNET, BUMPER, AND OTHER BY PANEL BEATING. INCLUSIVE OF THE REPAIR OF L/BONNET HINGE, R/BONNET HINGE AND R/FR FENDER.		2,500.00	600.00
	TO SPRAY PAINTING DAMAGE PARTS AND SURFACE FRT DOOR AND PILLER.		2,200.00	750.00
	TO CHECK WIRING SYSTEM.		80.00	30.00
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	NOT NECESSARY	60.00	-
	APPLY ANTI RUST COATING.		80.00	30.00
			-	-
			-	-
			-	-
			-	-
			-	-
			4,920.00	1,410.00
	GRAND TOTAL		12,830.00	7,011.40
	RECOMMENDED COST OF REPAIRS			7,011.40

Report Ref No. CS/AWA19004033/T1td3e2



LESS EXCESS			-500.00
NETT LIABILITY			6,511.40

Report Ref No. CS/AWA19004033/T1td3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.