

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20006338/ATF3E2  
**Date:** 08/02/2021

### REFERENCE

Insured/Claimant: WONG SOK YEE Policy No: 1800149392  
Date of Loss: 09/06/2020 Nature of Claim: OD Claim No: 5972569338SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG3190Z**  
Make & Model: AUDI A3, 999cc SEDAN TFSI (A) Engine No: CZE846765  
Reg. Date: 14/12/2018 (Man. Year: 2018) Chassis No: WAUZZZ8V2K1007852  
Colour: Black Odometer: 28683 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: S\$93,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	26,573.00	17,191.92	9,381.08	35.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,244.00	9,999.00	5,245.00	34.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>41,817.00</b>	<b>27,190.92</b>	<b>14,626.08</b>	<b>34.98</b>
<b>- Excess (S\$)</b>	<b>300.00</b>	<b>300.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>41,517.00</b>	<b>26,890.92</b>	<b>14,626.08</b>	<b>35.23</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,906.19</b>	<b>1,882.36</b>	<b>1,023.83</b>	<b>35.23</b>
<b>Nett Amount (S\$)</b>	<b>44,423.19</b>	<b>28,773.28</b>	<b>15,649.91</b>	<b>35.23</b>

### INSPECTION

Date of Assignment: 10/06/2020  
Date Inspected: 10/06/2020 Inspected At: 24 BENOI SECTOR  
Estimated Period of Repair: 11.0 days Repairer : Premium Automobiles Pte Ltd

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,894.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	176.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - RH	Necessary	36.00 FS	*30.16 FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Cracked	151.00 FS	*126.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	505.00 FS	*424.00 FS
6	1		*FRONT BUMPER CLOSING ELEMENT - RH	Damaged	280.00 FS	*234.40 FS
7	1		*FRONT BUMPER COVER TRIM - RH	Missing	153.00 FS	*128.40 FS
8	1		*WHEEL HOUSING LINER ADAPTER - RH	Damaged	36.00 FS	*29.52 FS
9	1		*RADIATOR GRILLE	Cracked	1,338.00 FS	*1,124.80 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	180.00 FS	*150.80 FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Missing	177.00 FS	*148.40 FS
12	1		*AIRCON STICKER	Necessary	7.00 FS	*5.68 FS
13	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*10.80 FS
14	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Bent	681.00 FS	*571.60 FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	178.00 FS	*149.60 FS
16	1		*FRONT BUMPER FOAM FILLER PIECE COVER	Cracked	115.00 FS	*96.40 FS
17	1		*SIGNAL HORN - RH LOW TONE	Not Necessary	188.00 FS	*- FS
18	1		*FRONT FENDER - RH	Buckled	802.00 FS	*672.80 FS
19	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	68.00 FS	*- FS
20	1		*FRONT FENDER BRACKET - RH	Bent	26.00 FS	*21.52 FS
21	1		*FRONT FENDER BRACKET - RH	Bent	36.00 FS	*30.40 FS
22	1		*FRONT FENDER BRACE	Bent	90.00 FS	*75.68 FS
23	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	31.00 FS	*- FS
24	1		*FRONT FENDER INSULATION - RH	Not Necessary	40.00 FS	*- FS
25	1		*WHEEL HOUSING LINER SEAL - RH	Not Necessary	32.00 FS	*- FS
26	1		*WHEEL HOUSING LINER - RH	Torn	159.00 FS	*133.20 FS
27	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	84.00 FS	*- FS
28	1		*BONNET	Dented	2,988.00 FS	*2,507.20 FS
29	1		*BONNET ATTACHMENT PARTS	Not Necessary	155.00 FS	*- FS
30	2		*BONNET LID HINGE - LH / RH	O/S Bent	116.00 FS	*48.24 FS
31	1		*BONNET GAS FILLED STRUT	Not Necessary	112.00 FS	*- FS
32	1		*BONNET CATCH HOOK	Not Necessary	84.00 FS	*- FS
33	2		*BONNET STRIKER - LH / RH	Not Necessary	208.00 FS	*- FS
34	1		*BONNET EDGE PROTECTION	Necessary	26.00 FS	*21.84 FS
35	1		*INNER FENDER COVER - RH	Not Necessary	39.00 FS	*- FS
36	2		*BONNET LID LOCK	Not Necessary	403.00 FS	*- FS
37	1		*BONNET BOWDEN CABLE - CENTRE	Not Necessary	54.00 FS	*- FS
38	1		*BONNET LID LOCK CABLE	Not Necessary	69.00 FS	*- FS
39	1		*BONNET SOUND ABSORBER	Not Necessary	207.00 FS	*- FS
40	1		*PLENUM CHAMBER COVER	Not Necessary	169.00 FS	*- FS
41	1		*LED HEADLIGHT - RH	Cracked	5,193.00 FS	*4,364.00 FS
42	1		*MAIN LIGHT ELECTRONICS POWER MODULE - RH	Not Necessary	714.00 FS	*- FS
43	1		*LED WITH HEAT SINK - RH	Not Necessary	689.00 FS	*- FS
44	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Not Necessary	524.00 FS	*- FS
45	1		*HEADLIGHT HOSE - RH	Not Necessary	38.00 FS	*- FS
46	1		*HEADLAMP REPAIR KIT	Not Necessary	124.00 FS	*- FS
47	1		*LIFT CYLINDER - LH / RH	O/S Cracked	268.00 FS	*112.40 FS
48	1		*LIFT CYLINDER HOSE	Cut	64.00 FS	*53.20 FS
49	1		*LOCK CARRIER	Cracked	685.00 FS	*575.20 FS
50	1		*AIRCON CONDENSER	Bent	519.00 FS	*436.00 FS
51	1		*REFRIGERANT LINE	Bent	613.00 FS	*495.20 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*REFRIGERANT LINE	Bent	471.00 FS	*380.40 FS
53	1		*RADIATOR	Distorted	932.00 FS	*752.80 FS
54	1		*ADDITIONAL RADIATOR	Distorted	851.00 FS	*687.20 FS
55	1		*RADIATOR SEALING STRIP	Not Necessary	15.00 FS	*- FS
56	2		*RADIATOR BRACKET	Damaged	78.00 FS	*62.88 FS
57	2		*RADIATOR BUSH - LOWER	Not Necessary	19.00 FS	*- FS
58	4		*READY MIX COOLANT	Necessary	169.00 FS	*141.44 FS
59	1		*RADIATOR FAN	Not Necessary	1,091.00 FS	*- FS
60	1		*RADIATOR AIR GUIDE - RH	Damaged	23.00 FS	*19.20 FS
61	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	12.00 FS	*- FS
62	1		*FRONT NO. PLATE	Dented	60.00 FS	*60.00 FS
63	1		*SUNDRIES	Necessary	500.00 FS	*26.72 FS
64	1		*NOISE INSULATION UNDERBODY	Torn	244.00 FS	*217.20 FS
65	1		*WHEEL HOUSING LINER FRONT LHS	Deformed	159.00 FS	*133.20 FS
66	1		*COOLANT HOSE WITH QUICK RELEASE COUPLING	Damaged	58.00 FS	*48.08 FS
67	1		*TEMPERATURE SENSOR BRACKET	Damaged	18.00 FS	*14.40 FS
68	1		*FRONT BUMPER COVER TRIM LHS	Deformed	153.00 FS	*128.40 FS
69	1		*BONNET CATCH HOOK	Bent	60.00 FS	*49.76 FS
70	1		*WHEEL HOUSING LINER ADAPTER LHS	Damaged	36.00 FS	*29.52 FS
71	1		*FRONT WINDSCREEN WATER DEFLECTOR STRIP LHS	Cut	87.00 F	*72.88 F

F=Franchise part. S=SpcNett.

<b>Total Parts (\$)</b>	<b>26,573.00</b>	<b>17,191.92</b>
-------------------------	------------------	------------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
3	TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY	New	350.00	280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET, AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,250.00	3,000.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET HINGES, RHS FRONT DOOR AND RHS UPPER A-PILLAR	New	4,900.00	2,475.00
6	TO CARRY OUT PRE-DIAGNOSTIC CHECK AND POST-DIAGNOSTIC CHECK	New	384.00	384.00
7	TO RESPRAY RHS SILL PANEL	New	900.00	550.00
8	TO PLACE THE VEHICLE ON CELLETTE BENCH TO REALIGN RHS FRONT BUMPER CHASSIS FRAME	New	1,200.00	1,200.00
9	TO RESPRAY FRONT BUMPER RHS CHASSIS FRAME	New	700.00	550.00
			<b>Gross Labour Cost (\$\$)</b>	<b>15,244.00</b>
				<b>9,999.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >