

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20006343/T1EA3Q2
Date: 08/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0100623258-14
Claimant Vehicle No :	SH7132P	Insured Vehicle No :	SGE7690C
Date of Loss:	16/06/2020	Nature of Claim:	TP
		Claim No:	3392388094SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7132P		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS047080
Reg. Date:	15/06/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU003558315
Colour:	Blue	Odometer:	391244 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,454.82	1,757.22	2,697.60	60.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	1,340.00	340.00	20.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,134.82	3,097.22	3,037.60	49.51
Approved Total (Overridden) (S\$)		2,500.00		

(S\$)	6,134.82	2,500.00	3,634.82	59.25
+ GST 7.00/7.00% (S\$)	429.44	175.00	254.44	59.25
Nett Amount (S\$)	6,564.26	2,675.00	3,889.26	59.25
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (S\$)		125.40		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,907.89		

INSPECTION

Date of Assignment: 16/06/2020

Date Inspected: 16/06/2020

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR PANEL RH	Repair	1,797.20 FL	*- FL
2	1		*REAR DOOR PANEL RH	Bent	1,789.90 FL	*1,789.90 FL
3	1		*RHS ROCKER PANEL	Repair	1,799.60 FL	*- FL
4	1		*RH WHEEL COVER	Cut	346.40 FL	*346.40 FL
5	1		*FRT DOOR COMFORT LOGO	Cut	75.00 FS	*75.00 FS
6	1		*REAR DOOR COMFORT APP	Cut	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,888.10	2,291.30
- List Item Discount on L Items 25.00/25.00% (\$)	1,433.28	534.08
Total Parts (\$)	4,454.82	1,757.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	760.00	640.00
2	SPRAY PAINTING CHARGE	New	600.00	600.00
3	TRANFER DOOR PART TO NEW DOOR	New	200.00	60.00
4	TUFF COAT	New	120.00	40.00
Gross Labour Cost (S\$)			1,680.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >