



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWER
SINGAPORE 068811
ATTN: STACEY NG

INV No. AC2005336
INV Date 30/07/2020
Reference CC6/AXA15001299/Kpa3s2
Code AXA2



PROFESSIONAL SERVICE FEE

Vehicle No. SKP 3515Y
Insured Veh. GZ 1493J
Claim No. C0328493
Policy No. P1560685
Accident Date 20/01/2015
Inspection Date 21/01/2015

Description	Total
Third Party Express Settlement	350.00
Less: Invoice no.AC1514493 dated 17/12/2015	-250.00
Subtotal	100.00
GST (7%)	7.00
Grand Total	107.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC6/AXA15001299/Kpa3s2-1

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 30-07-2020



ATTN: STACEY NG

Code : AXA2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 1493J	Veh. Inspected	SKP 3515Y
Policy No.	P1560685	Coverage (\$)	0.00
Claim No.	C0328493	Excess (\$)	0.00
Assign From		Assign Date	21/01/2015

2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ (A)	c.c	1318
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JHMGK3850FX200202	Colour	METALLIC SILVER
Odometer	15237	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65R15	DUNLOP	8 mm
L/H Front Tyre	175/65R15	DUNLOP	8 mm
R/H Rear Tyre	175/65R15	DUNLOP	8 mm
L/H Rear Tyre	175/65R15	DUNLOP	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/01/2015	Inspection Date	21/01/2015
Survey held at	K KIM HIN AUTO PTE LTD 160 SIN MING DRIVE #02-20 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
--	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 3515Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING , ALIGN, REFIX AND TO RENEW AFFECTED PARTS.		120.00	60.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		200.00	180.00
			320.00	240.00
GRAND TOTAL			320.00	240.00
RECOMMENDED COST OF REPAIRS				240.00

Report Ref No. CC6/AXA15001299/Kza3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.