

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 6321Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE (CONSISTENT)	BENT	680.20	680.20
1	TAILGATE 'JAZZ' EMBLEM (CONSISTENT)	NECESSARY	26.20	26.20
1	TAILGATE GLASS MOULDING -LOWER (CONSISTENT)	NECESSARY	42.00	42.00
1	TAILGATE GLASS MOULDING -TOP (CONSISTENT)	NECESSARY	46.00	46.00
1	REAR BUMPER (CONSISTENT)	BUCKLED	440.50	440.50
1	N/S REAR BUMPER SIDE RETAINER (CONSISTENT)	DISTORTED	18.00	18.00
8	REAR BUMPER CLIPS @\$6.00 (CONSISTENT)	NECESSARY	48.00	48.00
	LESS 20% DISCOUNT		-260.18	-260.18
			1,040.72	1,040.72
	SPECIAL NETT ITEMS			
1	TAILGATE 'THANKS FOR YOUR PATIENCE ' STICKER (SN) (CONSISTENT)	NECESSARY	150.00	150.00
1	TAILGATE '8' REFLECTIVE STICKER (SN) (CONSISTENT)	NECESSARY	5.00	5.00
1	TAILGATE GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	TAILGATE GLASS DAMPING SEAL (SN) (CONSISTENT)	NECESSARY	20.00	20.00
			215.00	215.00
	LABOUR			
	TO REMOVE,CUT OUT DAMAGED PARTS ,PANEL BEATING,WELDING ,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.		480.00	420.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		600.00	540.00
	TO APPLY UNDERSEALING.		30.00	30.00
	TO REMOVE AND RENEW REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		120.00	120.00
	TO TRANSFER TAILGATE'S FITTINGS.		80.00	60.00
			-	-
			-	-
			-	-
			1,310.00	1,170.00
	GRAND TOTAL		2,565.72	2,425.72

Report Ref No. CC6/AXA15001557/Kba3q2-1



Report Ref No. CC6/AXA15001557/Kba3q2-1

KONG SENG CHEONG

Licensed Appraiser