

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC6/AXA15001557/Kba3q2-1	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:JAS TAN			Date: 25-08-2020 Code: AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Ir	nsured Veh.	SJQ 8835Y	Veh. Inspected	SKF 6321Y
Р	Policy No.	GA000399	Coverage (\$)	0.00
С	Claim No.	C0329473	Excess (\$)	0.00
A	Assign From		Assign Date	26/01/2015
2. Vehicle Particulars & Condition				
N	/lake & Model	HONDA JAZZ	c.c	1339
E	ngine No.	HIDDEN	Year of Reg.	2012
С	Chassis No.	JHMGE6750CS208161	Colour	METALLIC SILVER
С	Odometer	96192	Steering	IN ORDER
В	Brakes	IN ORDER	Modification	NIL
G	Seneral	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
-	R/H Front Tyre	175/65 R15	DUNLOP	9 mm
-	./H Front Tyre	175/65 R15	DUNLOP	9 mm
-	R/H Rear Tyre	175/65 R15	DUNLOP	6 mm
L	./H Rear Tyre	175/65 R15	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.			
D	DAMAGES SEE DETAILS.			
5.	General Information			
A	Accident Date	25/01/2015	Inspection Date	26/01/2015
S	Survey held at	K KIM HIN AUTO PTE LTD		
		160 SIN MING DRIVE #02-20 SIN MING AUTO CITY SINGAPORE 575722		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
E	STIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			