Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006345/GPA3Q2

Date: 20/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100470664

Claimant Vehicle No: SKE7295M Insured Vehicle No: SCF1808M

Date of Loss: 04/06/2020 Nature of Claim: TP Claim No: 3634621691SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKE7295M

Make & Model: TOYOTA CAMRY, 2.0 ABS AIRBAG (A) Engine No: 1AZE017066

Reg. Date: 11/01/2007 (Man. Year: 2006) Chassis No: MR053BK4107004735

Colour: Silver Odometer: 250525 km

Engine Capacity: 1998 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,369.90	922.95	2,446.95	72.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,160.00	940.00	220.00	18.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,529.90	1,862.95	2,666.95	58.87
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	4,529.90	1,500.00	3,029.90	66.89
+ GST 7.00/7.00% (S\$)	317.09	105.00	212.09	66.89
Nett Amount (S\$)	4,846.99	1,605.00	3,241.99	66.89
+ Loss of Use (4.0 x S\$	400.00			
+ Doc/	7.45			
N	2,012.45			
Global Sum	2,012.00			

INSPECTION

Date of Assignment: 05/06/2020

Date Inspected: 11/06/2020 Inspected At: Kian Teong Auto Centre (HQ)

BLK 176 SIN MING DRIVE #01-08

SIN MING AUTOCARE Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster Report Page 2 of 4

Adjuster: XING GUO QIANG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BOOTH	Repair	980.00 F	*- FL	
2	1		*REAR END PANEL	Repair	448.00 F	*- FL	
3	1		*REAR BUMPER REINFORCEMENT	Bent	495.00 F	*361.80 FL	
4	1		*REAR BUMPER	Deformed	778.50 F	*566.20 FL	
5	1		*REAR BOOTH LOCK	Not Necessary	165.00 F	*- FL	
6	1		*REAR BOOTH LATCH	Not Necessary	98.00 F	*- FL	
7	1		*REAR BOOTH EMBLEM (CAMRY)	Necessary	48.70 F	*36.90 FL	
8	1		*REAR BOOTH EMBLEM (TOYOTA LOGO)	Necessary	46.70 F	*30.70 FL	
9	2		*REAR BOOTH EMBLEM	Necessary	90.00 F	*35.00 FL	
10	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	220.00 FS	*150.00 FS	
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 0.00/25.00% (S\$)					1,180.60 257.65	
				Total Parts (S\$)	3,369.90	922.95	
Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO SPRAY PAINT ALL DAMAGED PARTS	New	580.00	500.00
TO REMOVE AND CHANGE ALL DAMAGED PARTS TO KNOCK AND RE-ALIGN ALL DAMAGED PARTS	New	480.00	400.00
TO CHECK REAR TAIL LAMP AND SENSOR WIRING	New	100.00	40.00
Gross Labour Cost (S\$)		1,160.00	940.00
Depart was unsubmitted du	ing this print out		
	OUR Items TO SPRAY PAINT ALL DAMAGED PARTS TO REMOVE AND CHANGE ALL DAMAGED PARTS TO KNOCK AND RE-ALIGN ALL DAMAGED PARTS TO CHECK REAR TAIL LAMP AND SENSOR WIRING Gross Labo	TO SPRAY PAINT ALL DAMAGED PARTS TO REMOVE AND CHANGE ALL DAMAGED PARTS TO KNOCK AND RE-ALIGN ALL DAMAGED PARTS TO CHECK REAR TAIL LAMP AND SENSOR WIRING New	TO SPRAY PAINT ALL DAMAGED PARTS TO REMOVE AND CHANGE ALL DAMAGED PARTS TO New 480.00 KNOCK AND RE-ALIGN ALL DAMAGED PARTS TO CHECK REAR TAIL LAMP AND SENSOR WIRING New 100.00 Gross Labour Cost (S\$) 1,160.00

< END OF ESTIMATES >