Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20006347/KGA3Q2

Date: 09/10/2020

**REFERENCE** 

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00015530

Claimant Insured Vehicle No: SDL6883T **SKL1212E** Vehicle No:

Date of Loss: 22/05/2020 ΤP Nature of Claim: Claim No: 1202000017968

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SKL1212E** Reg No:

Make & Model: MERCEDES-BENZ S350L, 3.5 (A) Engine No: 27695030006200 Chassis No: Reg. Date: 09/09/2011 (Man. Year: 2011) WDD2211572A397688 151282 km

Colour: Metallic Black Odometer:

**Engine Capacity:** 3498 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

**General Condition:** Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

**CONDITION OF TYRES** 

Front Tyre Size: 255/40Z R19 Rear Tyre Size: 255/40Z R19 Dunlop 4 mm Front Left Side: Rear Left Side: Dunlop 5 mm Front Right Side: Rear Right Side: Dunlop 5 mm Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,788.60	6,447.60	1,341.00	17.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,465.00	1,000.00	465.00	31.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,253.60	7,447.60	1,806.00	19.52
Approved Total (Overridden) (S\$)		5,900.00		
(S\$)	9,253.60	5,900.00	3,353.60	36.24
+ GST 7.00/7.00% (S\$)	647.75	413.00	234.75	36.24
Nett Amount (S\$)	9,901.35	6,313.00	3,588.35	36.24
Global Sum S	Settlement (S\$)	0.00		

**INSPECTION** 

Date of Assignment: 05/06/2020

S & H Motor Pte Ltd (Sin Ming) 09/06/2020 Inspected At: Date Inspected:

160 Sin Ming Drive #07-02, Sin Ming

AutoCity

Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: Chong Pui Lin Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

Reference				
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 08 Oct 2020)		
Parts:	143	MERCEDES-BENZ S350L 3.5 (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	Code: (Unsubmitted, no print-code for SKL1212E)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition I	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,845.00 FN	*1,845.00 FN
2	1		*RH FRONT BUMPER WASH NOZZLE	*Check	295.00 FN	*- FN
3	1		*RH FRONT BUMPER WASH NOZZLE COVER	Cracked	180.00 FN	*180.00 FN
4	1		*RH FRONT BUMPER LED DAYLIGHT LAMP	Cracked	485.00 FN	*485.00 FN
5	1		*RH FRONT BUMPER LED DAYLIGHT LAMP CHROME TRIM	Dented	175.00 FN	*175.00 FN
6	1		*RH FRONT BUMPER AIR GRILLE	*Check	235.00 FN	*- FN
7	1		*RH FRONT BUMPER OUTER PARKING SENSOR	Missing	285.00 FN	*285.00 FN
8	1		*RH FRONT BUMPER RETAINER PANEL	Distorted	89.00 FN	*89.00 FN
9	1		*RH FRONT BUMPER METAL RETAINER BRACKET (TO CHECK)	*Check	295.00 FN	*- FN
10	1		*FRONT BUMPER SPONGE (TO CHECK)	*Check	285.00 FN	*- FN
11	1		*RH FRONT FENDER	Bent	978.00 FN	*978.00 FN
12	1		*RH FRONT FENDER BADGE BLUE EFFICIENCY	Necessary	82.00 FN	*82.00 FN
13	1		*RH FRONT FENDER LOWER CHROME TRIM	*Check	85.00 FN	*- FN
14	1		*RH HEAD LAMP	Cracked	3,045.00 FN	*3,045.00 FN
15	1		*RH HEAD LAMP INNER PANEL (TO CHECK)	Repair	295.00 FN	*- FN
F=Fra	anchise	part. N=N	NettItemDisc.			
			Si	ub Total (S\$)	8,654.00	7,164.00
			- Nett Item Discount on N Items 10.00	/10.00% (S\$)	865.40	716.40
			Tot	al Parts (S\$)	7,788.60	6,447.60

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	<u>Labour Items</u>						
1	TO REMOVE FRONT DAMAGED PARTS, TO STRAIGHTEN OUT FRONT CHASSIS, TO RESHAPE AND REPAIR AND REPLACE FRONT BUMPER REINFORCEMENT PANEL, RH FRONT FENDER AND INNER PANEL, HEAD LAMP INNER PANEL, FRONT SUPPORT PANEL, FRONT CHASSIS MEMBER AND ADJUST BODY PANEL ALIGNMENT	New I	600.00	500.00			
2	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY .TO FOCUS HEADLAMP	New	35.00	20.00			
3	TO SPRAY PAINT AFFECTED FRONT AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND MATERIAL	New	650.00	480.00			
4	TO PERFORM COMPUTER DIAGNOSTIC ON DRIVETRAIN ABS SYSTEMS ,PARKING SYSTEM,AND CLEAR FAULT CODES (*Check)	New	180.00	0.00			
	Gross Labour	1,465.00	1,000.00				
	Report was unsubmitted during this print-out.						

< END OF ESTIMATES >