Not bothoise!

(1) Sing &?

Resiny After Paint

Gelagi

S&H Motor Pte Ltd

Tan Gek Khim 12 Namly Grove Singapore 267307

File No:

SH/2020/057/6/044/TP

06-June-2020

Estimated cost of repair for vehicle no: Accident involving vehicle no: SKL1		SKL1212E		Mercedes S		
		212E	&	SDL6883T	on	22.05.2020
Description				0		Cost Drice / I

Accident involving venicle no:	SKL1212E	&	SDL6883T	on	22.05.	2020	
Description			Quantity		Cost 1	Price / List Price	ce
						0	
Front bumper			. 1	Nett	\$	Bu 1,845.00	
RH Front bumper wash nozzle			1	Nett	\$	295.00) '
RH Front bumper wash nozzle cover			1	Nett	\$	CM 180.00) L
RH Front bumper LED daylight lan	_		1	Nett	\$	cm 485.00) '
RH Front bumper LED daylight lan	np chrome trim		1	Nett	\$	New 175.00)
RH Front bumper air grille			1	Nett	\$	235.00) 1
RH Front bumper outer parking sen	sor		1	Nett	\$	M/7 285.00	
RH Front bumper retainer panel			1	Nett	\$	DI 89.00	۱ ا
RH Front bumper metal retainer bra	acket (to check)		1	Nett	\$	295.00	•
Front bumper sponge (to check)			1	Nett	\$	285.00) 1
RH front fender			1	Nett	\$	978.00	
RH front fender badge "blue efficie	ncyKK Auto Consultants	hence no	dify 1	Nett	\$	Na 82.00	
RH front fender lower chrome trim	the Repairer of the fol	lowing.		Nett	\$	85.00	
RH head lamp	To resurvey before/after s To display damaged part(s)	pray painting	1	Nett	\$	cm 3,045.00	
RH head lamp inner panel (to chec	 Parts prices are subject to 	confirmatio	1 1	Nett	\$	M 295.00	_ ;
	 Third party survey is on a No illegal modification(s) is 	Without Pre	judice" basis		\$	8,654.00	
	 Supplementary item(s) mu 	et he recurs	eyed and les	s 10%	\$	865.40	
	is subject to final approval	from Insurar	nce Company		\$	7,788.60	
	Acknowledged by Repairer Signature:						
To remove front damaged parts, to	straighten out front	chassis	, to reshape	and			
repair and replace front bumper rein	nforcment panel, R	H front	fender and				
inner panel, head lamp inner panel,	front support panel	l, front	chassis mem	ber			50
and adjust body panel alignment					\$	600.00	
	,						
To disconnect wire harness to facili	tate repairs and che	ck for	damage and				
reconnect wiring system and check	for full functionalit	y. To fo	ocus headlan	np	\$	35.00	2
							Se d
To spray paint affected front and in	ner damaged portio	n inclu	sive of			=	Fol
preparatory works and material					\$	650.00	
	13. %						
To perform computer diagnostic on	drivetrain, ABS sys	stems, p	parking syste	m,			
and clear fault codes					\$	180.00	•
							_
					\$	9,253.60	

T/Party: FWD Singapore Pte. Ltd.

Page 1 of 1