

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20006351/ACF3E2

Date: 14/04/2021

REFERENCE

Insured/Claimant:	LOH CHIEN NEE (LUO QIANNI)	Policy No:	2100498620	
Date of Loss:	13/06/2020	Nature of Claim:	OD	Claim No: 2735298213SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGD223U	Engine No:	CVN022715
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Chassis No:	WAUZZZF44HA063309
Reg. Date:	23/01/2017 (Man. Year: 2016)	Odometer:	79731 km
Colour:	Gold		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,623.00	20,740.00	15,883.00	43.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,504.00	8,252.00	8,252.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	53,127.00	28,992.00	24,135.00	45.43
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	52,527.00	28,392.00	24,135.00	45.95
+ GST 7.00/7.00% (S\$)	3,676.89	1,987.44	1,689.45	45.95
Nett Amount (S\$)	56,203.89	30,379.44	25,824.45	45.95

INSPECTION

Date of Assignment:	17/06/2020		
Date Inspected:	16/06/2020	Inspected At:	24 BENOI SECTOR Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	12.0 days		

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,010.00 FS	*1,608.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	269.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Necessary	67.00 FS	*52.96 FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	185.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	198.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	59.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,084.00 FS	*867.20 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	127.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER	Bent	757.00 FS	*605.20 FS
10	1		*FRONT BUMPER BRACKET - LH	Damaged	214.00 FS	*171.20 FS
11	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	34.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	36.00 FS	*- FS
13	1		*FRONT BUMPER COVER	Deformed	120.00 FS	*96.00 FS
14	1		*FRONT BUMPER FOAM FILLER PIECE	Damaged	117.00 FS	*93.60 FS
15	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*10.24 FS
16	1		*AIRCON STICKER	Necessary	7.00 FS	*5.36 FS
17	1		*LOCK CARRIER BRACKET	Cracked	129.00 FS	*103.20 FS
18	2		*FRONT BUMPER SUPPORT - LH / RH	Damaged	54.00 FS	*43.36 FS
19	1		*HORN - LH HIGH TONE	Not Necessary	119.00 FS	*- FS
20	1		*SPRING SHACKLE - LH	Not Necessary	27.00 FS	*- FS
21	1		*BONNET	Dented	2,634.00 FS	*2,107.20 FS
22	1		*BONNET ATTACHMENT PARTS	Not Necessary	116.00 FS	*- FS
23	2		*BONNET LID HINGE - LH / RH	Not Necessary	574.00 FS	*- FS
24	1		*BONNET IMPACT PROTECTION - CENTRE	Necessary	26.00 FS	*20.56 FS
25	2		*BONNET IMPACT PROTECTION - LH / RH	Necessary	52.00 FS	*41.36 FS
26	2		*BONNET STRIKER - LH / RH	Not Necessary	94.00 FS	*- FS
27	2		*BONNET LID LOCK	Not Necessary	403.00 FS	*- FS
28	1		*BONNET BOWDEN CABLE - CENTRE	Not Necessary	54.00 FS	*- FS
29	1		*BONNET BOWDEN CABLE	Necessary	54.00 FS	*43.20 FS
30	1		*BONNET RELEASE LEVER	Not Necessary	13.00 FS	*- FS
31	1		*FRONT FENDER - LH	Buckled	722.00 FS	*577.60 FS
32	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	190.00 FS	*- FS
33	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	47.00 FS	*- FS
34	1		*FRONT FENDER BRACKET - LH	Not Necessary	33.00 FS	*- FS
35	1		*DEFORMATION ELEMENT BRACKET - LH	Not Necessary	46.00 FS	*- FS
36	1		*FRONT FENDER BRACE - LH	Not Necessary	112.00 FS	*- FS
37	1		*WHEEL HOUSING LINER - LH	Not Necessary	226.00 FS	*- FS
38	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	86.00 FS	*- FS
39	1		*WHEEL SPOILER	Not Necessary	69.00 FS	*- FS
40	1		*WHEEL SPOILER TRIM - LH	Not Necessary	33.00 FS	*- FS
41	1		*STONE CHIP GUARD	Necessary	48.00 FS	*37.92 FS
42	1		*FENDER TOP LEDGE COVER - INNER	Necessary	29.00 FS	*23.20 FS
43	1		*FENDER TOP LEDGE COVER - OUTER	Necessary	21.00 FS	*16.72 FS
44	2		*LED HEADLIGHT - LH / RH	Cracked	14,642.00 FS	*11,713.60 FS
45	1		*LIFT CYLINDER - LH	Not Necessary	198.00 FS	*- FS
46	1		*LOCK CARRIER	Not Necessary	956.00 FS	*- FS
47	2		*COOLANT REGULATOR SUPPORT	Not Necessary	71.00 FS	*- FS
48	1		*AIRCON CONDENSER	Dented	586.00 FS	*468.80 FS
49	2		*REFRIGERANT LINE PRESSURE SENSOR	Not Necessary	368.00 FS	*- FS
50	1		*RADIATOR	Dented	615.00 FS	*492.00 FS
51	2		*RADIATOR RUBBER BUSH - LOWER	Not Necessary	17.00 FS	*- FS
52	2		*RADIATOR RUBBER BUSH - LOWER	Not Necessary	24.00 FS	*- FS
53	1		*READY MIX COOLANT	Necessary	86.00 FS	*68.80 FS
54	1		*ADDITIONAL RADIATOR - LOWER CENTRE	Not Necessary	480.00 FS	*- FS
55	1		*TEMPERATURE SENSOR BRACKET	Damaged	18.00 FS	*13.68 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*EXTERNAL TEMPERATURE SENSOR	Not Necessary	55.00 FS	*- FS
57	1		*RADIATOR FAN RING	Not Necessary	240.00 FS	*- FS
58	1		*RADIATOR FAN	Not Necessary	1,877.00 FS	*- FS
59	1		*RADIATOR AIR GUIDE - LH / RH	N/S Cracked	54.00 FS	*22.08 FS
60	2		*RADIATOR AIR GUIDE - LH / RH	Cracked	24.00 FS	*17.76 FS
61	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	15.00 FS	*- FS
62	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	21.00 FS	*- FS
63	1		*AIR INTAKE AIR DUCT - RH	Not Necessary	21.00 FS	*- FS
64	1		*AIR INTAKE AIR GUIDE	Not Necessary	50.00 FS	*- FS
65	1		*AIR INTAKE SEAL	Not Necessary	13.00 FS	*- FS
66	1		*AIR FILTER	Not Necessary	362.00 FS	*- FS
67	1		*AIR INTAKE HOSE	Not Necessary	90.00 FS	*- FS
68	1		*REAR BUMPER	Not Necessary	2,079.00 FS	*- FS
69	1		*REAR BUMPER FIXING PARTS	Not Necessary	69.00 FS	*- FS
70	1		*REAR BUMPER SECURING STRIP	Necessary	210.00 FS	*168.00 FS
71	1		*REAR BUMPER SPOILER	Deformed	234.00 FS	*187.20 FS
72	2		*REAR LIGHT REFLECTOR - LH / RH	Not Necessary	78.00 FS	*- FS
73	1		*REAR BUMPER CARRIER	Bent	845.00 FS	*708.80 FS
74	2		*REAR BUMPER CARRIER SEAL	Not Necessary	26.00 FS	*- FS
75	2		*REAR BUMPER GUIDE SECTION - LH / RH	Necessary	42.00 FS	*17.52 FS
76	2		*REAR PARKING AID SENSOR - INNER / OUTER (NPA)	Not Necessary	0.00 FS	*- FS
77	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
78	1		*PACKING ADHESIVE	Necessary	18.00 FS	*14.24 FS
79	1		*AUDI EMBLEM	Necessary	117.00 FS	*93.20 FS
80	1		*A4 INSCRIPTION	Necessary	90.00 FS	*71.76 FS
81	1		*TFSI INSCRIPTION	Necessary	90.00 FS	*71.76 FS
82	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
83	1		*REAR NO PLATE	Not Necessary	60.00 FS	*- FS
84	1		*SUNDRIES	Necessary	400.00 FS	*26.72 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 36,623.00 20,740.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND RENEW AIRCOND CONDENSER,ADDITIONAL RADIATOR,RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER,BONNET,AND BOTH HEADLIGHTS.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	5,600.00	3,000.00
4	TO RESPRAY FRONT BUMPER,LHS FRONT FENDER,BONNET AND HINGES	New	3,500.00	1,650.00
5	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	0.00
6	TO DISMANTLE AND RENEW REAR BUMPER.TO REPAIR REAR LID.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,400.00	500.00
7	TO RESPRAY REAR BUMPER AND REAR LID	New	2,000.00	550.00
8	TO CARRY OUT PRE-DIAGNOSTIC CHECK AND POST-DIAGNOSTIC CHECK	New	384.00	192.00
9	TO REPAIR REAR END PANLLING	New	700.00	250.00
10	TO RESPRAY REAR END PANELLING	New	1,000.00	550.00
Gross Labour Cost (\$\$)			16,504.00	8,252.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >