

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20006352/T1RA3Q2
Date: 17/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800130285
Claimant Vehicle No :	SH6078U	Insured Vehicle No :	SME8912K
Date of Loss:	16/06/2020	Nature of Claim:	TP
		Claim No:	7508455520SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH6078U		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDFU504293
Reg. Date:	03/09/2015 (Man. Year: 2015)	Chassis No:	KMHLB41UMGU077212
Colour:	Blue	Odometer:	678296 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,578.48	859.36	2,719.12	75.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	480.00	780.00	61.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,838.48	1,339.36	3,499.12	72.32
Approved Total (Overridden) (S\$)		1,050.00		

(S\$)	4,838.48	1,050.00	3,788.48	78.30
+ GST 7.00/7.00% (S\$)	338.69	73.50	265.19	78.30
Nett Amount (S\$)	5,177.17	1,123.50	4,053.67	78.30
+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
+ Car Rental (S\$)		143.69		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,399.68		

INSPECTION

Date of Assignment: 17/06/2020

Date Inspected: 17/06/2020

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Deformed	1,052.20 FL	*1,052.20 FL
2	1		*FRONT BUMPER SIDE BRACKET-LH	Not Necessary	24.60 FL	*- FL
3	1		*FRONT BUMPER TOP BRACKET -LH	Not Necessary	22.40 FL	*- FL
4	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
5	1		*FRONT BUMPER GRILLE -LH	Not Necessary	93.60 FL	*- FL
6	1		*HEADLAMP SUPPORT PANEL	Not Necessary	907.40 FL	*- FL
7	1		*FRONT FENDER -LH	Not Necessary	663.00 FL	*- FL
8	1		*FRONT FENDER SHIELD-LH	Not Necessary	174.90 FL	*- FL
9	1		*HEADLAMP -LH	Not Necessary	1,388.00 FL	*- FL
10	1		*ADVERTISEMENT -LHF FENDER	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,448.10	1,074.20
- List Item Discount on L Items 20.00/20.00% (\$)	869.62	214.84
Total Parts (\$)	3,578.48	859.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	280.00
2	SPRAY PAINTING CHARGE	New	500.00	200.00
3	TUFF KOTE	New	80.00	0.00
4	WIRING CHARGE	New	80.00	0.00
Gross Labour Cost (\$)			1,260.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >