

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3694L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	I40VC PANEL ASSY-FR DR RH	BENT	2,256.40	2,256.40
1	I40VC PANEL ASSY-RR DR RH	BENT	2,201.10	2,201.10
1	I40VC CAP ASSY-WHEEL HUB	CUT	107.10	107.10
1	I40VC COVER ASSY-RR BUMPE	TO REPAIR SEE LABOUR	1,106.00	-
1	I40VC MOULDING ASSY-SIDE	TO REPAIR SEE LABOUR	341.40	-
	LESS 20% DISCOUNT		-1,202.40	-912.92
			4,809.60	3,651.68
	<u>NETT ITEMS</u>			
1	(I40) FRT DOOR LOGO SONATA (N)	NECESSARY	75.00	75.00
1	APP LOGO REAR DOOR L/R CT (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-15.50	-15.50
			139.50	139.50
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF I40VC COVER ASSY-RR BUMPE AND I40VC MOULDING ASSY-SIDE.		900.00	560.00
	SPPRAYPAINT CHARGE.		1,200.00	800.00
	CHECK ALL LIGHTING.		50.00	30.00
	TRANSFER DOOR PARTS.		240.00	120.00
			2,390.00	1,510.00
	GRAND TOTAL		7,339.10	5,301.18
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			4,250.00

Report Ref No. NS/INC20006354/T1yf3e2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.