

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD20002675/GSF3E2-1

Date: 26/06/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00013043

Claimant Vehicle No : SJS2805M **Insured Vehicle No :** SLH8432A

Date of Loss: 11/02/2020 Nature of Claim: TP Claim No: 1202000008287

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS2805M		
Make & Model:	HONDA CIVIC, 2.0 3DRS TYPE R (A)	Engine No:	K20Z42008046
Reg. Date:	07/08/2009 (Man. Year: 2008)	Chassis No:	SHHFN23608U300164
Colour:	Black	Odometer:	0 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	235/40Z R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Jinyu 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Jinyu 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,616.29	8,383.36	9,232.93	52.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,440.00	2,540.00	900.00	26.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,056.29	10,923.36	10,132.93	48.12
Approved Total (Overridden) (S\$)		8,700.00		
(S\$)	21,056.29	8,700.00	12,356.29	58.68
+ GST 7.00/7.00% (S\$)	1,473.94	609.00	864.94	58.68
Nett Amount (S\$)	22,530.23	9,309.00	13,221.23	58.68

INSPECTION

Date of Assignment: 16/06/2020

Date Inspected: 18/02/2020 Inspected At:

SKM Motor Works Pte Ltd (HQ)
10 Kaki Bukit Road 2, #03-31 First East
Centre
Singapore 417868

Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jun 2020)
Parts:	143	HONDA CIVIC 2.0 3DRS TYPE R (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS2805M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	875.80 FL	*- FL
2	2		*FRONT BONNET HINGES L/R	Repair	77.80 FL	*- FL
3	1		*FRONT BONNET MECHANISM LOCK	Bent	85.10 FL	*85.10 FL
4	4		*FRONT BONNET RUBBER GUIDE STOPPER L/R	Serviceable	24.00 FL	*- FL
5	1		*FRONT GRILLE	Cracked	358.90 FL	*358.90 FL
6	1		*FRONT GRILLE LOGO EMBLEM	Necessary	84.90 FL	*84.90 FL
7	4		*FRONT GRILLE CLIPS	Necessary	26.00 FL	*26.00 FL
8	2		*FRONT HEADLAMP L/R	Cracked	2,200.00 FL	*2,200.00 FL
9	4		*FRONT HEADLAMP CLIPS L/R	Necessary	26.00 FL	*26.00 FL
10	2		*FRONT HEADLAMP LOWER BRACKET L/R	Bent	58.20 FL	*58.20 FL
11	1		*FRONT BUMPER	Cracked	873.90 FL	*873.90 FL
12	2		*FRONT BUMPER FOGLAMP L/R	Serviceable	500.40 FL	*- FL
13	4		*FRONT BUMPER INNER AIR DUCT CLIPS L/R	Serviceable	26.00 FL	*- FL
14	2		*FRONT BUMPER INNER AIR DUCT L/R	Serviceable	169.80 FL	*- FL
15	1		*FRONT BUMPER LOWER CENTER GRILLE	Serviceable	489.60 FL	*- FL
16	1		*FRONT BUMPER LOWER UNDER COVER	Repair	68.00 FL	*- FL
17	1		*FRONT BUMPER REINFORCEMENT	Bent	309.50 FL	*309.50 FL
18	2		*FRONT BUMPER REINFORCEMENT BRACKET L/R	Serviceable	140.00 FL	*- FL
19	2		*FRONT BUMPER SIDE RETAINER L/R	Bent	36.00 FL	*36.00 FL
20	2		*FRONT FENDER L/R	Repair	1,213.00 FL	*- FL
21	2		*FRONT FENDER ARCH GARNISH L/R	Bent	306.00 FL	*306.00 FL
22	1		*FRONT SUPPORT PANEL TOP GARNISH	Cracked	89.40 FL	*89.40 FL
23	6		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	33.00 FL	*33.00 FL
24	1		*FRONT SUPPORT PANEL	Repair	550.00 FL	*- FL
25	2		*FRONT SUB CHASSIS FRAME L/R	Repair	1,800.00 FL	*- FL
26	2		*AIRCON CONDENSER TOP BRACKET L/R	Bent	30.00 FL	*30.00 FL
27	2		*AIRCON CONDENSER TOP RUBBER BUSH L/R	Bent	18.00 FL	*18.00 FL
28	1		*AIRCON CONDENSER	Cracked	729.40 FL	*729.40 FL
29	1		*AIRCON COOLING PIPE	Repair	240.00 FL	*- FL
30	1		*AIRCON DISCHARGE PIPE	Repair	150.00 FL	*- FL
31	1		*RADIATOR	Cracked	1,410.20 FL	*1,410.20 FL
32	2		*RADIATOR LOWER RUBBER BUSH L/R	Bent	16.00 FL	*16.00 FL
33	1		*RADIATOR FAN COWLING	Repair	109.40 FL	*- FL
34	1		*RADIATOR LOWER HOSE	Repair	36.56 FL	*- FL
35	1		*REAR TAILGATE	Bent	1,207.00 FL	*950.20 FL
36	2		*REAR TAILGATE DAMPER L/R	Repair	211.80 FL	*- FL
37	2		*REAR TAILGATE HINGES L/R	Repair	93.40 FL	*- FL
38	1		*REAR TAILGATE LOGO EMBLEM (RED)	Serviceable	60.00 FL	*- FL
39	1		*REAR TAILGATE CIVIC EMBLEM	Necessary	55.00 FL	*55.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR TAILGATE TYPE R EMBLEM	Necessary	53.00 FL	*53.00 FL
41	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	152.80 FL	*152.80 FL
42	2		*REAR TAILGATE REFLECTOR LAMP L/R	Serviceable	481.40 FL	*- FL
43	1		*REAR TAILGATE CENTRE LIGHT CLUSTER	Serviceable	282.70 FL	*- FL
44	1		*REAR TAILGATE OUTER GARNISH	Serviceable	422.00 FL	*- FL
45	1		*REAR TAILGATE MECHANISM LOCK	Bent	165.20 FL	*165.20 FL
46	1		*REAR TAILGATE MECHANISM LOCK GARNISH	Bent	12.50 FL	*12.50 FL
47	2		*REAR TAILGATE RUBBER GUIDE L/R	Serviceable	21.00 FL	*- FL
48	1		*REAR TAILGATE WEATHER STRIP	Cut	161.90 FL	*161.90 FL
49	2		*REAR TAILLAMP L/R	Serviceable	610.00 FL	*- FL
50	1		*REAR BUMPER	Cracked	920.30 FL	*920.30 FL
51	2		*REAR BUMPER SIDE RETAINER L/R	Serviceable	29.20 FL	*- FL
52	1		*REAR BUMPER LOWER DIFFUSER ASSY	Cracked	388.00 FL	*388.00 FL
53	2		*REAR BUMPER SIDE SHIELD L/R	Serviceable	64.00 FL	*- FL
54	6		*REAR BUMPER SIDE SHIELD CLIPS L/R	Serviceable	39.00 FL	*- FL
55	1		*REAR BUMPER REINFORCEMENT	Bent	275.60 FL	*275.60 FL
56	1		*REAR END PANEL INNER TOP GARNISH	Cracked	122.80 FL	*122.80 FL
57	4		*REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	26.00 FL	*26.00 FL
58	1		*REAR END PANEL LOCK STRIKER	Serviceable	12.00 FL	*- FL
59	1		*REAR END PANEL LOCK STRIKER COVER	Serviceable	10.00 FL	*- FL
60	1		*REAR END PANEL	Bent	330.40 FL	*330.40 FL
61	1		*SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD	Repair	316.00 FL	*- FL
62	1		*SPARE TYRE PANEL	Repair	1,100.00 FL	*- FL
63	1		*RADIATOR TOP HOSE	Repair	36.50 FL	*- FL
64	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
65	1		*FRONT BUMPER NUMBER PLATE	Cracked	25.00 FS	*15.00 FS
66	1		*FRONT BUMPER NUMBER PLATE HOLDER	Cracked	50.00 FS	*25.00 FS
67	1		*SET FRONT BUMPER LOWER UNDER COVER CLIPS	Serviceable	30.00 FS	*- FS
68	2		*FRONT HEADLAMP BULB L/R	Serviceable	160.00 FS	*- FS
69	2		*FRONT HEADLAMP HIGH BEAM BULB L/R	Serviceable	80.00 FS	*- FS
70	2		*FRONT HEADLAMP PARKING BULB L/R	Serviceable	20.00 FS	*- FS
71	2		*FRONT HEADLAMP SIGNAL BULB L/R	Serviceable	30.00 FS	*- FS
72	1		*RADIATOR COOLANT - BOTTLE	Necessary	80.00 FS	*40.00 FS
73	1		*REAR TAILGATE NUMBER PLATE	Serviceable	25.00 FS	*- FS
74	1		*REAR TAILGATE NUMBER PLATE HOLDER	Serviceable	50.00 FS	*- FS
75	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
76	1		*SET REAR BUMPER REVERSE SENSOR	Serviceable	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,780.36	10,444.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,164.07	2,060.84
Total Parts (\$\$)	17,616.29	8,383.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR	New	140.00	0.00
2	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET	New	120.00	60.00
3	TO REMOVE, CHANGE AIR CON PARTS, VACUUMS, REFILL AIR CON GAS	New	160.00	120.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.	New	1,200.00	1,100.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,700.00	1,200.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
Gross Labour Cost (\$\$)			3,440.00	2,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >