



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 7930P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,202.00	-
1	FRONT BUMPER RETAINER LH	SERVICEABLE	102.00	-
1	RESONATOR (B/S FENDER LH) AIR BOX	SERVICEABLE	134.67	-
1	RESONATOR HOSE	SERVICEABLE	37.00	-
1	FRONT HEADLAMP LH	CUT	816.00	816.00
1	FRONT FENDER LH	BENT	837.60	837.60
1	FRONT FENDER LINER LH	DISTORTED	47.00	47.00
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,133.00	-
1	FRONT SIDE VIEW MIRROR LH	SERVICEABLE	939.00	-
1	SIDE ROCKER PANEL GARNISH LH	TO REPAIR SEE LABOUR	236.40	-
	LESS 10% DISCOUNT		-548.47	-170.06
			<b>4,936.20</b>	<b>1,530.54</b>
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER FASTENER CLIP (SN)	NOT NECESSARY	30.00	-
1	SET FRONT FENDER LINER CLIP LH (SN)	NECESSARY	30.00	30.00
1	DOOR STICKER "TRANS-CAB" LH (SN)	NOT NECESSARY	80.00	-
1	SET SIDE ROCKER PANEL GARNISH CLIP LH (SN)	NOT NECESSARY	60.00	-
1	FRONT TYRE LH (SN)	SERVICEABLE	360.00	-
1	FRONT WHEEL RIM LH (SN)	SERVICEABLE	254.00	-
1	HUB CUP RIM FRONT (SN)	SERVICEABLE	35.00	-
			<b>849.00</b>	<b>30.00</b>
<b><u>LABOUR</u></b>				
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER,FRONT DOOR LH AND SIDE ROCKER PANEL GARNISH LH.		2,800.00	300.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		220.00	30.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,700.00	400.00

Report Ref No. CC3/AXA15002341/Kja3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
			6,620.00	810.00
	<b>GRAND TOTAL</b>		<b>12,405.20</b>	<b>2,370.54</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,900.00</b>
---	--	--	--	-----------------

Report Ref No. CC3/AXA15002341/Kja3n2

**KONG SENG CHEONG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.