

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cecilia Low

Date: 24 Jun 2020

Preliminary Advice

Insured Vehicle No	: GW397B	Accident Date	: 07/06/2020
TP Vehicle No	: FBL732J	Assignment Date	: 18/06/2020
Make	: VESPA GTS 300 SUPER	Est. Duration of Repair	: 3.00
Date of Inspection	: 23/06/2020		
Inspection At	: XIN YIN AUTO (HQ) BLK 8 PREMIER @ KAKI BUKIT AVE 4 #05-23 SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, n/s & o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,050.00 (Labour Only)
Revised Amount	:S\$	860.00 (Labour Only)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	860.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING FOR PARTS PRICES FROM REPAIRER.