

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20006388/EQF3E2

**Date:** 21/08/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00008232002	
Claimant Vehicle No :	FBL732J	Insured Vehicle No :	GW397B	
Date of Loss:	07/06/2020	Nature of Claim:	TP	Claim No: SNM20D202148/C02/LOWCT

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL732J			
Make & Model:	VESPA GTS 300 SUPER, 278cc	Engine No:	M454M1079916	
Reg. Date:	30/05/2016 (Man. Year: 2016)	Chassis No:	ZAPM4520200027465	
Colour:	Grey	Odometer:	14521 km	
Engine Capacity:	278 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	120/70-12	Rear Tyre Size:	130/70-12
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,011.70	4,292.00	5,719.70	57.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,190.00	1,100.00	1,090.00	49.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,201.70</b>	<b>5,392.00</b>	<b>6,809.70</b>	<b>55.81</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,300.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,201.70</b>	<b>4,300.00</b>	<b>7,901.70</b>	<b>64.76</b>

### INSPECTION

Date of Assignment:	18/06/2020	
Date Inspected:	23/06/2020 Inspected At:	Xin Yin Auto (HQ) BLK 8 PREMIER @ KAKI BUKIT AVE 4 #05-23 Singapore 415875
Estimated Period of Repair:	5.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 21 Aug 2020)	
<b>Parts:</b>	N/A	VESPA GTS 300 SUPER 278cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBL732J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*SET FRONT FORK TUES ASSY WHOLE</b> (2 SET)	Bent (1Set Only)	1,370.00 FL	*685.00 FL
2	1		<b>*FRONT MUGCARD</b>	Cut	395.00 FL	*395.00 FL
3	1		<b>*FORK UNDER BRACKET</b>	Not Necessary	185.00 FL	*- FL
4	1		<b>*FRONT RIM SHAFT</b>	Not Necessary	285.00 FL	*- FL
5	1		<b>*FRONT BRAKE DISC (NPA)</b>	Not Necessary	0.00 FL	*- FL
6	1		<b>*FRONT FENDER</b>	Not Necessary	125.00 FL	*- FL
7	1		<b>*FRONT FENDER SEAL</b>	Not Necessary	105.00 FL	*- FL
8	1		<b>*HANDLE BAR</b>	Bent	225.00 FL	*225.00 FL
9	1		<b>*SET HAND GRIP</b>	Not Necessary	125.00 FL	*- FL
10	1		<b>*HANDLE BAR INNER BRACKET</b>	Not Necessary	125.00 FL	*- FL
11	1		<b>*SIDE MIRROR LEFT (NPA)</b>	Not Necessary	0.00 FL	*- FL
12	1		<b>*SIDE MIRROR RIGHT (NPA)</b>	Not Necessary	0.00 FL	*- FL
13	1		<b>*FRONT SIGNALS (LH)</b>	Cut	135.00 FL	*135.00 FL
14	1		<b>*FRONT SIGNAL PANEL COVER</b>	Repair	225.00 FL	*- FL
15	1		<b>*FRONT SIGNAL LOWER GARNISH</b>	Not Necessary	105.00 FL	*- FL
16	1		<b>*HEADLAMP (NPA)</b>	Not Necessary	0.00 FL	*- FL
17	1		<b>*SET FAIRING ASSY (NPA)</b>	Not Necessary	0.00 FL	*- FL
18	1		<b>*SIDE COWLING INNER GARNISH</b>	Not Necessary	95.00 FL	*- FL
19	1		<b>*CENTRE INNER PANEL</b>	Not Necessary	155.00 FL	*- FL
20	1		<b>*FRONT FOOTREST BRACKET</b>	Not Necessary	285.00 FL	*- FL
21	1		<b>*FRONT N/S FOOTREST RUBBER</b>	Not Necessary	95.00 FL	*- FL
22	1		<b>*BRAKE PEDAL</b>	Not Necessary	55.00 FL	*- FL
23	1		<b>*REAR N/S FOOTREST</b>	Cut	125.00 FL	*125.00 FL
24	1		<b>*REAR N/S FOOTREST BRACKET</b>	Not Necessary	85.00 FL	*- FL
25	1		<b>*REAR TAILLAMP</b>	Not Necessary	135.00 FL	*- FL
26	2		<b>*REAR FENDER</b>	Repair	225.00 FL	*- FL
27	1		<b>*ENGINE COVER METAL</b>	Repair	380.00 FL	*- FL
28	1		<b>*SWING ARM (NPA)</b>	Not Necessary	0.00 FL	*- FL
29	1		<b>*SET ABSORBER</b>	Not Necessary	480.00 FL	*- FL
30	1		<b>*LH GARNISH CRACKED</b>	Cut	165.00 FL	*165.00 FL
31	1		<b>*FUEL TANK COVER X1SET METAL</b>	Repair	680.00 FL	*- FL
32	1		<b>*REAR MIDSHIELD COVER (REFER TO ENGINE COVER) (LH)</b>	Cut	385.00 FL	*385.00 FL
33	1		<b>*CLUTCH LEVER</b>	Not Necessary	220.00 FL	*- FL
34	1		<b>*BALANCER (LH)</b>	Cut	125.00 FL	*125.00 FL
35	1		<b>*EXQ COVER</b>	Not Necessary	245.00 FL	*- FL
36	1		<b>*H/P BRAKE BROKEN</b>	Not Necessary	285.00 FL	*- FL
37	1		<b>*SET NUMBER PLATE FRONT AND BEHIND</b>	Necessary	50.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*SET STEERING CONE	Necessary	90.00 FS	*90.00 FS
39	1		*ENGINE COVER AND LIGHT STRICKER	Necessary	95.00 FS	*95.00 FS
40	1		*RADIATOR ASSY	Bent	485.00 FL	*485.00 FL
41	1		*FAN FRONT COVER	Broken	385.00 FL	*125.00 FL
42	1		*RADIATOR HOSE	Not Necessary	95.00 FL	*- FL
43	1		*COOLANT	Necessary	35.00 FL	*20.00 FL
44	1		*SIDE PANEL LEFT SIDE	Broken	225.00 FL	*225.00 FL
45	1		*SIDE PANEL RIGHT SIDE	Cut	225.00 FL	*225.00 FL
46	1		*SIDE PANEL STICKER 1 SET FOR BOTH	Necessary	80.00 FL	*80.00 FL
47	1		*SIDE SPOILER	Not Necessary	68.00 FL	*- FL
48	1		*AIR-INTAKE COVER	Broken	185.00 FL	*185.00 FL
49	1		*GLOVE BOARD	Crushed	395.00 FL	*395.00 FL
50	1		*GLOVE BOARD COVER	Crushed	195.00 FL	*195.00 FL
51	1		*STEP BOARD	Not Necessary	285.00 FL	*- FL
52	1		*SET STEP BOARD SEALS	Not Necessary	225.00 FL	*- FL
53	1		*LIMITED EDITIONAL VERIO-COVER	Cut	355.00 FL	*355.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,098.00</b>	<b>4,745.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,086.30	453.00
<b>Total Parts (\$\$)</b>	<b>10,011.70</b>	<b>4,292.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT AFFECTED AREA AND REPLACE FRONT DAMAGED PARTS, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	700.00	500.00
2	TO PUTTY AND SPRAY PAINTING FRONT PORTION	New	800.00	400.00
3	TO APPLY ANTI RUST PROOFING TO FRONT LEFT AFFECTED AREA	New	120.00	30.00
4	TO CHECK ELECTRICAL SYSTEM, WIRING AND FOCUS FRONT HEADLAMP	New	80.00	30.00
5	TO REMOVE AND INSTALL FRONT PADEL, BRAKE PADEL AND ABSORBER	New	150.00	50.00
6	TO BALANCE THE WHEEL	New	50.00	0.00
7	TO CONDUCT ALIGNMENT	New	50.00	30.00
8	LABOUR TO REPLACE RADIATOR AND FAN MOTOR ASSY AND TOP UP COOLANT	New	120.00	30.00
9	LABOUR TO REPLACE SIDE PANEL, AIR INTAKE AND VIOV BOARD AND COVER	New	120.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>2,190.00</b>	<b>1,100.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >