Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III20006395/GVF3E2

Date: 16/07/2020

**REFERENCE** 

India International Insurance Pte Handling Insurer:

Policy No:

D19MPC0002941

**Claimant Vehicle** No:

FBP1019H

**Insured Vehicle** No:

SMA6007H

Date of Loss: 23/01/2020

TP Nature of Claim:

Claim

MPC2020D0000586

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: FBP1019H

Make & Model: YAMAHA GDR155A (AEROX), 155cc Engine No:

G3J8E0088051 30/01/2019 (Man. Year: 2019) Chassis No: MH3SG4640KJ049039

Reg. Date:

Odometer: 0 km

No:

Colour: Black 155 cc

**Engine Capacity:** Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Good Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 140/70-14 110/80-14 Rear Tyre Size: Front Left Side: IRC 5 mm Rear Left Side: IRC 5 mm Rear Right Side: Front Right Side: 0 mm 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,558.90	898.30	660.60	42.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	280.00	210.00	70.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,838.90	1,108.30	730.60	39.73
+ GST 7.00/7.00% (S\$)	128.72	77.58	51.14	39.73
Nett Amount (S\$)	1,967.62	1,185.88	781.74	39.73

**INSPECTION** 

Date of Assignment: 18/06/2020

Date Inspected: 18/06/2020 Inspected At: Teo Spray Painting (HQ)

BLK 6 DEFU LANE 10, DEFU IND PARK

C #01-558

Singapore 539187

Estimated Period of Repair: 2.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen ... 16/7/2020

Adjuster Report Page 2 of 4

Adjuster: XING GUO QIANG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

## **REPAIR DETAILS**

Reference

Part Source: (Last Synchronised: 16 Jul 2020)

Parts: N/A YAMAHA GDR155A (AEROX) 155cc (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBP1019H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOP FRONT CENTRAL COVER	Not Necessary	90.00 FL	*- FL
2	1		*UNDERBRACKET	Not Necessary	240.00 FL	*- FL
3	1		*STEERING CONE	Not Necessary	90.00 FL	*- FL
4	1		*HANDLE BAR	Bent	64.00 FL	*64.00 FL
5	1		*BRAKE LEVER RH	Not Necessary	24.00 FL	*- FL
6	1		*METER COVER	Cracked	60.00 FL	*60.00 FL
7	1		*MUFFLER COVER	Cut	50.00 FL	*50.00 FL
8	1		*SIDE COVER RH	Cut	140.00 FL	*140.00 FL
9	1		*INNER COVER	Cracked	50.00 FL	*50.00 FL
10	1		*MIRROR BRACKET	Not Necessary	14.00 FL	*- FL
11	1		*LOWER HEADLAMP CENTRE COVER	Not Necessary	76.00 FL	*- FL
12	1		*LOWER COVER RH	Cut	50.00 FL	*50.00 FL
13	1		*SIGNAL LIGHT RH	Cracked	38.00 FL	*38.00 FL
14	1		*HEAD LAMP	Cracked	320.00 FL	*160.00 FL
15	1		*HEAD LAMP BRACKET	Not Necessary	40.00 FL	*- FL
16	1		*SIDE REAR LAMP	Scratched	50.00 FL	*50.00 FL
17	1		*BOX	Cut	100.00 FS	*100.00 FS
18	1		*UPPER SIDE PANEL RH	Cracked	65.00 FL	*65.00 FL
19	1		*SIDE COVER RH	Cut	60.00 FL	*60.00 FL
20	1		*SIDE STICKER RH	Necessary	65.00 FL	*65.00 FL
21	1		*SIDE COVER STICKER RH	Necessary	35.00 FL	*35.00 FL
F=Fra	anchise	part. S=SpcN	lett. L=ListItemDisc.	_		
				Sub Total (S\$)	1,721.00	987.00
	- List Item Discount on L Items 10.00/10.00% (S\$)				162.10	88.70
				Total Parts (S\$)	1,558.90	898.30

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TRANSPORT.	New	60.00	30.00
2	LABOUR CHARGES.	New	220.00	180.00
		Gross Labour Cost (S\$)	280.00	210.00
	F	Report was unsubmitted during this print-out.		

< END OF ESTIMATES >