Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20006403/UEA3Q2

Date: 28/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900236285

Claimant
White No: SMQ1949M

Vehicle No: SSJ78420 Insured Vehicle No: SMQ 1949M

Date of Loss: 13/06/2020 Nature of Claim: TP Claim No: 6784174438SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJJ7842U

Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ3141459

Reg. Date: 25/09/2008 (Man. Year: 2008) Chassis No: JTDER12W603000795

Colour: Grey Odometer: 178495 km

Engine Capacity: 1794 cc
Market Value/New Car
N/A

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm
Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,118.41	2,748.66	1,369.75	33.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	1,550.00	590.00	27.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,258.41	4,298.66	1,959.75	31.31
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	6,258.41	3,000.00	3,258.41	52.06
+ GST 7.00/7.00% (S\$)	438.09	210.00	228.09	52.06
Nett Amount (S\$)	6,696.50	3,210.00	3,486.50	52.06
+ Car Rental (6.0 x S\$1	00.00/day) (S\$)	600.00		
+ Doc/S	earch Fee (S\$)	2.00		
Ne	tt Liability (S\$)	3,812.00		

INSPECTION

Date of Assignment: 07/07/2020

Date Inspected: 07/07/2020 Inspected At: Hock Wah Motor Workshop Pte Ltd

(Bedok)

Blk 3011, Bedok Industrial Park E,,

#01-2008/2010/2012 Singapore 489977

Estimated Period of Repair: 5.0 days

Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,272.00 FL	*1,272.00 FL
2	1		*TAILGATE DAMPER RH	Not Necessary	227.00 FL	*- FL
3	1		*TAILGATE DAMPER LH	Not Necessary	227.00 FL	*- FL
4	1		*TAILGATE EMBLEM	Necessary	63.00 FL	*63.00 FL
5	1		*TAILGATE LOGO	Necessary	59.00 FL	*59.00 FL
6	1		*END PANEL	Badly Dented	519.00 FL	*519.00 FL
7	1		*END PANEL TOP GARNISH	Twisted	245.12 FL	*245.12 FL
8	1		*REAR BUMPER	Distorted	513.00 FL	*513.00 FL
9	1		*REAR BUMPER RETAINER RH	Not Necessary	87.00 FL	*- FL
10	1		*REAR BUMPER RETAINER LH	Not Necessary	87.00 FL	*- FL
11	1		*REAR BUMPER REFLECTOR LH	Not Necessary	69.00 FL	*- FL
12	4		*REAR BUMPER CLIP	Necessary	20.00 FL	*20.00 FL
13	1		*REAR FENDER LAMP LH	Cracked	524.00 FL	*408.00 FL
14	1		*TAILGATE WEATHERSTRIP	Torn	299.10 FL	*299.10 FL
15	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
16	1		*REAR BUMPER SPOILER	Not fitted	680.00FS	*-FS
17	1		*REAR FENDER LH (NPA)	Repair	0.00 FS	*-FS
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.			
				Sub Total (S\$)	5,171.22	3,598.22
	- List Item Discount on L Items 25.00/25.00% (S\$) 1,052.81 849.56					
				Total Parts (S\$)	4,118.41	2,748.66
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	S New	900.00	600.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	900.00	820.00
3	ANTI-RUST COATING	New	150.00	60.00
4	WIRING	New	40.00	20.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
	Gross	Labour Cost (S\$)	2,140.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >