

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20006407/APA3Q2

Date: 08/09/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00012719

Claimant
Vehicle No : SJP5205R **Insured Vehicle No :** SJH4858E

Date of Loss: 17/06/2020 Nature of Claim: TP Claim No: 1202000018527

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP5205R	Engine No:	G4FC9U624006
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMHU41BR9U719890
Reg. Date:	27/03/2009 (Man. Year: 2009)	Odometer:	88139 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,089.68	1,671.68	418.00	20.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	1,010.00	640.00	38.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,739.68	2,681.68	1,058.00	28.29
Approved Total (Overridden) (\$\$)		2,100.00		
(\$\$)	3,739.68	2,100.00	1,639.68	43.85
+ GST 7.00/7.00% (\$\$)	261.78	147.00	114.78	43.85
Nett Amount (\$\$)	4,001.46	2,247.00	1,754.46	43.85
+ Loss of Use (6.0 x S\$60.00/day) (\$\$)		360.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		2,614.45		

INSPECTION

Date of Assignment: 17/06/2020

Date Inspected: 18/06/2020 Inspected At:

Mg Solution Pte Ltd - Kaki Bukit (HQ)
25 Kaki Bukit Road 4 #04-01
Singapore 41800

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jul 2020)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP5205R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	625.00 FL	*489.10 FL
2	2		*REAR BUMPER RETAINER	Necessary	105.20 FL	*78.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Deformed	298.70 FL	*298.70 FL
4	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	91.80 FL	*- FL
5	1		*REAR BUMPER SPONGE	Cracked	168.50 FL	*109.90 FL
6	1		*REAR END PANEL	Dented	580.90 FL	*580.90 FL
7	1		*REAR END PANEL TOP GARNISH	Deformed	229.50 FL	*158.00 FL
8	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
9	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	40.00 FS	*10.00 FS
10	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*60.00 FS
11	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,509.60	2,014.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	419.92	342.92
Total Parts (\$\$)	2,089.68	1,671.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	600.00	500.00
2	TO SPRAY PAINT AFFECTED AREA	New	600.00	400.00
3	TO APPLY RUST PROOFING AND TUFF COAT	New	150.00	60.00
4	CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	150.00	50.00
Gross Labour Cost (\$\$)			1,650.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >