

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### **TAX INVOICE**

CHINA TAIPING INSURANCE (S) PTE LTD INV No. AC2104928

3 ANSON ROAD #16-00 SPRINGLEAF TOWER

SINGAPORE 079909

INV Date 13/07/2021 Reference CC3/CTI20006416/Kgs3q2

Code CTI

#### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 5986G

Insured Veh. PC 8306K

Claim No. SNM20D202154

Policy No. DMB1SN19346219000

Accident Date 16/06/2020

Inspection Date 17/06/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

**LKM** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909  Code: CTI  Policy Particulars: - THIRD PARTY CLAIM  Insured Veh. PC 8306K  Policy No. DMB1SN19346219000  Claim No. SNM20D202154  Excess (\$) 0.00	ID 5986G			
Code: CTI	TD 5986G			
Policy Particulars :- THIRD PARTY CLAIM           Insured Veh.         PC 8306K         Veh. Inspected         SHI           Policy No.         DMB1SN19346219000         Coverage (\$)         0.00           Claim No.         SNM20D202154         Excess (\$)         0.00	ID 5986G			
Insured Veh.   PC 8306K   Veh. Inspected   SHI				
Policy No.         DMB1SN19346219000         Coverage (\$)         0.00           Claim No.         SNM20D202154         Excess (\$)         0.00				
Claim No. SNM20D202154 Excess (\$) 0.00	00			
Assign From	00			
Assign From Assign Date 17/0	/06/2020			
2. Vehicle Particulars & Condition				
Make & Model TOYOTA PRIUS (A) c.c 179	98			
Engine No. HIDDEN Year of Reg. 201	18			
Chassis No. JTDKB3FU403075667 Colour M.	. P. WHITE / RED			
Odometer 156775 KM Steering IN	ORDER			
Brakes IN ORDER Modification STA	ANDARD ALLOY RIM			
General GOOD				
3. Conditions of Tyres				
Size Make Ba	lance			
R/H Front Tyre         195/65 R15         SAILUN         8 m	nm			
L/H Front Tyre 195/65 R15 SAILUN 8 m	nm			
R/H Rear Tyre         195/65 R15         SAILUN         8 m	nm			
L/H Rear Tyre 195/65 R15 SAILUN 8 m	nm			
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date 16/06/2020 Inspection Date 17/0	/06/2020			
Survey held at TRANS-CAB AUTO SERVICES PTE LTD				
NO.2 ANG MO KIO ST 63 SINGAPORE 569111				
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED RI	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working D	Days			



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5986G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BUCKLED	442.60	442.60
1	REAR BUMPER REINFORCEMENT	BENT	332.70	332.70
1	REAR BUMPER TOWING COVER	SERVICEABLE	15.40	-
1	GUARD ,REAR BUMPER ,CENTER	BUCKLED / DENTED	576.30	576.30
1	ANTENNA ,ELECTRICAL KEY	SERVICEABLE	72.00	-
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	116.50	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	117.70	-
1	REAR BUMPER SIDE RH	SERVICEABLE	123.70	-
1	REAR BUMPER SIDE LH	SERVICEABLE	123.70	-
1	REAR TAILGATE	BENT	1,147.80	1,147.80
1	REAR TAILGATE OUTER GARNISH	CRACKED	925.60	925.60
1	COVER ,REAR COMBINATION LAMP,RH	MISSING	64.50	64.50
1	BOARD ASSY ,BACK DOOR TRIM	MTG CRACKED	259.20	259.20
1	BOARD ,BACK DOOR TRIM	SERVICEABLE	225.20	-
1	PANEL ASSY ,BACK DOOR TRIM ,UPPER	SERVICEABLE	52.10	-
1	GARNISH ,BACK DOOR SIDE ,LH	SERVICEABLE	95.60	-
1	GARNISH ,BACK DOOR SIDE ,RH	SERVICEABLE	95.60	-
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	372.30	-
1	PANEL SUB-ASSY ,BODY LOWER BACK	TO REPAIR SEE LABOUR	650.30	-
1	TAILLAMP LOWER RH	SERVICEABLE	502.00	-
1	TAILLAMP UPPER RH	SERVICEABLE	451.80	-
1	TAILLAMP LOWER LH	SERVICEABLE	502.00	-
1	TAILLAMP UPPER LH	SERVICEABLE	443.30	-
1	PANEL ASSY ,DECK TRIM SIDE ,RH	TO REPAIR SEE LABOUR	355.90	-
1	BOX,DECK FLOOR ,RH	TO REPAIR SEE LABOUR	313.60	-
1	BOX,DECK FLOOR,LH	TO REPAIR SEE LABOUR	313.00	-
1	BOARD ,REAR FLOOR ,NO.1	TO REPAIR SEE LABOUR	519.00	-



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	PANEL ASSY ,DECK TRIM SIDE ,LH	SERVICEABLE	355.90	-
1	MOULDING ,BACK DOOR OUTSIDE GARNISH ,LOWER LH	SERVICEABLE	56.50	-
1	MOULDING ,BACK DOOR OUTSIDE GARNISH ,LOWER RH	SERVICEABLE	56.50	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	445.50	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	445.50	-
1	COVER ,FLOOR UNDER ,NO.1	SERVICEABLE	175.10	-
1	COVER ,FLOOR UNDER ,NO.2	SERVICEABLE	241.90	-
1	COVER ,REAR FLOOR	TO REPAIR SEE LABOUR	229.90	-
1	COVER ,DECK TRIM ,REAR	SERVICEABLE	126.70	-
1	COVER ASSY ,TONNEAU	SERVICEABLE	979.40	-
1	PAN, REAR FLOOR	TO REPAIR SEE LABOUR	583.40	-
1	EXTENSION ,REAR FLOOR PAN TO QUARTER PANEL, RH	TO REPAIR SEE LABOUR	196.50	-
1	EXTENSION ,REAR FLOOR PAN TO QUARTER PANEL, LH	TO REPAIR SEE LABOUR	196.50	-
1	EXTENSION ,REAR FLOOR SIDE PANEL ,RH	TO REPAIR SEE LABOUR	78.30	-
1	EXTENSION ,REAR FLOOR SIDE PANEL ,LH	TO REPAIR SEE LABOUR	78.30	-
1	LOCK ASSY ,BACK DOOR W/COURTESY LAMP SWITCH	SERVICEABLE	467.00	-
1	COVER ,BACK DOOR LOCK	SERVICEABLE	30.20	-
1	SWITCH ASSY ,BACK DOOR OPENER	SERVICEABLE	179.10	-
1	STRIKER ASSY ,BACK DOOR LOCK	SERVICEABLE	25.80	-
1	SPOILER ,SUB ASSY ,REAR	WARPED / CRACKED	1,575.40	1,575.40
1	LAMP SUB ASSY ,LICENSE PLATE	CRACKED	287.80	287.80
1	LAMP SET ,STOP CENTER	SERVICEABLE	192.30	-
1	GLASS ,BACK WINDOW FIX	SHATTERED	761.40	761.40
1	DAM ,BACK DOOR GLASS ADHESIVE ,NO.2	NECESSARY	28.90	28.90
1	MOULDING ,BACK WINDOW ,LOWER NO.2	NECESSARY	23.60	23.60
1	MOULDING ,BACK WINDOW ,OUTSIDE LH NO.2	NECESSARY	30.90	30.90
1	MOULDING ,BACK WINDOW ,OUTSIDE RH NO.2	NECESSARY	30.90	30.90
1	SPACER ,BACK WINDOW GLASS	NECESSARY	10.20	10.20



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	WIRE ,BACK DOOR ,NO.2	SERVICEABLE	294.40	-
1	WIRE ,LUGGAGE ROOM ,NO.3	SERVICEABLE	170.70	-
1	WIRE ,BACK DOOR ,NO.1	SERVICEABLE	247.40	-
1	STAY ASSY ,BACK DOOR ,LH	SERVICEABLE	242.50	-
1	STAY ASSY ,BACK DOOR ,RH	SERVICEABLE	242.50	-
1	HINGE ASSY ,BACK DOOR ,LH	SERVICEABLE	61.00	-
1	HINGE ASSY ,BACK DOOR ,RH	SERVICEABLE	61.00	-
	LESS 25% DISCOUNT		-4,604.58	-1,624.45
			13,813.72	4,873.35
	SPECIAL NETT ITEMS			
1	SET PAKING AID (SN)	DENTED	700.00	220.00
	SET REAR BUMPER CLIP (SN)	NECESSARY	75.00	65.00
	REAR WINDSCREEN SEALANT (SN)	NECESSARY	150.00	80.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	180.00	180.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	120.00	30.00
1	REAR TAILGATE TOYOTA LOGO (SN)	NOT NECESSARY	47.00	-
1	REAR TAILGATE WORDING 'PRIUS' (SN)	NOT NECESSARY	52.90	-
1	REAR TAILGATE WORDING 'HYBRID' (SN)	NOT NECESSARY	53.50	-
1	REAR TAILGATE STICKER 'TRANS-CAB' (SN)	NECESSARY	80.00	30.00
1	REAR TAILGATE STICKER '6555-3333' (SN)	NECESSARY	80.00	30.00
1	REAR BUMPER PROTECTOR (SN)	NECESSARY	120.00	30.00
1	SET REAR RH BUMPER RETAINER CLIP (SN)	NOT NECESSARY	38.00	-
1	REAR NUMBER PLATE WITH HOLDER (SN)	SERVICEABLE	200.00	-
1	SET REAR LH BUMPER RETAINER CLIP (SN)	NOT NECESSARY	38.00	-
1	SET END PANEL INNER TRIM CLIP (SN)	NOT NECESSARY	35.00	-
1	SET END PANEL INSULATION PAD (SN)	NOT NECESSARY	200.00	-
2	END PANEL SEAM SEALANT (SN)	NOT NECESSARY	170.00	-
1	SET TAILLAMP LOWER CLIP (SN)	NOT NECESSARY	35.00	-
1	SET TAILLAMP UPPER CLIP (SN)	NOT NECESSARY	35.00	-
1	SET REAR BOOT TRIM BOARD CLIP (SN)	NOT NECESSARY	45.00	-
1	SET REAR BOOT OUTER GARNISH CLIP (SN)	NOT NECESSARY	35.00	-
1	WHEEL RIM COVER (SN)	SERVICEABLE	211.50	-
1	TYRE 195/65/15 (SN)	SERVICEABLE	350.00	-



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	WHEEL ,RIM (SN)	SERVICEABLE	1,879.40	-
1	SET REAR SPOILER CLIP (SN)	NECESSARY	45.00	45.00
			4,975.30	710.00
	<u>LABOUR</u>			
	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		380.00	50.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		7,500.00	880.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY ,BODY LOWER BACK,PANEL ASSY ,DECK TRIM SIDE ,RH,BOX ,DECK FLOOR ,RH ,BOX ,DECK FLOOR,LH,BOARD ,REAR FLOOR ,NO.1,TAILLAMP PANEL LH,TAILLAMP PANEL RH,CVER ,REAR FLOOR,PAN,REAR FLOOR,}		7,500.00	500.00
	EXTENSION,REAR FLOOR PAN TO QUARTER PANEL,RH,EXTENSION,REAR FLOOR PAN TO QUARTER PANEL,LH,EXTENSION ,REAR FLOOR SIDE PANEL,RH AND EXTENSION ,REAR FLOOR SIDE PANEL,LH.}		-	-
	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REINSTALL REAR BUMPER PARKING SENSOR .		170.00	50.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER , TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT REAR (BIG) W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR .		170.00	120.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR .	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED .		170.00	20.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT .	NOT NECESSARY	220.00	-
	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT REAR (SMALL)W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR .		170.00	60.00



**RECOMMENDED COST OF REPAIRS** 

#### **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

7,323.35

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO SUPPLY AND RE-DO REAR END PANEL INSULATION PADDING .	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING .	NOT NECESSARY	170.00	-
			18,480.00	1,740.00
	GRAND TOTAL		37,269.02	7,323.35

Report Ref No. CC3/CTI20006416/Kgs3q2

KONG SENG CHEONG

**Licensed Appraiser** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

#### PHOTOGRAPHS FOR VEHICLE NO. SHD 5986G

#### **INSPECTION**















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

#### PHOTOGRAPHS FOR VEHICLE NO. SHD 5986G

#### **RE-INSPECTION**















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

