



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2007654  
INV Date 13/11/2020  
Reference CC6/FCI20006427/Aea3q2  
Code FCI2



### PROFESSIONAL SERVICE FEE

Vehicle No. SJM 9712H  
Insured Veh. SHC 3710D  
Claim No. D20002481MFSH  
Policy No. D-18088936MFSH  
Accident Date 15/06/2020  
Inspection Date 16/06/2020

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 500.00        |
| <b>Subtotal</b>                | <b>500.00</b> |
| <b>GST (7%)</b>                | <b>35.00</b>  |
| <b>Grand Total</b>             | <b>535.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC6/FCI20006427/Aea3q2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-11-2020



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |                |                       |            |
|---------------------|----------------|-----------------------|------------|
| <b>Insured Veh.</b> | SHC 3710D      | <b>Veh. Inspected</b> | SJM 9712H  |
| <b>Policy No.</b>   | D-18088936MFSH | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | D20002481MFSH  | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | VIC            | <b>Assign Date</b>    | 16/06/2020 |

### 2. Vehicle Particulars & Condition

|                         |               |                     |            |
|-------------------------|---------------|---------------------|------------|
| <b>Make &amp; Model</b> | TOYOTA AXIO   | <b>c.c</b>          | 1496       |
| <b>Engine No.</b>       | HIDDEN        | <b>Year of Reg.</b> | 2009       |
| <b>Chassis No.</b>      | NZE1416094469 | <b>Colour</b>       | BLUE       |
| <b>Odometer</b>         | 136680        | <b>Steering</b>     | IN ORDER   |
| <b>Brakes</b>           | IN ORDER      | <b>Modification</b> | SPORTS RIM |
| <b>General</b>          | GOOD          |                     |            |

### 3. Conditions of Tyres

|                       |             |             |                |
|-----------------------|-------------|-------------|----------------|
|                       | <b>Size</b> | <b>Make</b> | <b>Balance</b> |
| <b>R/H Front Tyre</b> | 205/55 R15  | NEXEN       | 6 mm           |
| <b>L/H Front Tyre</b> | 205/55 R15  | NEXEN       | 6 mm           |
| <b>R/H Rear Tyre</b>  | 205/55 R15  | NEXEN       | 6 mm           |
| <b>L/H Rear Tyre</b>  | 205/55 R15  | NEXEN       | 6 mm           |

### 4. Description of Damages

|                                                                        |
|------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.<br>DAMAGES SEE DETAILS. |
|------------------------------------------------------------------------|

### 5. General Information

|                       |                                                                                     |                        |            |
|-----------------------|-------------------------------------------------------------------------------------|------------------------|------------|
| <b>Accident Date</b>  | 15/06/2020                                                                          | <b>Inspection Date</b> | 16/06/2020 |
| <b>Survey held at</b> | ZERO GRAVITY<br>2 KAKI BUKIT AVE 2<br>#01-25 KAKI BUKIT AUTOHUB<br>SINGAPORE 417921 |                        |            |

### 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

### 5b. Estimate Days of Repair

|                                     |                       |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | <b>5 Working Days</b> |
|-------------------------------------|-----------------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 9712H

| Qty | Description of Parts                       | Condition     | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--------------------------------------------|---------------|----------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>         |               |                            |                   |
| 1   | DOOR (L/H/F)                               | DENTED        | 1,234.72                   | 1,234.72          |
| 1   | DOOR (L/H/R)                               | DENTED        | 1,123.95                   | 1,123.95          |
| 2   | DOOR STICKER (FRAME) (L/H/F) @\$51.72      | NECESSARY     | 103.44                     | 103.44            |
| 2   | DOOR STICKER (FRAME) (L/H/R) @\$51.72      | NECESSARY     | 103.44                     | 103.44            |
| 1   | WINDOW REGULATOR (L/H/F)                   | DAMAGED       | 193.40                     | 193.40            |
| 1   | WINDOW REGULATOR (L/H/R)                   | NOT NECESSARY | 193.40                     | -                 |
| 1   | WINDOW REGULATOR MOTOR (L/H/F)             | NOT NECESSARY | 562.86                     | -                 |
| 1   | WINDOW REGULATOR MOTOR (L/H/R)             | NOT NECESSARY | 562.86                     | -                 |
| 2   | DOOR HINGE (R/H LOWER) @\$75.18            | BENT          | 150.36                     | 75.18             |
| 2   | DOOR HINGE (R/H UPPER) @\$75.18            | NOT NECESSARY | 150.36                     | -                 |
| 1   | DOOR CHECKER (L/H/R)                       | NOT NECESSARY | 132.17                     | -                 |
| 1   | DOOR INNER LOCK (L/H/F)                    | DAMAGED       | 441.84                     | 441.84            |
| 1   | DOOR WEATHERSTRIP (R/H/F)                  | NOT NECESSARY | 171.20                     | -                 |
| 1   | DOOR WEATHERSTRIP (R/H/R)                  | NOT NECESSARY | 171.20                     | -                 |
| 1   | DOOR CHANNEL (L/H/F)                       | NOT NECESSARY | 135.84                     | -                 |
| 1   | BRACKET DOOR CHANNEL (L/H/F)               | BENT          | 85.40                      | 85.40             |
| 1   | DOOR STOPPER RUBBER (L/H/F)                | NOT NECESSARY | 13.97                      | -                 |
| 1   | DOOR STOPPER RUBBER (L/H/R)                | NOT NECESSARY | 13.97                      | -                 |
| 1   | DOOR INNER TRIM BOARD (L/H/F)              | CRACKED       | 875.24                     | 480.10            |
| 10  | DOOR INNER TRIM BOARD CLIP (L/H/F) @\$4.50 | NECESSARY     | 45.00                      | 30.00             |
| 10  | DOOR INNER TRIM BOARD CLIP (R/H/R) @\$4.50 | NOT NECESSARY | 45.00                      | -                 |
| 1   | DOOR FRAME BEADING (L/H/F)                 | NOT NECESSARY | 342.84                     | -                 |
| 1   | DOOR FRAME BEADING (L/H/R)                 | NOT NECESSARY | 342.84                     | -                 |
| 1   | DOOR HANDLE (OUTER) (L/H/F)                | NOT NECESSARY | 328.00                     | -                 |
| 1   | DOOR HANDLE (OUTER) BASE (L/H/F)           | NOT NECESSARY | 286.76                     | -                 |
| 1   | WINDOW OUTER RUBBER (L/H/F)                | NOT NECESSARY | 145.25                     | -                 |
| 1   | DOOR CATCH (L/H/F)                         | NOT NECESSARY | 23.50                      | -                 |
| 1   | SWITCH (DOOR) (L/H/F)                      | NOT NECESSARY | 56.40                      | -                 |
| 1   | ROCKER PANEL (L/H)                         | NOT NECESSARY | 414.15                     | -                 |
| 1   | CENTER PILLAR (L/H)                        | NOT NECESSARY | 483.10                     | -                 |

Report Ref No. CC6/FCI20006427/Aea3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                                                         | Description of Parts                                   | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|--------------------------------------------------------|---------------|---------------------------|-------------------|
|                                                                             | LESS 25% DISCOUNT                                      |               | -2,233.12                 | -967.87           |
|                                                                             |                                                        |               | 6,699.34                  | 2,903.60          |
| 2                                                                           | DOOR ANTI SPLASH PLASTIC SEAL @\$96.55 (SN)            | NECESSARY     | 193.10                    | 80.00             |
|                                                                             | LESS 25% DISCOUNT                                      |               | -48.28                    | -                 |
|                                                                             |                                                        |               | 144.82                    | 80.00             |
|                                                                             | <b><u>SPECIAL NETT ITEMS</u></b>                       |               |                           |                   |
| 1                                                                           | SIDE SKIRT (L/H) (SN)                                  | DEFORMED      | 500.00                    | 500.00            |
|                                                                             |                                                        |               | 500.00                    | 500.00            |
|                                                                             | <b><u>LABOUR</u></b>                                   |               |                           |                   |
|                                                                             | TO PROVIDE UNDER TURFCOAT.                             |               | 150.00                    | 60.00             |
|                                                                             | PANEL BEATING & REPLACING OF THE ABOVE .               |               | 1,000.00                  | 700.00            |
|                                                                             | TO PUTTY AND RESPRAY AFFECTED PORTION .                |               | 1,000.00                  | 700.00            |
|                                                                             | TO REMOVE ,TRANSFER & INSTALL RELATED COMPONENT.       | NOT NECESSARY | 250.00                    | -                 |
|                                                                             | TO REMOVE AND REFIT COMPONENTS /FACILITATE THE REPAIR. |               | 180.00                    | 160.00            |
|                                                                             | TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT. |               | 80.00                     | 30.00             |
|                                                                             |                                                        |               | 2,660.00                  | 1,650.00          |
| <b>GRAND TOTAL</b>                                                          |                                                        |               | <b>10,004.16</b>          | <b>5,133.60</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                        |               |                           | <b>4,100.00</b>   |

Report Ref No. CC6/FCI20006427/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJM 9712H

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJM 9712H

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

