

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20006441/EYF3E2

Date: 27/07/2020

REFERENCE

Insured/Claimant:	KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD	Policy No:	DMCVSN1835581901
Date of Loss:	03/04/2020	Nature of Claim:	OD
		Claim No:	SNM20D201655/C01/TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD8414G	Engine No:	D13439949
Make & Model:	VOLVO FMX420, 12.8 D 84RT SC (M)	Chassis No:	YV2JG10GXE755649
Reg. Date:	23/12/2013 (Man. Year: 2013)	Odometer:	0 km
Colour:	White		
Engine Capacity:	12777 cc		
Market Value/New Car Price:	S\$60,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	315/80 R22.5	Rear Tyre Size:	315/80 R22.5
Front Left Side:	ALLROUND 5 mm	Rear Left Side:	ALLROUND 5 mm
Front Right Side:	ALLROUND 5 mm	Rear Right Side:	ALLROUND 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,329.70	15,117.93	12,211.77	44.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,050.00	3,500.00	4,550.00	56.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,379.70	18,617.93	16,761.77	47.38
Approved Total (Overridden) (S\$)		14,900.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	33,879.70	13,400.00	20,479.70	60.45
+ GST 7.00/7.00% (S\$)	2,371.58	938.00	1,433.58	60.45
Nett Amount (S\$)	36,251.28	14,338.00	21,913.28	60.45

INSPECTION

Date of Assignment:	18/06/2020		
Date Inspected:	19/06/2020	Inspected At:	Vfix Auto Service Pte Ltd (HQ) 26 Chia Ping Road Singapore 619977
Estimated Period of Repair:	14.0 days		

Adjuster: CHEN TSUE YEE**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Jul 2020)	
Parts:	N/A	VOLVO FMX420 12.8 D 84RT SC (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD8414G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	4,043.40 F	*4,043.40 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	890.00 F	*890.00 FL
3	1		*FRONT BUMPER TOP PAD	Not Necessary	458.00 F	*- FL
4	1		*FRONT BUMPER TOP PAD CENTER GARNISH	Not Necessary	245.00 F	*- FL
5	1		*FRONT BUMPER CENTER GRILLE	Not Necessary	487.90 F	*- FL
6	1		*FRONT BUMPER SIDE PAD	Broken	457.60 F	*457.60 FL
7	1		*FRONT BUMPER LOWER PAD	Dented	475.00 F	*475.00 FL
8	1		*FRONT BUMPER LOWER PAD OUTER COVER	Not Necessary	326.50 F	*- FL
9	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	475.00 F	*- FL
10	1		*FRONT BUMPER LOWER STEP PLATE	Not Necessary	370.00 F	*- FL
11	1		*FRONT BUMPER LOWER STEP PLATE TOP CHROME	Not Necessary	245.60 F	*- FL
12	1		*FRONT BUMPER TOWING COVER	Not Necessary	42.00 F	*- FL
13	1		*FRONT BUMPER FOG LAMP LH	Broken	420.00 F	*420.00 FL
14	1		*FRONT BUMPER FOG LAMP COVER LH	Broken	120.00 F	*120.00 FL
15	1		*FRONT SIDE BUMPER LH	Broken	476.00 F	*476.00 FL
16	1		*FRONT HEAD LAMP LH	Cracked	375.00 F	*375.00 FL
17	1		*FRONT HEAD LAMP RIM LH	Broken	195.70 F	*195.70 FL
18	1		*FRONT PARKING LAMP LH	Not Necessary	274.00 F	*- FL
19	1		*FRONT SIGNAL LAMP LH	Not Necessary	252.00 F	*- FL
20	1		*FRONT DOOR BOTTOM STEP GARNISH LH	Not Necessary	450.00 F	*- FL
21	1		*FRONT DOOR BOTTOM STEP GARNISH SIDE COVER LH	Cracked	680.00 F	*680.00 FL
22	1		*FRONT DOOR PILLAR LH INNER	Not Necessary	820.00 F	*- FL
23	1		*FRONT DOOR PILLAR LH CENTER	Repair	850.00 F	*- FL
24	1		*FRONT DOOR LH	Dented	3,300.00 F	*3,300.00 FL
25	1		*FRONT DOOR WINDOW GLASS	Broken	650.00 F	*650.00 FL
26	1		*FRONT DOOR OUTER MOULDING	Crushed	217.00 F	*217.00 FL
27	1		*FRONT DOOR OUTER GARNISH	Not Necessary	98.00 F	*- FL
28	1		*FRONT DOOR OUTER HANDLER	Cut	244.00 F	*244.00 FL
29	1		*FRONT DOOR OUTER KEYLOCK	Bent	110.00 F	*110.00 FL
30	2		*FRONT DOOR HINGE LH	Bent	180.00 F	*180.00 FL
31	1		*FRONT DOOR JACKER	Not Necessary	160.00 F	*- FL
32	1		*FRONT DOOR INNER LOCK	Cracked	320.00 F	*320.00 FL
33	1		*FRONT DOOR LOCK CATCH	Not Necessary	46.00 F	*- FL
34	1		*FRONT DOOR LOCK WEATHER STRIP	Torn	210.00 F	*210.00 FL
35	1		*FRONT DOOR INNER TRIM	Deformed	317.00 F	*317.00 FL
36	1		*CORNER PANEL (LH)	Dented	1,210.00 F	*657.00 FL
37	1		*FRONT DOOR REGULATOR MOTOR	Not Necessary	790.00 F	*- FL
38	1		*FRONT DOOR GEARLINKAGE	Bent	220.00 F	*220.00 FL
39	1		*FRONT TOP STEP BOARD LH	Not Necessary	576.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT BOTTOM STEP BOARD LH	Not Necessary	450.00 F	*- FL
41	1		*FRONT SIDE STEP BOARD GARNISH LH	Not Necessary	370.00 F	*- FL
42	1		*FRONT STEP PLATE LH	Not Necessary	380.00 F	*- FL
43	1		*FRONT SIDE MIRROR HOUSING LH	Broken	670.00 F	*670.00 FL
44	1		*FRONT SIDE MIRROR HOUSING BOTTOM BRACKET LH	Cut	90.00 F	*90.00 FL
45	1		*FRONT SIDE MIRROR COVER LH	Broken	210.00 F	*210.00 FL
46	1		*FRONT SIDE MIRROR BOTTOM COVER LH	Missing	150.00 F	*150.00 FL
47	1		*FRONT SIDE MIRROR GLASS LH	Broken	140.00 F	*140.00 FL
48	1		*FRONT SIDE MIRROR BOTTOM GLASS LH	Broken	90.00 F	*90.00 FL
49	1		*FRONT FENDER MUDGUARD REAR LH	Not Necessary	489.00 F	*- FL
50	1		*SIDE MIRROR BRACKET (LH)	Bent	1,314.00 F	*890.00 FL
51	1		*FRONT TYRE LH	Not Necessary	400.00 FS	*- FS
52	1		*FRONT RIM LH	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 27,329.70 16,797.70
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 1,679.77

Total Parts (\$\$) 27,329.70 15,117.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE DAMAGED BODY PANEL WITH ALL NECESSARY COMPONENTS/ ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN FRONT DOOR PILLAR, REPAIR / RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS / ATTACHMENTS	New	4,000.00	2,000.00
2	TO SPRAY PAINT REPLACED / REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	2,000.00	1,000.00
3	TO CHECK AND REFIT WIRING	New	600.00	250.00
4	TO RESET AND DIAGNOSIS FAULT CODE	New	700.00	150.00
5	TO DISMANTLE AND REFIX FRONT DOOR PART	New	150.00	100.00
6	TO DISMANTLE AND REFIX INTERIOR, CARPET AND CUSHION	New	600.00	0.00
Gross Labour Cost (\$\$)			8,050.00	3,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >