

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20006443/APA3Q2
Date: 20/05/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLQ6069G	Insured Vehicle No :	SHD3212U
Date of Loss:	18/06/2020	Nature of Claim:	TP
		Claim No:	MCT20060172

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ6069G	Engine No:	LEB5913095
Make & Model:	HONDA VEZEL, 1.5 HYBRID (A)	Chassis No:	RU31213086
Reg. Date:	01/07/2017 (Man. Year: 2017)	Odometer:	204797 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	RADAR 6 mm	Rear Left Side:	RADAR 6 mm
Front Right Side:	RADAR 6 mm	Rear Right Side:	RADAR 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,688.80	3,199.76	489.04	13.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,540.00	790.00	750.00	48.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,228.80	3,989.76	1,239.04	23.70
Approved Total (Overridden) (S\$)		3,200.00		

(S\$)	5,228.80	3,200.00	2,028.80	38.80
+ GST 7.00/7.00% (S\$)	366.02	224.00	142.02	38.80
Nett Amount (S\$)	5,594.82	3,424.00	2,170.82	38.80
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		3,831.45		

INSPECTION

Date of Assignment: 19/06/2020

Date Inspected: 19/06/2020

Estimated Period of Repair: 3.0 days

Inspected At:

N-51 Automotive Pte Ltd (HQ)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB
 Singapore 417921

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Sep 2020)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ6069G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Dented	950.00 FL	*950.00 FL
2	1		*FRONT RH DOOR BLACK TAPE	Necessary	18.50 FL	*18.50 FL
3	1		*FRONT RH DOOR GLASS CHANNEL WEATHERSTRIP	Cut	88.50 FL	*88.50 FL
4	1		*FRONT RH DOOR GLASS CHANNEL WEATHERSTRIP SEAT (FRONT)	Necessary	30.00 FL	*30.00 FL
5	2		*FRONT RH DOOR INNER RUBBER STOPPER L/R	Not Necessary	37.00 FL	*- FL
6	1		*FRONT RH DOOR INNER TRIM BOARD	Cracked	480.00 FL	*480.00 FL
7	1		*FRONT RH DOOR LOWER WEATHER STRIP	Not Necessary	28.50 FL	*- FL
8	1		*FRONT RH DOOR MECHANISM LOCK	Damaged	196.30 FL	*196.30 FL
9	1		*FRONT RH DOOR OUTER HANDLE	Cracked	385.00 FL	*211.00 FL
10	1		*FRONT RH DOOR OUTER HANDLE INNER RUBBER GASKET	Necessary	28.00 FL	*28.00 FL
11	1		*FRONT RH DOOR OUTER MOULDING	Deformed	60.00 FL	*60.00 FL
12	1		*FRONT RH DOOR POWER SWITCH	Not Necessary	249.30 FL	*- FL
13	1		*FRONT RH DOOR SIDE MIRROR	Damaged	926.50 FL	*926.50 FL
14	1		*FRONT RH DOOR SIDE MIRROR COVER	Repair	80.00 FL	*- FL
15	1		*FRONT RH DOOR WEATHERSTRIP SEAL (REAR)	Not Necessary	17.50 FL	*- FL
16	1		*FRONT RH DOOR WINDOW GLASS	Shattered	590.50 FL	*590.50 FL
17	1		*FRONT RH DOOR WINDOW GLASS REGULATOR	Damaged	382.90 FL	*382.90 FL
18	1		*SET FRONT RH DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,598.50	3,992.20
- List Item Discount on L Items 20.00/20.00% (S\$)	909.70	792.44
Total Parts (S\$)	3,688.80	3,199.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,CHARGE WINDOW GLASS	New	60.00	40.00
2	TO SEND VEHICLE FOR CLEANING ,SHAMPOO ,UPHOLSTERY AND CUSHION SEAT	New	150.00	60.00
3	TO TRANSFER DOOR GLASS ,REGULATOR GEAR MOTOR ,RAILING ,CHANNEL ,TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	100.00	40.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAI ,PORTION ,AND WHERE CONSISTEN TO THE ACCIDENT	New	650.00	300.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	580.00	350.00
Gross Labour Cost (S\$)			1,540.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >