



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2007857  
INV Date 23/11/2020  
Reference CC4/FCI20006447/Kka3q2  
Code FCI2



#### PROFESSIONAL SERVICE FEE

Vehicle No. SJY 3925L  
Insured Veh. SH 9126U  
Claim No. D20002290MFSH/1  
Policy No. D-20094922MFSH  
Accident Date 30/05/2020  
Inspection Date 08/06/2020

Description	Total
Survey Inspection	174.00
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>174.00</b>
<b>GST (7%)</b>	<b>12.18</b>
<b>Grand Total</b>	<b>186.18</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20006447/Kka3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 23-11-2020		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SH 9126U	Veh. Inspected	SJY 3925L	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20002290MFSH/1	Excess (\$)	0.00	
Assign From	CHRIS	Assign Date	05/06/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	SUZUKI SX4 SPORT (A)	c.c	1586	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JSAGYA21S00340611	Colour	METALLIC PEARL WHITE	
Odometer	183631	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	MICHELIN	9 mm	
L/H Front Tyre	205/60 R16	MICHELIN	9 mm	
R/H Rear Tyre	205/60 R16	MICHELIN	8 mm	
L/H Rear Tyre	205/60 R16	MICHELIN	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	30/05/2020	Inspection Date	08/06/2020	
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 3925L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	BUCKLED	790.45	790.45
8	FRONT BUMPER CLIPS @\$5.80	NECESSARY	46.40	46.40
1	FRONT BUMPER SIDE BRACKET RH	TO REPAIR SEE LABOUR	17.95	-
1	FRONT FENDER RH	BUCKLED	272.20	272.20
1	FRONT FENDER INNER LINER RH	DISTORTED / CRACKED	58.65	58.65
8	FRONT FENDER INNER LINER CLIPS RH @\$5.80	NECESSARY	46.40	46.40
1	FRONT FENDER "VVT" EMBLEM RH	NECESSARY	52.20	52.20
1	FRONT WHEEL ARCH EXTENSION COVER RH	BUCKLED	195.80	195.80
1	FRONT HEADLAMP RH	CUT	369.05	369.05
1	FRONT DOOR RH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 15% DISCOUNT		-277.37	-274.67
			1,571.73	1,556.48
	<b><u>LABOUR</u></b>			
	LABOUR CHARGES TO REMOVE,REFIX,REPLACE,REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF FRONT BUMPER SIDE BRACKET RH AND FRONT DOOR RH.		600.00	400.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER,FRONT FENDER RH,FRONT DOOR RH & ETC.		700.00	600.00
	TO CHECK WIRING & ELECTRICAL SYSTEM.		80.00	20.00
			1,380.00	1,020.00
	<b>GRAND TOTAL</b>		<b>2,951.73</b>	<b>2,576.48</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,000.00</b>

Report Ref No. CC4/FCI20006447/Kka3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJY 3925L

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

