

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315



Reg. No: 52983356E GST Reg. No. 20-0405911-H

### TAX INVOICE

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No.

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSE

SINGAPORE 189556

NA2003418

**INV** Date 30/06/2020

Reference NS/INC20006448/T1tf3n2

Code



#### PROFESSIONAL SERVICE FEE

Vehicle No. SHA 8190G

Insured Veh. FT 3112P

Claim No. MT/1094693-002

Policy No. 5103500308-01

Accident Date 17/06/2020

Inspection Date 18/06/2020

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'National Assessment Centre Services'

**National Assessment Centre Services** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref:	NS/INC20006448/T1tf3n2		
		D UNION HOUSESINGAPORE	Date:	30-06-2020 INC4	
1.		Policy Particulars	:- THIRI	D PARTY CLAIM	
	Insured Veh.	FT 3112P	Veh. lı	nspected	SHA 8190G
	Policy No.	5103500308-01	Cover	age (\$)	0.00
	Claim No.	MT/1094693-002	Exces	s (\$)	0.00
	Assign From		Assig	n Date	18/06/2020
2.	•	Vehicle Partic	culars 8	Condition	
	Make & Model	HYUNDAI I40	c.c		1685
	Engine No.	HIDDEN	Year o	f Reg.	2015
	Chassis No.	KMHLB41UMGU075316	Colou	r	YELLOW
	Odometer	609904	Steering		IN ORDER
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/60 R16	HANKO	OOK	6 mm
	L/H Front Tyre	205/60 R16	HANKO	OOK	6 mm
	R/H Rear Tyre	205/60 R16	HANKO	OOK	6 mm
	L/H Rear Tyre	205/60 R16	HANKO	OOK	6 mm
4.		Description			
	THE VEHICLE SU	STAINED DAMAGES AT THE FR	ONT O/S	PORTION AND UN	IDERCARRIAGE.
	DAMAGES SEE D	ETAILS.			
5.		Genera	l Inform	ation	
	Accident Date	17/06/2020	Inspec	tion Date	18/06/2020
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD  59 LOYANG DRIVE SINGAPORE 508969				
5a.		Re	emarks		
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W			
5b.	5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315



Reg. No: 52983356E GST Reg. No. 20-0405911-H

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 8190G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER COVER	DEFORMED	544.50	544.50
1	FRONT BUMPER SIDE BRACKET-RH	DEFORMED	24.60	24.60
1	FRONT BUMPER TOP BRACKET-RH	NOT NECESSARY	22.40	-
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT BUMPER GRILLE-RH	CRACKED	93.60	93.60
1	HEADLAMP-RH	NOT NECESSARY	1,388.00	-
1	HEADLAMP SUPPORT TOP COVER-RH	NOT NECESSARY	222.60	-
1	FRONT STEEL RIM-RH	BENT	650.60	650.60
1	FRONT WHEEL BEARING-RH	NOT NECESSARY	540.50	-
1	FRONT WHEEL HUB-RH	NOT NECESSARY	153.60	-
1	FRONT SHOCK ABSORBER-RH	NOT NECESSARY	342.20	-
1	FRONT SHOCK ABSORBER MOUNTING-RH	NOT NECESSARY	217.60	-
1	FRONT SUSPENSION UPPER ARM-RH	NOT NECESSARY	250.40	-
1	STEERING TIE ROD-RH	BENT	135.00	135.00
1	STEERING TIE ROD END-RH	BENT	125.20	125.20
1	STEERING BALL JOINT-RH	NOT NECESSARY	73.10	-
1	STABILIZER BAR LINKS-RH	NOT NECESSARY	68.10	-
1	FRONT SUSPENSION LOWER ARM-RH	BENT	595.90	595.90
1	ENGINE UNDERCOVER	TORN	334.60	334.60
1	ENGINE LOWER COVER-RH	TORN	56.30	56.30
1	WIPER CONTAINER & MOTOR	DEFORMED	136.90	136.90
	LESS 20% DISCOUNT		-1,199.54	-543.84
			4,798.16	2,175.36
	SPECIAL NETT ITEMS			
1	ADVERTISEMENT-FRONT BUMPER (SN)	NECESSARY	100.00	100.00
1	FRONT TYRE-RH (80%)(SN)	PUNCTURE	216.00	172.80
			316.00	272.80
	<u>LABOUR</u>			
	PANEL BEATING.		900.00	280.00

Report Ref No. NS/INC20006448/T1tf3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING CHARGE.		300.00	200.00
	TUFF KOTE.	NOT NECESSARY	80.00	-
	WIRING CHARGE.		100.00	30.00
	FRONT WHEEL ALIGNMENT.		100.00	80.00
	REMOVE/REFIX FRONT UNDERCARRIAGE.		300.00	150.00
			1,780.00	740.00
	GRAND TOTAL		6,894.16	3,188.16

RE	COMMENDED COST OF LUMP SUM REPAIRS		2,550.00
(TC	ITS PRE-ACCIDENT CONDITION)		
(CC	NFIRMED)		

Report Ref No. NS/INC20006448/T1tf3n2

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**Automotive Assessor** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

### PHOTOGRAPHS FOR VEHICLE NO. SHA 8190G

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

### PHOTOGRAPHS FOR VEHICLE NO. SHA 8190G

RE-INSPECTION









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

### PHOTOGRAPHS FOR VEHICLE NO. SHA 8190G

### RE-INSPECTION







