

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 7885M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR PANEL BUMPER SIDE RETAINERS	NOT NECESSARY	350.00	-
1	PANEL BUMPER REFLECTORS	NOT NECESSARY	720.00	-
1	RUBBER MOULDING	NOT NECESSARY	120.00	-
			1,190.00	-
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT RH RIM (SN)	CUT	3,200.00	500.00
1	REAR CARBON FIBRE PANEL (SN) (CUT)	NOT CONSISTENT WITH THE IMPACT	6,800.00	-
1	REAR L/H PANEL BUMPER CLIP (SN)	NOT NECESSARY	150.00	-
			10,150.00	500.00
	<u>LABOUR</u>			
	REMOVE AND REFIT REAR CARBON FIBRE PANEL.	NOT NECESSARY	500.00	-
	REMOVE AND REFIT REAR PANEL BUMPER.	NOT NECESSARY	500.00	-
	REMOVE, REFIT AND REPLACED DAMAGE AND CHECK UP REAR ELECTRICAL WIRING.	NOT NECESSARY	150.00	-
	REMOVE AND REFIT INNER GARNISHES TRIM TO ASSIST REPAIR. (REMOVE, REFIT FRONT RH RIM & ALIGNMENT)		200.00	100.00
	TO APPLY UNDERCOATING ON REPLACED PANEL.	NOT NECESSARY	120.00	-
	TO RESPRAY PAINTING.	NOT NECESSARY	800.00	-
			2,270.00	100.00
GRAND TOTAL			13,610.00	600.00
RECOMMENDED COST OF REPAIRS				600.00

Report Ref No. CS/SGK20006451/Esf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.