

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20006464/AES3Q2

**Date:** 24/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100095520

**Claimant**  
**Vehicle No :** SMH5883P **Insured Vehicle No :** SJJ4699L

Date of Loss: 18/06/2020 Nature of Claim: TP Claim No: 1211750911SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH5883P		
Make & Model:	JAGUAR XE, 2.0 I4 (A)	Engine No:	170329Y0162PT204
Reg. Date:	31/10/2017 (Man. Year: 2017)	Chassis No:	SAJAB4AX6JCP21619
Colour:	Black	Odometer:	85359 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,312.51	6,708.73	12,603.78	65.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,450.00	1,160.00	3,290.00	73.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,762.51</b>	<b>7,868.73</b>	<b>15,893.78</b>	<b>66.89</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,200.00</b>		
<b>(S\$)</b>	23,762.51	6,200.00	17,562.51	73.91
<b>+ GST 7.00/7.00% (S\$)</b>	1,663.38	434.00	1,229.38	73.91
<b>Nett Amount (S\$)</b>	<b>25,425.89</b>	<b>6,634.00</b>	<b>18,791.89</b>	<b>73.91</b>
<b>+ Car Rental (5.0 x S\$150.00/day) (S\$)</b>		750.00		
<b>Nett Liability (S\$)</b>		<b>7,384.00</b>		

### INSPECTION

Date of Assignment: 19/06/2020

Date Inspected: 23/06/2020 Inspected At: Dynamic Autowork Pte. Ltd (HQ)  
8 Kaki Bukit Ave 4, #08-09 Premier @  
Kaki Bukit  
Singapore 415875

Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,684.10 FL	*1,684.10 FL
2	4		*FRONT BUMPER SENSOR	Not Necessary	773.40 FL	*- FL
3	4		*FRONT BUMPER SENSOR HOLDER	Necessary	69.40 FL	*69.40 FL
4	1		*FRONT BUMPER LOWER GRILLE SIDE GARNISH RH	Cracked	229.15 FL	*229.15 FL
5	1		*FRONT BUMPER SIDE RETAINER	O/S Necessary	61.20 FL	*30.60 FL
6	1		*FRONT BUMPER SIDE AIR DUCT	Cracked	102.80 FL	*102.80 FL
7	1		*FRONT BUMPER BOTTOM COVER GARNISH	Torn	284.80 FL	*284.80 FL
8	1		*FRONT BUMPER SPONGE	Not Necessary	386.90 FL	*- FL
9	1		*FRONT FENDER RH	Repair	799.30 FL	*- FL
10	1		*FRONT FENDER COWLING RH	Not Necessary	303.65 FL	*- FL
11	1		*HEADLAMP RH (LED)	Cut	3,960.40 FL	*3,049.00 FL
12	1		*FRONT WATER COOLER RH	Dented	535.50 FL	*535.50 FL
13	1		*FRONT WATER COOLER COWLING	Torn	268.80 FL	*268.80 FL
14	1		*FRONT WATER COOLER PIPE	Not Necessary	259.05 FL	*- FL
15	1		*FRONT WHEEL SPORT RIM RH	Cut	1,528.83 FS	*1,000.00 FS
16	1		*FRONT ABS SENSOR	Not Necessary	379.20 FL	*- FL
17	1		*FRONT STEERING RACK AND PINION	Not Necessary	3,968.50 FL	*- FL
18	1		*FRONT DRIVESHAFT RH	Not Necessary	1,448.60 FL	*- FL
19	1		*FRONT LOWER ARM RH	Not Necessary	538.25 FL	*- FL
20	1		*FRONT KNUCKLE ARM C/W BEARING RH	Not Necessary	1,084.15 FL	*- FL
21	1		*FRONT WHEEL HUP RH	Not Necessary	512.80 FL	*- FL
22	1		*FRONT SHOCK ABSORBER RH	Not Necessary	565.25 FL	*- FL
23	1		*SET FRONT BUMPER CLIP	Necessary	120.00 FS	*50.00 FS
24	1		*SET FRONT BUMPER LOWER GRILLE SIDE GARNISH CLIP	Not Necessary	50.00 FS	*- FS
25	1		*SET FRONT BUMPER CENTER GRILLE CLIP	Not Necessary	80.00 FS	*- FS
26	1		*SET FRONT BUMPER BOTTOM COVER GARNISH CLIP	Necessary	80.00 FS	*30.00 FS
27	1		*SET FRONT FENDER COWLING CLIP	Not Necessary	80.00 FS	*- FS
28	1		*FRONT WHEEL TYRE RH	Not Necessary	850.00 FS	*- FS
29	1		*COOLANT	Not Necessary	80.00 FS	*- FS
30	1		*BRAKE OIL	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 21,134.03 7,334.15**  
**- List Item Discount on L Items 10.00/10.00% (\$\$) 1,821.52 625.42**

**Total Parts (\$\$) 19,312.51 6,708.73**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,400.00	400.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	500.00
3	REFOCUS HEADLAMP BEAM	New	80.00	0.00
4	REMOVE AND REFIX FRONT WATER COOLER	New	150.00	80.00
5	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	850.00	0.00
6	FOUR WHEEL ALIGNMENT	New	120.00	80.00
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	450.00	100.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,450.00</b>	<b>1,160.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >