

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20006465/R1QF3E2

Date: 24/09/2020

REFERENCE

| | | | |
|------------------------------|---|-----------------------------|-------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMPCSN30217319011 |
| Claimant Vehicle No : | SLN8886S | Insured Vehicle No : | SLK8546P |
| Date of Loss: | 06/05/2020 | Nature of Claim: | TP |
| | | Claim No: | SNM20D202172 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--|-------------|-------------------|
| Reg No: | SLN8886S | | |
| Make & Model: | MITSUBISHI OUTLANDER, 2.4 2.4 CVT AWD S/R FACE (A) | Engine No: | 4B12SY7663 |
| Reg. Date: | 30/05/2017 (Man. Year: 2017) | Chassis No: | JMYXTGF3WHZ001891 |
| Colour: | Red | Odometer: | 47434 km |
| Engine Capacity: | 2360 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 225/55 R18 | Rear Tyre Size: | 225/55 R18 |
| Front Left Side: | Michelin 6 mm | Rear Left Side: | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 1,951.00 | 1,176.00 | 775.00 | 39.72 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,260.00 | 1,300.00 | 1,960.00 | 60.12 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 5,211.00 | 2,476.00 | 2,735.00 | 52.49 |
| + GST 7.00/7.00% (S\$) | 364.77 | 173.32 | 191.45 | 52.49 |
| Nett Amount (S\$) | 5,575.77 | 2,649.32 | 2,926.45 | 52.49 |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 22/09/2020 | |
| Date Inspected: | 26/06/2020 Inspected At: | Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339 |
| Estimated Period of Repair: | 3.0 days | |

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S\$664.00 NETT)

REPAIR DETAILS

Reference

| | |
|----------------------------|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 23 Sep 2020) |
| Parts: M1-SUV | mitsubishi OUTLANDER 2.4 2.4 CVT AWD S/R FACE (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SLN8886S) |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|--------------------------|-----|----------|-------------------------------|-------------|-----------------|-----------------|
| 1 | 1 | | *PARKING SENSOR | * Check | 280.00 FS | *- FS |
| 2 | 1 | | *SUNDRIES | Necessary | 50.00 FS | *30.00 FS |
| 3 | 1 | | *REINFORCEMENT, RR BUMPER, RH | * Check | 79.00 FS | *- FS |
| 4 | 1 | | *REINFORCEMENT, RR BUMPER, LH | Serviceable | 79.00 FS | *- FS |
| 5 | 1 | | *BRKT, R/BMPR FACE SIDE, LH | Serviceable | 12.00 FS | *- FS |
| 6 | 1 | | *BRKT, R/BMPR FACE SIDE, RH | Necessary | 12.00 FS | *12.00 FS |
| 7 | 1 | | *FACE, RR BUMPER | Deformed | 807.00 FS | *807.00 FS |
| 8 | 1 | | *EXTENSION, RR BUMPER | Deformed | 232.00 FS | *232.00 FS |
| 9 | 1 | | *REFLECTOR, TAIL LAMP, RH | Broken | 95.00 FS | *95.00 FS |
| 10 | 1 | | *MOULDING, RR BUMPER, RH | * Check | 106.00 FS | *- FS |
| 11 | 1 | | *MOULDING, RR WHEEL ARCH, RH | * Check | 199.00 FS | *- FS |
| Total Parts (S\$) | | | | | 1,951.00 | 1,176.00 |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--|----------|--------------------------------|-----------------|
| Labour Items | | | | |
| 1 | RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER, REPAIR RH REAR FENDER | New | 1,650.00 | 550.00 |
| 2 | REMOVE AND INSTALL PARKING ASSIST | New | 100.00 | 80.00 |
| 3 | PAINT WORK SPRAY REAR BUMPER FACE, RH REAR FENDER AND AFFECTED PORTION | New | 1,260.00 | 420.00 |
| 4 | CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM | New | 50.00 | 50.00 |
| 5 | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | New | 200.00 | 200.00 |
| | | | Gross Labour Cost (S\$) | 1,300.00 |
| | | | 3,260.00 | 1,300.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >