

The insurer has given adjuster a maximum mandate of S\$0.00 to authorize directly on their behalf, but the adjuster has disabled direct offer mode.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20006465/R1QF3E2
Date: 16/10/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30217319011
Claimant Vehicle No:	SLN8886S	Insured Vehicle No:	SLK8546P
Date of Loss:	06/05/2020	Nature of Claim:	TP
			Claim No: SNM20D202172

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN8886S		
Make & Model:	MITSUBISHI OUTLANDER, 2.4 2.4 CVT AWD S/R FACE (A)	Engine No:	4B12SY7663
Reg. Date:	30/05/2017 (Man. Year: 2017)	Chassis No:	JMYXTGF3WHZ001891
Colour:	Red	Odometer:	47434 km
Engine Capacity:	2360 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,951.00	1,176.00	775.00	39.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,260.00	1,300.00	1,960.00	60.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,211.00	2,476.00	2,735.00	52.49
+ GST 7.00/7.00% (S\$)	364.77	173.32	191.45	52.49
Nett Amount (S\$)	5,575.77	2,649.32	2,926.45	52.49

INSPECTION

Date of Assignment:	22/09/2020		
Date Inspected:	26/06/2020	Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

10/16/2020

Merimen e-Claims

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$664.00 NETT)

REPAIR DETAILS**Reference**

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Oct 2020)
Parts:	M1-SUV	MITSUBISHI OUTLANDER 2.4 2.4 CVT AWD S/R FACE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN8886S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARKING SENSOR	Not Necessary	280.00 FS	*- FS
2	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
3	1		*REINFORCEMENT, RR BUMPER, RH	Serviceable	79.00 FS	*- FS
4	1		*REINFORCEMENT, RR BUMPER, LH	Serviceable	79.00 FS	*- FS
5	1		*BRKT, R/BMPR FACE SIDE, LH	Serviceable	12.00 FS	*- FS
6	1		*BRKT, R/BMPR FACE SIDE, RH	Necessary	12.00 FS	*12.00 FS
7	1		*FACE, RR BUMPER	Deformed	807.00 FS	*807.00 FS
8	1		*EXTENSION, RR BUMPER	Deformed	232.00 FS	*232.00 FS
9	1		*REFLECTOR, TAIL LAMP, RH	Broken	95.00 FS	*95.00 FS
10	1		*MOULDING, RR BUMPER, RH	Serviceable	106.00 FS	*- FS
11	1		*MOULDING, RR WHEEL ARCH, RH	Serviceable	199.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)**1,951.00****1,176.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER, REPAIR RH REAR FENDER	New	1,650.00	550.00
2	REMOVE AND INSTALL PARKING ASSIST	New	100.00	80.00
3	PAINT WORK SPRAY REAR BUMPER FACE, RH REAR FENDER AND AFFECTED PORTION	New	1,260.00	420.00
4	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	50.00	50.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	200.00	200.00
Gross Labour Cost (S\$)			3,260.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >