

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20006470/AEA3Q2**Date:** 09/05/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MPC0000704_01
Claimant Vehicle No :	SMS5431C	Insured Vehicle No :	SLQ7732T
Date of Loss:	28/03/2020	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS5431C	Engine No:	PY30981367
Make & Model:	MAZDA CX-9, 2.5 TURBO 2WD (A)	Chassis No:	JM6TC2WLAK0319746
Reg. Date:	28/02/2020 (Man. Year: 2019)	Odometer:	4284 km
Colour:	White		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/50 R20	Rear Tyre Size:	255/50 R20
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,996.50	1,617.60	1,378.90	46.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,760.00	1,650.00	2,110.00	56.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,756.50	3,267.60	3,488.90	51.64
+ GST 7.00/7.00% (S\$)	472.96	228.73	244.23	51.64
Nett Amount (S\$)	7,229.46	3,496.33	3,733.13	51.64
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	19/06/2020		
Date Inspected:	23/06/2020	Inspected At:	Trans Eurokars Pte Ltd (Ubi) 5 Ubi Close Singapore 408605
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 May 2022)

Parts: M1-SUV MAZDA CX-9 2.5 TURBO 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMS5431C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,359.50 F	*1,359.50 F
2	1		*BRACKET CENTER	Not Necessary	5.40 F	*- F
3	1		*STAY ,REAR BUMPER	Not Necessary	21.00 F	*- F
4	1		*CROME CENTER,REAR BUMPER	Not Necessary	241.00 F	*- F
5	1		*COVER UNDER ,REAR BUMPER	Not Necessary	66.60 F	*- F
6	1		*REAR REINFORCEMENT	Not Necessary	553.90 F	*- F
7	2		*RETAINER CENTER ,SENSOR	Necessary	31.00 F	*31.00 F
8	2		*SENSOR CENTER ,ULTRASONIC	Not Necessary	401.00 F	*- F
9	5		*PAD PROTECTOR ,SENSOR	Necessary	39.00 F	*39.00 F
10	16		*FASTENER ,REAR BUMPER	Necessary	48.00 F	*48.00 F
11	6		*GROMMET ,REAR BUMPER	Necessary	16.20 F	*16.20 F
12	6		*RIVET ,REAR BUMPER	Necessary	45.60 F	*45.60 F
13	9		*CLIPS ,REAR BUMPER	Necessary	26.10 F	*26.10 F
14	2		*SEAL RUBBER ,REAR BUMPER	Necessary	27.40 F	*27.40 F
15	4		*CLIP ,REAR BUMPER	Necessary	14.80 F	*14.80 F
16	1		*SUNRIES	Necessary	100.00 FS	*10.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **2,996.50** **1,617.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT ,REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,320.00	660.00
2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT	New	1,260.00	630.00
3	TO TRANSFER REVERSE SENSORS	New	330.00	180.00
4	TO CARRY OUT BODY CAVITY PRESERVATION	New	250.00	0.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	0.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
Gross Labour Cost (\$)			3,760.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >