



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2103035

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 29/04/2021  
Reference CC6/CTI20006472/Kpa3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. GBA 4105B  
Insured Veh. GBG 5111U  
Claim No. SNM20D202174  
Policy No. DMCVSN1756431902  
Accident Date 17/06/2020  
Inspection Date 22/07/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20006472/Kpa3q2	
			Date: 29/04/2021	
			Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBG 5111U	Veh. Inspected	GBA 4105B	
Policy No.	DMCVSN1756431902	Coverage (\$)	0.00	
Claim No.	SNM20D202174	Excess (\$)	0.00	
Assign From		Assign Date	22/07/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JTFHT02P600004498	Colour	YELLOW	
Odometer	333175 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	BRIDGESTONE	8 mm	
L/H Front Tyre	195 R15X8	BRIDGESTONE	8 mm	
R/H Rear Tyre	195 R15X8	BRIDGESTONE	8 mm	
L/H Rear Tyre	195 R15X8	BRIDGESTONE	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	17/06/2020	Inspection Date	22/07/2020	
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 4105B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DENTED/CRACKED	568.10	496.30
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	296.80	-
2	FRONT BUMPER RETAINER @\$84.00	SERVICEABLE	168.00	-
10	FRONT BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	FRONT GRILLE	CRACKED	843.00	624.70
2	HEDA LAMPS @\$897.40	N/S MTG CRACKED/O/S SERVICEABLE	1,794.80	799.50
1	BONNET	BENT	967.44	757.00
1	BONNET LOCK	TO REPAIR SEE LABOUR	89.00	-
1	BONNET EMBLEM	NECESSARY	59.00	59.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	324.00	-
1	AIR-CON CONDENSER	PUNCTURE	1,430.00	1,430.00
	LESS 25% DISCOUNT		-1,647.53	-1,054.13
			4,942.61	3,162.37
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	40.00	-
1	DHL LOGO (SN)	NECESSARY	300.00	100.00
			340.00	100.00
	<b><u>LABOUR</u></b>			
	TO PUTTY & SPRAY PAINT.		480.00	400.00
	TO CHECK FRONT WIRING & FOCUS HEAD LIGHTS.		30.00	20.00
	TO REPLACE AIRCON CONDENSER VACUUM AND REFILL GAS.		80.00	80.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT,BONNET LOCK AND FRONT SUPPORT PANEL.		600.00	400.00
			1,190.00	900.00
	<b>GRAND TOTAL</b>		<b>6,472.61</b>	<b>4,162.37</b>

Report Ref No. CC6/CTI20006472/Kpa3q2



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,300.00</b>
---	--	--	-----------------

Report Ref No. CC6/CTI20006472/Kpa3q2

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. GBA 4105B

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBA 4105B

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. GBA 4105B

### RE-INSPECTION

