

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: *SDZ8U*

Yr Regn:

Type: *M/Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Rear

R/Bal.

L/Bal.

D.O.I.

Des. of Damages: *Frt* / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*net 4 113642**102 30-4-2029 27A 31358**1000 6.0A**28/7/20 4/5 @ 16.500 confirmed with Alan*

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

4th Jan

Not Authorised
4 days 1/5 @ 16500 /
the photo after repair
S.NETT 27/6/20

VEHICLE No: SDZ 8U

1PC FRONT BUMPER 9205.84
2PCS FRONT BUMPER PDC SENSORS @\$450.00 265.00
1PC FRONT BUMPER FOG LAMP COVER N/S 180.00
1PC FRONT BUMPER CHROME MOULDING N/S 115.00
1PC FRONT BUMPER REINFORCEMENT
1PC FRONT BUMPER SIDE HOLDER N/S
1PC FRONT BUMPER SPONGE
1PC HEADLAMP N/S 8300.00
1PC HEADLAMP RIM N/S 280.00
1PC FRONT OIL COOLER N/S 2530.00
1PC FRONT FENDER N/S
1PC FRONT GRILLE
1PC FRONT SPORT RIM N/S

dis/cro \$18,500.00 ✓
shorted \$900.00 1PC
n/s \$680.00 ✓
rec/scr \$320.00 ✓
11 \$2,200.00 X
11 \$299.00 X
11 \$850.00 X
c/a \$9,800.00 ✓
c/re \$665.00 ✓
best/pur \$3,900.00 ✓
R \$12,000.00 X
c/a n/c \$10,800.00 X
11 \$6,500.00 X
\$67,414.00

(10%)

TO CHECK WIRING
TO DISMANTLE & REPLACED FRONT PDC SENSOR
TO SPRAY RUST PROOFING
TO DISMANTLE & REPLACED FRONT OIL COOLER
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING
TO REPROGRAMME & RESET SYSTEM

\$50.00 20
\$80.00 50
11 \$50.00 X
\$120.00 60
\$1,000.00 400
\$800.00 450
\$300.00 80

TOTAL \$69,824.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

2-21895.84
102
19706.28
1060.00
20766.28
(661)