

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/III20006494/UPA3Q2

**Date:** 30/10/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SML2659U	<b>Insured Vehicle No :</b>	SHD4594K
Date of Loss: 21/06/2020	Nature of Claim: TP	Claim No: MCT20060207

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML2659U	Engine No:	L13B14101267
Make & Model:	HONDA JAZZ, 1.3 (A)	Chassis No:	JHMGK3850KS214492
Reg. Date:	13/05/2019 (Man. Year: 2019)	Odometer:	13472 km
Colour:	White		
Engine Capacity:	1318 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	175/65 R15	Rear Tyre Size:	175/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,383.80	4,045.28	6,338.52	61.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	2,340.00	1,260.00	35.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>13,983.80</b>	<b>6,385.28</b>	<b>7,598.52</b>	<b>54.34</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,100.00</b>		
<b>Nett Amount (\$\$)</b>	<b>13,983.80</b>	<b>5,100.00</b>	<b>8,883.80</b>	<b>63.53</b>
<b>+ Loss of Use (6.0 x S\$60.00/day) (\$\$)</b>		360.00		
<b>Nett Liability (\$\$)</b>		<b>5,460.00</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>5,400.00</b>		

### INSPECTION

Date of Assignment:	22/06/2020	
Date Inspected:	22/06/2020 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	5.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Aug 2020)
<b>Parts:</b>	144	HONDA JAZZ 1.3 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SML2659U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	68.10 F	*68.10 FL
2	1		*TAILGATE	Badly Dented	845.20 F	*749.60 FL
3	1		*TAILGATE JAZZ EMBLEM	Necessary	45.00 F	*45.00 FL
4	1		*TAILGATE INNER LOCK	Twisted / Shorted	209.60 F	*197.40 FL
5	1		*TAILGATE INNER TRIM	Torn	388.20 F	*241.20 FL
6	1		*TAILGATE WEATHERSTRIP	Twisted	166.80 F	*145.60 FL
7	1		*REAR BUMPER	Distorted	645.50 F	*492.70 FL
8	2		*REAR BUMPER SIDE RETAINERS	Bird Droppings	61.00 F	*61.00 FL
9	1		*REAR BUMPER CENTRE BLACK GARNISH	Bent / Cracked	115.00 F	*115.00 FL
10	1		*REAR BUMPER BLACK O/S SIDE GARNISH	Cracked	65.00 F	*65.00 FL
11	1		*SET REAR BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
12	1		*REAR END PANEL	Badly Dented	366.00 F	*328.60 FL
13	1		*REAR END PANEL TOP GARNISH	Twisted	198.00 F	*198.00 FL
14	1		*REAR FLOOR PANEL	Repair	995.00 F	*- FL
15	1		*REAR FLOOR PANEL TOP BOARD	Serviceable	355.00 F	*- FL
16	1		*REAR FLOOR PANEL TOOLS SPONGE	Torn	685.00 F	*465.20 FL
17	2		*TAILLAMPS	Cracked	900.40 F	*576.40 FL
18	2		*REAR FENDERS	Repair	1,700.00 F	*- FL
19	1		*REAR FENDER INNER TRIM BOARDS	O/S Torn	798.00 F	*285.30 FL
20	1		*REAR EXHAUST	Repair	652.00 F	*- FL
21	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	380.00 FS	*200.00 FS
22	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
23	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
24	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	200.00 FS	*150.00 FS
25	1		*SET REAR REVERSE CAMERA	Shorted	380.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>10,383.80</b>	<b>4,859.10</b>
<b>- List Item Discount on L Items 0.00/20.00% (S\$)</b>	0.00	813.82
<b>Total Parts (S\$)</b>	<b>10,383.80</b>	<b>4,045.28</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
4	TO TRANSFER TAILGATE COMPONENTS	New	100.00	60.00
5	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
6	TO SPRAY RUST PROOFING	New	100.00	60.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	850.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,100.00
<b>Gross Labour Cost (S\$)</b>			<b>3,600.00</b>	<b>2,340.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**