Qualified Loss Adjusters And Motor Appraisers Correspondence Address: 1 Simei St.3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0390320

Date of Report

: 27/04/2020

To: M/s. Gim Pheng Renovation

Date of Assignment

: 25/03/2020

C/o. Blk 5 Defu Lane 10

Report requested by

: M/s. Gim Pheng Renovation

Date of Accident

: 24/03/2020

#01-580

Singapore 539186

Date of Inspection

: 25/03/2020

Claim No.

: Third Party Claim

Policy No.

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.

: SGJ8339K

Engine Capacity (cc): 1794cc

Make & Model

: Toyota Wish

Mileage (km)

: 675777km

Date of Registration

: 21/07/2006

Chassis / Frame No.

: ZNE100316041

Colour

; Met. Black

Engine No.

: 1ZZ2630409

TYRE CONDITION

Front LH

: 5 mm

Front RH

: 5 mm

Make

: Firenza

Make

: Firenza

Rear LH

: 5 mm

Rear RH

: 5 mm

Make

: Firenza

Make

: Firenza

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork

: Good

Paintwork

: Good

Handbrake

: Serviceable

Footbrake

: Serviceable

Steering

: Serviceable

Apparent Engine Modification

: Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location

M/s. Y S Automobile Service

Blk 5, Defu Lane 10, #01-580, Singapore 539186

ASSESSMENT

Repairer's Estimate

\$ 24,286.23

Revised Amount Less Excess

\$ \$:

Recommended Reserve

21,628.63

: \$ 17,300.00 (Lump Sum)

Estimated Normal Period of Repairs

: 16 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addresses (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may protected by legal privileged. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third pany. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited. Page 1 of 5 Qualified Loss Adjusters And Motor Appraisers Correspondence Address: 1 Simei St.3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No : SGJ8339K

Report No.: PAS/TP/0390320

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Y S Automobile Service, Blk 5, Defu Lane 10, #01-580, Singapore 539186.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the RHF portion. (The RHF roadwheel was also affected)

DAMAGES

The bonnet, front support panel assy, RHF wheel house, front apron panels, front chassis members, front bumper, front fenders, both front doors, radiator assy, a/c condenser, ABS pump, alternator assy, a/c compressor assy, RHF rim, RHF knuckle arm, RHF lower arm, RHF shock absorber, front windscreen, headlamps, front grille, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$21,628.63.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$17,300.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How

Automobile Appraiser

MSAAA

Licensed Appraiser



Vehicle No : SGJ8339K

Report No.: PAS/TP/0390320

APPRAISEMENT SCHEDULE

:							airer's	Ö	ur
S/No.	Qty	Parts Descriptions	Condition	4			mate (S\$)	Assessment (S\$)	
						_			
1	-	Bonnet	Dented/Buckled			\$	786.00	\$	786.00
2		Bonnet chrome moulding	Broken			\$	232.00	\$	232.00
3	1 pc	Bonnet lock	Bent			\$	89.50	\$	89.50
4	2 pcs	Bonnet hinge R/L	Bent	\$	58.40	\$	116.80	\$	116.80
5	2 pcs	Headlamp R/L	Broken/Cracked	\$	872.90	\$	1,745.80	\$	1,745.80
6	1 pc	Frt grille	Broken			\$	117.20	\$	117.20
7	1 pc	Frt bumper	Dented			\$	697.40	\$	697.40
8	8 pcs	Frt bumper clip	Necessary	\$	3.50	\$	28.00	\$	28.00
9	l pc	Frt bumper sponge	Dented/Broken			\$	109.80	\$	109.80
10	1 pc	Frt bumper reinforcement	Dented			\$	292.70	\$	292.70
11	•	Frt bumper retainer R/L	Broken/Necessary		55.20	\$	110.40	\$	110.40
12		Frt fender R/L	Dented/Distorted	\$	733.00	\$	1,466.00	\$	1,466.00
13		Frt apron panel RH	Dented			\$	481.60	\$	481.60
14	2 pcs	Frt fender cowling R/L	Torn/Deformed	\$	168.10	\$	336.20	\$	336.20
15	1 pc	Frt support panel	Dented			\$	888.20	\$	888.20
16	l pc	Frt brace panel	Bent			\$	88.90	\$	88.90
17	l pc	Radiator assy	Dented/Bent			\$	1,806.10	\$	1,806.10
18	1 pc	Radiator fan blade	Refit			\$	146.70	\$	-
19	1 pc	Radiator fan motor	Refit			\$	461.40	\$	-
20	1 pc	Radiator fan cowling	Broken			\$	216.50	\$	216.50
21	l pc	A/c condenser	Dented/Bent			\$	1,591.60	\$	1,591.60
22	1 pc	A/c discharge hose	Refit			\$	284.80	\$	te-
23	1 pc	A/c suction pipe	Refit			\$	242.90	\$	-
24	l pc	A/c liquid pipe	Dented/Bent			\$	148.30	\$	148.30
25	l pc	Washer tank	Dented/Cracked			\$	149.70	\$	149.70
26	l pc	Alternator assy	Dented/Broken			\$	1,336.60	\$	1,336.60
27	1 pc	A/c compressor assy	Dented/Damaged			\$	1,678.00	\$	1,678.00
28	1 pc	A/c compressor belt	Torn			\$	229.10	\$	229.10
29	l pc	Brake actuator (ABS) assy	Dented/Damaged			\$	3,905.50	\$	3,905.50
30	1 pc	Frt engine mounting	Torn/Bent			\$	186.60	\$	186.60
31	1 pc	Frt center crossmember	Bent			\$	404.20	\$	404.20
32	1 pc	Frt driveshaft RH	Serviceable			\$	1,301.00	\$	-
33			Warped			\$	216.50	\$	216.50
34		Frt wheel bearing RH	Distorted/Necessa	ary		\$	132.00	\$	132.00
35		Frt knuckle arm RH	Bent			\$	637.30	\$	637.30
36		Frt lower ball joint RH	Bent			\$	198.00	\$	198.00
37	1 pc	Frt lower arm RH	Bent			\$	631.90	\$	631.90
38	1 pc	Frt shock absorber RH	Bent/Jammed			\$	417.90	\$	417.90
39	1 pc		Cracked			\$	1,277.60	\$	1,277.60
40	1 pc		Necessary			\$	22.00	\$	22.00
41	l pc		Necessary			\$	39.60	\$	39.60
42		Frt apron panel LH	Dented/Repair						0. 7, 8 & 9)
43	2 pc	s Frt chassis member R/L	Dented/Repair						5. 7, 8 & 9)
44	2 pc	s Frt door R/L	Dented/Repair				(Refe	r labour no	0. 7, 8 & 9)
							25,248.30		22,811.50
				Less	Discount: 2	25% <u>\$</u>			5,702.88
			L	ist Parts :	Sub-Total:	\$	18,936.23	\$	17,108.63



PROMINENT APPRAISER SERVICES PTE LTD
Qualified Loss Adjusters And Motor Appraisers
Correspondence Address: 1 Simei St.3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No: SGJ8339K				Report No.: PAS/TP/0390320				
S/No.	Qty	Parts Descriptions	Condition			airer's mate (S\$)	Our Assessment (S\$)	
					_\$	18,936.23	\$ 1	17,108.63
1	l pc	Frt windscreen sealant	Necessary	S/N	\$	50.00	\$	40.00
2	1 pc	Frt alloy rim RH	Dented/Defaced	S/N	\$	250.00	\$	250.00
3	1 pc	Frt tyre RH (Depreciate 30%)	Cut/Bulged	S/N	\$	300.00	\$	210.00
			Special Nett Sub-Total:			600.00	\$	500.00
				Parts Total :	<u> </u>	19,536.23	<u> </u>	17,608.63



PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SGJ8339K			Report No.: PAS/TP/0390320				
S/No.	Labour Descriptions	Repairer's Estimate (S\$)		Our Assessment (S\$)			
1	Towing.	\$	150.00	\$	120.00		
2	To check electrical system, repair wire harness and focus headlamp.	\$	150.00	\$	120.00		
3	To remove, replace and reinstall a/c condenser & a/c pipings. (Include vacuum & recharge a/c gas)	\$	120.00	\$	120.00		
4	To remove, replace and reinstall radiator & cooling system. (Include pressure test cooling system)	\$	100.00	\$	80.00		
5	To remove, check and replace RHF undercarriage parts.	\$	220.00	\$	180.00		
6	To conduct wheel alignment.	\$	60.00	\$	60.00		
7	To conduct chassis alignments.	\$	350.00	\$	300.00		
8	To straighten, repair, realign on affected area and replace damaged parts.	\$	1,800.00	\$	1,540.00		
9	To spray painting, blending on affected and adjacent area.	\$	1,800.00	\$	1,500.00		
	Labour Total:	\$	4,750.00	\$	4,020.00		
	Total (Parts & Labour) :	\$	24,286.23		21,628.63		

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$

Under normal circumstances, the repairs should be completed within a reasonable period

16 Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)

122 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.