Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20006498/QGS3Q2

Date: 12/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100424953

Claimant Vehicle No: SHB739Y Insured Vehicle No: SKU7687G

Date of Loss: 18/06/2020 Nature of Claim: TP Claim No: 1227696794SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB739Y

Make & Model: TOYOTA PRIUS, 1.8 (A) Engine No: 2ZR1452094

Reg. Date: 10/11/2014 (Man. Year: 2014) Chassis No: JTDKN36U405752681

Colour: Maroon Odometer: 428541 km

Engine Capacity: 1798 cc Market Value/New Car

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|------------|------------|--------|
| Parts | 11,924.30 | 1,588.42 | 10,335.88 | 86.68 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,968.00 | 1,710.00 | 3,258.00 | 65.58 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 16,892.30 | 3,298.42 | 13,593.88 | 80.47 |
| Approved Total (Overridden) (S\$) | | 3,000.00 | | |
| Nett Amount (S\$) | 16,892.30 | 3,000.00 | 13,892.30 | 82.24 |
| + Loss of Use (7.0 x S\$5 | 50.00/day) (S\$) | 350.00 | | |
| + Car Rental (7.0 x S\$104.33/day) (S\$) | | 730.31 | | |
| + Doc/So | earch Fee (S\$) | 7.00 | | |
| Net | t Liability (S\$) | 4,087.31 | | |
| Global Sum S | ettlement (S\$) | 4,000.00 | | |

INSPECTION

Date of Assignment: 19/06/2020

Date Inspected: 19/06/2020 Inspected At: SMRT Automotive Services Pte Ltd

(Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 5.0 days

Adjuster Report Page 2 of 5

Adjuster: OI SUN PIN Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Recommended Parts

| NO. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|----------------|-----|----------|--|---------------|------------|-----------|
| 1 | 1 | | *BUMPER REAR (DISC 25%) | Crushed | 458.60 F | *343.95 F |
| 2 | 1 | | *BUMPER CLIPS (DISC 25%) | Necessary | 16.10 F | *12.08 F |
| | | | 10pcs | | | |
| 3 | 1 | | *BUMPER SIDE RETAINER RR/RH (DISC 25%) | Broken | 94.80 F | *71.10 F |
| 4 | 1 | | *EMBLEM REAR (DISC 25%) | Necessary | 60.30 F | *45.23 F |
| 5 | 1 | | *NAME PLATE (PRIUS) (DISC 25%) | Necessary | 60.80 F | *45.60 F |
| 6 | 1 | | *NAME PLATE (TOYOTA) (DISC 25%) | Necessary | 51.90 F | *38.93 F |
| 7 | 1 | | *NAME PLATE (HYBRID) (DISC 25%) | Necessary | 51.90 F | *38.93 F |
| 8 | 1 | | *TAIL LAMP RH (DISC 10%) | Crushed | 557.80 F | *502.02 F |
| 9 | 2 | | *PIXEL STICKER (SN) | Necessary | 120.00 F | *120.00 F |
| 10 | 1 | | *SMRT LOGO (SN) | Necessary | 7.80 F | *7.80 F |
| 11 | 1 | | *STICKER DECAL 6555 8888 (SN) | Necessary | 21.60 F | *21.60 F |
| 12 | 1 | | *SMRT LOGO (SN) | Necessary | 7.80 F | *7.80 F |
| 13 | 1 | | *STICKER DECAL 6555 8888 (SN) | Necessary | 21.60 F | *21.60 F |
| 14 | 1 | | *BUMPER REINFORCEMENT REAR | Serviceable | 205.70 F | *- F |
| 15 | 1 | | *ARM SUB-ASSY RR BUMPER LH | Serviceable | 139.60 F | *- F |
| 16 | 1 | | *ARM SUB-ASSY, RR BUMPER RH | Serviceable | 139.60 F | *- F |
| 17 | 1 | | *SENSOR REVERSE | Serviceable | 180.00 F | *- F |
| 18 | 1 | | *BUMPER LIP COVER RR/RH | Serviceable | 118.10 F | *-F |
| 19 | 1 | | *BUMPER LIP REAR | Serviceable | 228.90 F | *- F |
| 20 | 1 | | *BUMPER SEAL, RR RH | Serviceable | 65.70 F | *-F |
| 21 | 1 | | *BUMPER SIDE RETAINER RR/LH | Serviceable | 94.80 F | *-F |
| 22 | 1 | | *UNDER COVER SUBASSY, RR FLOOR | Serviceable | 514.50 F | -, *-F |
| 23 | 1 | | *EXHAUST HEAT SHIELD, REAR | Serviceable | | *-F |
| 23 24 | | | *EXHAUST TAIL PIPE | Serviceable | 107.40 F | -г *-F |
| | 1 | | | | 656.20 F | -г *-F |
| 25 | 2 | | *SUPPORT, EXHAUST REAR | Serviceable | 67.20 F | |
| 26 | 1 | | *TAILGATE DOOR LOCK | Serviceable | 444.10 F | *-F |
| 27 | 1 | | *TAILGATE LOCK, COVER | Serviceable | 15.70 F | *-F |
| 28 | 1 | | *TAILGATE DOOR WEATHER STRIP | Serviceable | 353.40 F | *-F |
| 29 | 1 | | *STRIKER, BACK DOOR | Serviceable | 48.90 F | *- F |
| 30 | 1 | | *TAILGATE OUTSIDE GARNISH | Serviceable | 504.90 F | *- F |
| 31 | 1 | | *END PANEL | Serviceable | 602.10 F | *- F |
| 32 | 1 | | *SEALANT SIKAFLEX | Serviceable | 37.00 F | *- F |
| 33 | 1 | | *BOARD ASSY, RR RH | Serviceable | 379.20 F | *- F |
| 34 | 1 | | *SPACER, RR FLOOR | Serviceable | 130.60 F | *- F |
| 35 | 1 | | *PANEL ASSY, DECK RH | Serviceable | 307.00 F | *- F |
| 36 | 1 | | *BATTERY | Serviceable | 278.00 F | *- F |
| 37 | 1 | | *BATTERY CLAMP | Serviceable | 16.10 F | *- F |
| 38 | 1 | | *BATTERY TRAY | Serviceable | 42.80 F | *- F |
| 39 | 1 | | *TAIL LAMP BRACKET, RH | Serviceable | 30.70 F | *- F |
| 40 | 1 | | *THROUGH, BACK DOOR | Serviceable | 110.90 F | *- F |
| 41 | 1 | | *FENDER LINER RR/RH | Serviceable | 141.30 F | *- F |
| 42 | 1 | | *DUCT ASSY, QUARTER | Serviceable | 70.40 F | *- F |
| 43 | 1 | | *QUARTER GLASS RR/RH | Serviceable | 846.50 F | *- F |
| 44 | 1 | | *SEALANT W/SCREEN | Serviceable | 37.00 F | *-F |
| 45 | 1 | | *FLOOR PANEL RR/RH | Serviceable | 209.90 F | *- F |
| 4 5 | 1 | | *TAILGATE ASY | Repair | 1,007.90 F | *-F |
| 47 | 1 | | *SPOILER REAR | | | *-F |
| | | | | Repair | 953.70 F | -г *-F |
| 48 | 1 | | *FENDER RR/RH | Repair | 766.80 F | |
| 49 50 | 1 | | *SOLAR FILM (SN) | Not Necessary | 125.00 F | *-F |
| 50 | 1 | | *BUMPER REINFORCEMENT REAR (DISC 25%) | Bent | 205.70 F | *154.28 F |
| 51 | 1 | | *ARM SUB-ASSY, RR BUMPER RH (DISC 25%) | Bent | 139.60 F | *104.70 F |
| 52 | 1 | | *DUCT ASSY, QUARTER | Crushed | 70.40 F | *52.80 F |

Adjuster Report Page 4 of 5

| No. Qty Part No. Particulars | Condition | Repairer's | Amount | |
|---|-------------------|------------|----------|--|
| F=Franchise part. | Total Parts (S\$) | 11,924.30 | 1,588.42 | |
| Report was unsubmitted during this print-out. | | | | |

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|--|----------|------------|----------|
| Lab | our Items | | | |
| 1 | PANEL BEATING & BODYWORK. | New | 1,314.00 | 700.00 |
| 2 | SPRAY PAINT. | New | 2,394.00 | 900.00 |
| 3 | TO CHECK WIRING SYSTEM FUNCTION. | New | 80.00 | 20.00 |
| 4 | TO APPLY RUST-PROOFING ON AFFECTED AREA. | New | 100.00 | 30.00 |
| 5 | TO REMOVE & REFIT EXHAUST. | New | 120.00 | 0.00 |
| 6 | TO TEST AND REFIX REVERSE SENSOR SYSTEM. | New | 120.00 | 30.00 |
| 7 | TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR. | New | 120.00 | 30.00 |
| 8 | TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE. | New | 120.00 | 0.00 |
| 9 | TO REMOVE & REFIT REAR QUARTER GLASS RH. | New | 120.00 | 0.00 |
| 10 | TO REMOVE / REFIT SEAT. | New | 120.00 | 0.00 |
| 11 | TO REMOVE AND REFIT WIRE HARDESS. | New | 200.00 | 0.00 |
| 12 | TO REPLACE SUNDRY PARTS. | New | 100.00 | 0.00 |
| 13 | TO WASH AND VACUUM. | New | 60.00 | 0.00 |
| | Gross Labour Cost (S\$) | | 4,968.00 | 1,710.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >