

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jun 2020 10:19		22 Jun 2020 11:38 Edit Adj Rpt	S\$2,000.00 Edit Estimates	S\$2,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	TEE KENG SENG , ID: S8673920H, Tel: +6585716692, Email: JACKTEEKS@GMAIL.COM								
Main Claimant:	NG YEOW HIAN , ID: S8111748I								
Vehicle Reg. No.:	SJL6009E	Date of Loss:	19/06/2020 06:00 - :59 [53 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/20-000578	Policy/Cover Note No.:	MSD/VMS/20-408927-CA (TP, Fire & Theft) Coverage: 17/02/2020 - 16/02/2021						
Vehicle Reg. No. (Insured):	FBG64E	Policy No. (Claimant):	DMPG19012049						
		Excess:							
Repairer:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building, 659578 Bukit Batok - Tel: 6316 1131								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Claimant's Insurer:	ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 22/07/2020]								
Driver/Custodian (Insured):	TEE KENG SENG (33 / Male) , NRIC: S8673920H, Tel: +6585716692 Email: JACKTEEKS@GMAIL.COM								
Adj Asg. Remarks:	on WP. Liab: clear. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: 6316 1131.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJL6009E (MSC/V/20-000578)
 [FBG64E]
 TP
 NG YEOW HIAN
 Jun 19 2020 6:00AM
 [TEE KENG SENG]
 Woon Meng Motor Pte Ltd

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View	View in Browser <input type="checkbox"/>
Assessment Reports			1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/07/20 09:03	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
2	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
3	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
4	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
5	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
6	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
7	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
8	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
9	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
10	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
11	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
12	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
13	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
14	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
15	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
16	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
17	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
18	13/07/20 19:22	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
19	13/07/20 19:22	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
20	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
21	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
22	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
23	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
24	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
25	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
26	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
27	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
28	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
29	13/07/20 19:22	General View	Load JPG	<input checked="" type="checkbox"/>
30	13/07/20 19:22	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
31	13/07/20 19:22	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/06/20 10:29	TP Accident Report	Load PDF	<input type="checkbox"/>
2	22/06/20 10:37	Agree on SJE	Load PDF	<input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	22/06/20 11:37	Email - Outsource Instruction	Load PDF	<input type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			View View in Browser ▼
			1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail Print
1	19/06/20 17:45	Accident Statement	i Load HTM
Photos/Images			3 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail Print
1	19/06/20 17:36	Accident Photo	i Load JPG <input checked="" type="checkbox"/>
2	19/06/20 17:36	Accident Photo	i Load JPG <input checked="" type="checkbox"/>
3	19/06/20 17:36	Accident Photo	i Load JPG <input checked="" type="checkbox"/>
4	19/06/20 17:36	Accident Photo	i Load JPG <input checked="" type="checkbox"/>
5	19/06/20 17:36	Accident Photo	i Load JPG <input checked="" type="checkbox"/>
6	19/06/20 17:36	Accident Photo	i Load JPG <input checked="" type="checkbox"/>
7	19/06/20 17:36	Accident Photo	i Load JPG <input checked="" type="checkbox"/>
8	19/06/20 17:36	Accident Photo	i Load JPG <input checked="" type="checkbox"/>
9	19/06/20 17:36	Accident Photo	i Load JPG <input checked="" type="checkbox"/>
10	19/06/20 17:36	Accident Photo	i Load JPG <input checked="" type="checkbox"/>
11	19/06/20 17:36	Accident Photo	i Load JPG <input checked="" type="checkbox"/>
12	19/06/20 17:36	Accident Photo	i Load JPG <input checked="" type="checkbox"/>
13	19/06/20 17:42	Accident Photo	i Load JPG <input checked="" type="checkbox"/>
14	19/06/20 17:42	Accident Photo	i Load JPG <input checked="" type="checkbox"/>
15	19/06/20 17:42	Accident Photo	i Load JPG <input checked="" type="checkbox"/>
16	19/06/20 17:42	Accident Photo	i Load JPG <input checked="" type="checkbox"/>
17	19/06/20 17:42	Accident Photo	i Load JPG <input checked="" type="checkbox"/>
18	19/06/20 17:42	Accident Photo	i Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail Print
1	19/06/20 17:44	Sketch Plan	i Load JPG <input checked="" type="checkbox"/>
2	19/06/20 17:44	Sketch Plan #2	i Load JPG <input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG20006499/T1VF3S2**Date:** 17/07/2020REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/20-408927-CA
Claimant Vehicle No :	SJL6009E	Insured Vehicle No :	FBG64E
Date of Loss:	19/06/2020	Nature of Claim:	TP
		Claim No:	MSCV/20-000578

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL6009E	Engine No:	P520334476
Make & Model:	MAZDA 3, 1.5 HATCHBACK L SP.6EAT (A)	Chassis No:	JM6BM44A8G0326340
Reg. Date:	24/12/2015 (Man. Year: 2015)	Odometer:	71478 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,483.76	1,646.80	836.96	33.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,340.00	860.00	480.00	35.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,823.76	2,506.80	1,316.96	34.44
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	3,823.76	2,000.00	1,823.76	47.70
+ GST 7.00/7.00% (S\$)	267.66	140.00	127.66	47.69
Nett Amount (S\$)	4,091.42	2,140.00	1,951.42	47.70

INSPECTION

Date of Assignment:	22/06/2020	
Date Inspected:	26/06/2020 Inspected At:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23., #01-06 Midview Building Singapore 659578
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 17 Jul 2020)**Parts:** 144 MAZDA 3 1.5 HATCHBACK L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SJL6009E)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,118.40 FL	*1,118.40 FL
2	2		*REAR BUMPER RETAINER	Not Necessary	74.80 FL	*- FL
3	1		*REAR SENSOR RH	Distorted	203.60 FL	*203.60 FL
4	1		*REAR BUMPER LOWER GARNISH	Cut	58.80 FL	*58.80 FL
5	1		*REAR LAMP RH (OUTER)	Not Necessary	971.40 FL	*- FL
6	1		*REAR BOOTLID LAMP O/S	Cracked	465.90 FL	*465.90 FL
7	1		*MAZDA 3	Necessary	78.20 FL	*78.20 FL
8	1		*SKYACTIV	Necessary	66.80 FL	*66.80 FL
9	1		*EMBLEM	Necessary	66.80 FL	*66.80 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,104.70	2,058.50
- List Item Discount on L Items 20.00/20.00% (S\$)	620.94	411.70
Total Parts (S\$)	2,483.76	1,646.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REPAIR, REPLACE & INSTALL DAMAGED PARTS.	New	600.00	400.00
2	TO R&R LIGHT WIRING.	New	60.00	30.00
3	TO R&R SENSOR WIRING.	New	80.00	30.00
4	TO PUTTY & SPRAY PAINTING.	New	600.00	400.00
Gross Labour Cost (\$\$)			1,340.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >