

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006502/T1ES3Q2
Date: 10/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900024426
Claimant Vehicle No :	SHD3334B	Insured Vehicle No :	SMJ4654E
Date of Loss:	19/06/2020	Nature of Claim:	TP
		Claim No:	5493781393SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3334B	Engine No:	D4FDGU652171
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU092172
Reg. Date:	21/07/2016 (Man. Year: 2016)	Odometer:	52216 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,585.92	952.40	633.52	39.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	510.00	90.00	15.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,185.92	1,462.40	723.52	33.10
Approved Total (Overridden) (S\$)		1,150.00		

(S\$)	2,185.92	1,150.00	1,035.92	47.39
+ GST 7.00/7.00% (S\$)	153.01	80.50	72.51	47.39
Nett Amount (S\$)	2,338.93	1,230.50	1,108.43	47.39
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (S\$)		225.34		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,663.33		

INSPECTION

Date of Assignment: 22/06/2020

Date Inspected: 22/06/2020

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,106.00 FL	*1,106.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER SPONGE	Not Necessary	103.50 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	428.40 FL	*- FL
5	1		*REAR BUMPER UNDERCOVER	Not Necessary	228.00 FL	*- FL
6	1		*REAR BUMPER REFLECTOR -RH	Not Necessary	32.00 FL	*- FL
7	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
					Sub Total (\$\$)	1,969.90
					- List Item Discount on L Items 20.00/20.00% (\$\$)	383.98
					Total Parts (\$\$)	1,585.92

1,178.00

225.60

952.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	300.00	280.00
2	SPRAY PAINTING CHARGE	New	250.00	200.00
3	WIRING CHARGE	New	50.00	30.00
Gross Labour Cost (\$\$)			600.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >