



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 6315G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILGATE	DENTED	1,654.00	1,050.00
1	TAILGATE LOCK	SERVICEABLE	308.00	-
1	TAILGATE W/STRIP	SERVICEABLE	225.00	-
1	TAILGATE HANDLE	SERVICEABLE	103.40	-
1	TAILGATE EMBLEM LOGO	NECESSARY	36.30	36.30
1	TAILGATE EMBLEM COLT	NECESSARY	46.00	38.00
1	TAILGATE WINDSCREEN MOULDING	NECESSARY	134.45	66.00
1	TAILGATE INNER TRIM	CRACKED	458.00	245.00
1	REAR BUMPER	CRACKED	1,254.00	620.00
1	REAR BUMPER CLIP	NECESSARY	55.00	55.00
2	REAR BUMPER SIDE GUIDE	SERVICEABLE	28.80	-
2	REAR BUMPER BRACKET	SERVICEABLE	48.80	-
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,587.00	-
1	REAR CENTRE PANEL	BUCKLED	1,154.00	450.00
1	REAR END PANEL TOP GARNISH	SERVICEABLE	213.10	-
2	TAILLAMP	SERVICEABLE	1,415.00	-
1	EXHAUST PIPE MUFFLER	TO REPAIR SEE LABOUR	932.00	-
2	EXHAUST MOUNTING	SERVICEABLE	148.20	-
	LESS 10% DISCOUNT		-	-256.03
			9,801.05	2,304.27
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
1	REAR GLASS SEALANT (SN)	NECESSARY	180.00	40.00
1	NO PLATE REAR (SN)	SERVICEABLE	80.00	-
			540.00	40.00
<b><u>LABOUR</u></b>				
	CHECK ELECTRICAL WIRING SYSTEM.		50.00	30.00
	REMOVE AND REFIT CARPET AND UPHOLSTERY.		250.00	60.00
	REMOVE AND REFIT EXHAUST PIPE.	NOT NECESSARY	250.00	-

Report Ref No. CS1/LPC20006504/Gsf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	ANTI-RUST.		200.00	60.00
	REMOVE AND REFIT REAR WINDSCREEN GLASS.		280.00	100.00
	TRANSFER TAILGATE FITTING.		200.00	60.00
	TO PUTTY AND SPRAY PAINT CHARGES.		1,200.00	600.00
	REMOVE AND REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN AND REALIGN ETC. INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL AND EXHAUST PIPE MUFFLER.		1,200.00	600.00
			3,630.00	1,510.00
<b>GRAND TOTAL</b>			<b>13,971.05</b>	<b>3,854.27</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,854.27</b>

Report Ref No. CS1/LPC20006504/Gsf3e2

**MARKET VALUE: \$45,000.00**

**XING GUO QIANG**

**M.MATAI, AMSAE-A**

**Automotive Assessor**

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.