

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20006514/T1EA3Q2
Date: 20/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100284065
Claimant Vehicle No :	SHA9725H	Insured Vehicle No :	SKE1226C
Date of Loss:	20/06/2020	Nature of Claim:	TP
		Claim No:	8044180768SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA9725H		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEKU297750
Reg. Date:	10/07/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVKU164682
Colour:	Yellow	Odometer:	123902 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,369.58	2,360.58	9.00	0.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	810.00	610.00	200.00	24.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,179.58	2,970.58	209.00	6.57
+ GST 7.00/7.00% (S\$)	222.57	207.94	14.63	6.57

Nett Amount (S\$)	3,402.15	3,178.52	223.63	6.57
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (S\$)		125.19		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,411.20		

INSPECTION

Date of Assignment: 22/06/2020

Date Inspected: 22/06/2020

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -FR BUMPER	Deformed	418.30 FL	*418.30 FL
2	1		*LAMP ASSY -HEAD RH	Cut	1,993.64 FL	*1,993.64 FL
3	1		*BRACKET -FR BUMPER SIDE SU	Not Necessary	12.00 FL	*- FL
4	1		*LAMP ASSY -DAY RUNNING LIG	Cracked	642.50 FL	*642.50 FL
5	1		*MOULDING -FRONT BUMPER RH	Cut	93.00 FL	*93.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	3,159.44
					- List Item Discount on L Items 25.00/25.00% (\$\$)	789.86
					Total Parts (\$\$)	2,369.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	320.00
2	SPRAYPAINT CHARGE	New	300.00	200.00
3	CHECK ALL LIGHTING	New	50.00	30.00
4	TOWING FEE	New	60.00	60.00
Gross Labour Cost (\$\$)			810.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >