

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III20006521/UQF3E2

Date: 06/07/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SML1466R

Insured Vehicle No : SHB6373D

Date of Loss: 21/06/2020

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SML1466R

Make & Model: HONDA SHUTTLE, 1.5 G CVT (A)

Engine No: L15B6002624

Reg. Date: 07/05/2019 (Man. Year: 2019)

Chassis No: GK82002237

Colour: Grey

Odometer: 27500 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16

Rear Tyre Size: 205/50 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,946.44	4,341.80	6,604.64	60.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	1,300.00	1,240.00	48.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,486.44	5,641.80	7,844.64	58.17
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	13,486.44	4,500.00	8,986.44	66.63

INSPECTION

Date of Assignment: 22/06/2020

Date Inspected: 23/06/2020 Inspected At:

Automobile Hub Enterprise
1 KAKI BUKIT AVENUE 6
#02-11 AUTOBAY
SINGAPORE 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Jul 2020)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML1466R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	1,021.50 FL	*- FL
2	1		*FRONT BONNET LOCK	Not Necessary	186.90 FL	*- FL
3	1		*FRONT BUMPER	Distorted	1,260.50 FL	*862.90 FL
4	1		*FRONT BUMPER TOW COVER	Deformed	42.60 FL	*42.60 FL
5	1		*FRONT BUMPER LOWER GRILLE - CTR	Twisted / Torn	191.30 FL	*145.20 FL
6	1		*FRONT BUMPER FOG LAMP - RH	Cracked	415.20 FL	*392.20 FL
7	1		*FRONT BUMPER FOG LAMP COVER - RH	Torn	112.60 FL	*112.60 FL
8	1		*FRONT BUMPER SIDE GRILLE - RH	Torn	126.20 FL	*115.20 FL
9	1		*FRONT BUMPER REINFORCEMENT	Dented	445.60 FL	*420.80 FL
10	1		*FRONT BUMPER TOP BEAM	No such part	189.60 FL	*- FL
11	1		*FRONT BUMPER SIDE RETAINERS - L/R (2PCS)	Distorted / Bent (1Pc Only)	131.00 FL	*65.50 FL
12	1		*FRONT FENDER - RH	Repair	589.40 FL	*- FL
13	1		*FRONT GRILLE BASE	Cracked	380.90 FL	*380.90 FL
14	1		*FRONT GRILLE CHROME MOULDING - TOP	Not Necessary	361.90 FL	*- FL
15	1		*FRONT GRILLE CHROME MOULDING - LOWER	Not Necessary	186.60 FL	*- FL
16	1		*FRONT GRILLE LOGO	Not Necessary	89.90 FL	*- FL
17	1		*FRONT HEADLAMPS - L/R	O/S Cracked	5,265.00 FL	*2,433.60 FL
18	2		*FRONT HEADLAMP CHROME MOULDINGS	Not Necessary	391.20 FL	*- FL
19	2		*FRONT HEADLAMP LOWER BRACKETS	Not Necessary	179.20 FL	*- FL
20	2		*FRONT HEADLAMP SIDE GARNISHES	Not Necessary	117.20 FL	*- FL
21	1		*FRONT SUPPORT PANEL LOWER PANEL	Badly Dented	741.50 FL	*399.50 FL
22	1		*AIR CON CONDENSER	Not Necessary	891.90 FL	*- FL
23	1		*WASHER TANK	Not Necessary	196.60 FL	*- FL
24	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
25	1		*SET FRONT GRILLE CLIP	Not Necessary	30.00 FS	*- FS
26	1		*FRONT NO. PLATE	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,649.30	5,416.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,702.86	1,074.20
Total Parts (\$\$)	10,946.44	4,341.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE, REFIX A/C CONDENSER & REFILL A/C GAS	New	180.00	0.00
3	TO RESPRAY UNDERCOATING	New	60.00	30.00
4	TO RESPRAY PAINTING AND ETC	New	1,200.00	700.00
5	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	1,050.00	550.00
Gross Labour Cost (\$\$)			2,540.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >