

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006522/KEA3Q2
Date: 15/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100459192
Claimant Vehicle No :	SMQ6285L	Insured Vehicle No :	SLB2356H
Date of Loss:	18/06/2020	Nature of Claim:	TP
		Claim No:	5031014962SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ6285L	Engine No:	2NR5400561
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR2B23F3601191769
Reg. Date:	27/11/2019 (Man. Year: 2019)	Odometer:	30833 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	954.00	804.00	150.00	15.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,160.00	750.00	410.00	35.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,114.00	1,554.00	560.00	26.49
+ GST 7.00/7.00% (S\$)	147.98	108.78	39.20	26.49

Nett Amount (S\$)	2,261.98	1,662.78	599.20	26.49
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,904.78		

INSPECTION

Date of Assignment: 22/06/2020

Date Inspected: 22/06/2020

Estimated Period of Repair: 3.0 days

Inspected At:

City Auto Pte Ltd (Sin Ming) (HQ)
 Block 8 Sin Ming Road #01-58/60/62 Sin Ming Est
 Singapore 575643

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	630.10 FL	*630.10 FL
2	6		*REAR BUMPER CLIPS	Necessary	25.26 FL	*25.26 FL
3	1		*REAR BOOT LOGO	Necessary	51.95 FL	*51.95 FL
4	1		*REAR BOOT EMBLEM -VIOS	Necessary	48.33 FL	*48.33 FL
5	1		*REAR BOOT EMBLEM -E	Necessary	49.70 FL	*49.70 FL
6	1		*REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,155.34	1,005.34
- List Item Discount on L Items 25.00/25.00% (\$)	201.34	201.34
Total Parts (\$)	954.00	804.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO INSTALL REVERSE SENSOR	New	60.00	50.00
2	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS	New	500.00	300.00
3	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	600.00	400.00
Gross Labour Cost (\$\$)			1,160.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >