

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20006532/UBS3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00005587

Claimant
Vehicle No : FBM138U **Insured Vehicle No :** SJD9954Z

Date of Loss: 10/03/2020 Nature of Claim: TP Claim No: 1202000012378

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM138U	Engine No:	104EA45168063
Make & Model:	ADIVA AD1 200, 190cc 3W	Chassis No:	WB10D500XHZ700355
Reg. Date:	25/11/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Red/White		
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70Z R17	Rear Tyre Size:	190/55Z R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	72,427.83	34,253.65	38,174.18	52.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,110.00	885.00	1,225.00	58.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	74,537.83	35,138.65	39,399.18	52.86
Approved Total (Overridden) (\$\$)		28,000.00		
Nett Amount (\$\$)	74,537.83	28,000.00	46,537.83	62.44
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 22/06/2020

Date Inspected: 22/06/2020 Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)
1 KAKI BUKIT AVE 6 #02-62
Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Feb 2021)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBM138U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT FORK LEG -R/H	Not Necessary	2,077.00 FL	*- FL
2	1	*FRONT FORK LEG -L/H	Not Necessary	2,077.00 FL	*- FL
3	1	*LOWER FORK CROSS BRACE	Bent	1,930.00 FL	*1,930.00 FL
4	1	*FORK BRIDGE COVER	Bent	62.00 FL	*62.00 FL
5	2	*BEARING	Not Necessary	442.00 FL	*- FL
6	1	*COVERING PLATE	Broken	27.00 FL	*27.00 FL
7	1	*UPPER FORK CROSS BRACE	Cracked	1,575.00 FL	*1,575.00 FL
8	2	*FORK TUBE WITH SLIDER SLEEVES ,GOLD	Dented / Bent	6,126.00 FL	*6,126.00 FL
9	2	*SET FORK OIL SEAL & DUST COVER	Not Necessary	592.00 FL	*- FL
10	1	*FRONT RIM BLACK	Repair	3,857.00 FL	*- FL
11	1	*FRONT RIM SHAFT	Not Necessary	525.00 FL	*- FL
12	2	*FRONT RIM BEARING	Not Necessary	100.00 FL	*- FL
13	1	*FRONT RIM DUST COVER	Not Necessary	60.00 FL	*- FL
14	1	*FRONT BRAKE DISC	Bent	1,562.00 FL	*1,562.00 FL
15	1	*WIDSHIELD	Cracked	466.00 FL	*466.00 FL
16	1	*FRONT WHEEL COVER	Distorted	512.00 FL	*512.00 FL
17	1	*STEERING DAMPER	Damaged	1,789.00 FL	*1,789.00 FL
18	1	*HANDLE BAR -R/H	Bent	871.00 FL	*871.00 FL
19	1	*FRONT PANEL CARRIER	*Check	758.00 FL	*- FL
20	2	*MIRRORS -R/LH	N/S Missing/ O/S Cut	830.00 FL	*830.00 FL
21	1	*HEAD LAMP -R/H	Broken	1,391.00 FL	*1,391.00 FL
22	1	*HEAD LAMP -L/H	Broken	1,445.00 FL	*1,445.00 FL
23	1	*HEAD LAMP COVER	Broken	45.00 FL	*45.00 FL
24	2	*BULB H7/55W	Not Necessary	84.00 FL	*- FL
25	1	*REAR SIGNALS-R/LH	O/S Cracked	326.00 FL	*163.00 FL
26	2	*ISA SCREW	Not Necessary	16.00 FL	*- FL
27	2	*HEX NUT	Not Necessary	8.00 FL	*- FL
28	1	*AIR DUCT	Cracked	796.00 FL	*796.00 FL
29	1	*RADIATOR	Punctured	2,759.00 FL	*2,759.00 FL
30	1	*EXPANSION TANK	Torn	172.00 FL	*172.00 FL
31	1	*OIL COOLER	Twisted / Punctured	2,166.00 FL	*2,166.00 FL
32	1	*HANDLE -BAR WEIGHT	Scratched	139.00 FL	*139.00 FL
33	1	*BRAKE LEVER	Scratched	458.00 FL	*458.00 FL
34	1	*FAN	*Check	1,248.00 FL	*- FL
35	2	*FRONT TOP FAIRING -R/LH	Broken	1,332.00 FL	*1,332.00 FL
36	2	*FRONT SIDE FAIRING -R/LH	Broken	1,912.00 FL	*1,912.00 FL
37	2	*FRONT SIDE TRIM PANEL -R/LH	*Check	650.00 FL	*- FL
38	2	*FRONT SIDE LOWER COVER -R/LH	Broken	1,962.00 FL	*1,962.00 FL
39	1	*TANK FRONT COVER	Cracked	451.00 FL	*451.00 FL
40	1	*FRONT CENTRE AIR INTAKE	*Check	796.00 FL	*- FL
41	2	*FRONT SIGNALS-R/LH	Cracked	478.00 FL	*478.00 FL
42	1	*FRONT FOOTREST -R/H	Serviceable	1,682.00 FL	*- FL
43	1	*EXPANDING RIVET	Necessary	7.50 FL	*7.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	4		*PLUG IN RETAINER	Not Necessary	13.20 FL	*- FL
45	4		*SELF LOCKING PLUG NUT	Not Necessary	40.00 FL	*- FL
46	2		*PIN	Not Necessary	18.00 FL	*- FL
47	1		*HEAT SHIELD -R/LH	Repair	74.00 FL	*- FL
48	1		*EXHAUST PIPE ASSY	Dented / Bent	5,520.00 FL	*5,520.00 FL
49	1		*EXHAUST MANIFOLD WITH FRONT MUFFLER	*Check	8,400.00 FL	*- FL
50	1		*SWITCHING VALVE	*Check	640.00 FL	*- FL
51	1		*FUEK TANK	Repair	5,977.00 FL	*- FL
52	1		*THROTTLE COVER	Cracked	1,102.00 FL	*1,102.00 FL
53	1		*HEADLAMP TRIM	*Check	884.00 FL	*- FL
54	1		*CONTROL UNIT WITH EWS DATA	Not Necessary	6,200.00 FL	*- FL
55	1		*SET WIRING HARDNESS	Repair	2,038.00 FL	*- FL
56	1		*FRONT PANEL CARRIER	*Check	380.00 FL	*- FL
57	1		*FOOTREST -R/H	Not Necessary	318.00 FL	*- FL
58	1		*STOPPER	Not Necessary	31.00 FL	*- FL
59	1		*BRAKE PEDAL	Not Necessary	650.00 FL	*- FL
60	1		*THROTTLE GRIP	*Check	967.00 FL	*- FL
61	1		*AIR INLET DUCT	*Check	405.00 FL	*- FL
62	1		*SET NUMBER PLATE	Necessary	28.00 FS	*10.00 FS
63	1		*BADGE	*Check	203.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	80,449.70	38,058.50
- List Item Discount on L Items 10.00/10.00% (S\$)	8,021.87	3,804.85
Total Parts (S\$)	72,427.83	34,253.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING	New	50.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO SET CONTROL UNIT (*Check)	New	800.00	0.00
4	TO RESPRAY PAINTING	New	680.00	450.00
5	TO PROVIDE LABOUR	New	500.00	400.00
Gross Labour Cost (\$\$)			2,110.00	885.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >