

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006538/KES3N2

Date: 19/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800128275-01

Claimant
Vehicle No : SLA8423M **Insured Vehicle No :** SKC535C

Date of Loss: 19/06/2020 Nature of Claim: TP Claim No: 5539414451SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA8423M		
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Engine No:	G4FGGU118160
Reg. Date:	18/03/2016 (Man. Year: 2016)	Chassis No:	KMHD841CMHU099406
Colour:	Metallic Grey	Odometer:	53779 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,249.60	438.00	811.60	64.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,240.00	480.00	760.00	61.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,489.60	918.00	1,571.60	63.13
+ GST 7.00/7.00% (\$\$)	174.27	64.26	110.01	63.13
Nett Amount (\$\$)	2,663.87	982.26	1,681.61	63.13
+ Loss of Use (2.0 x S\$80.00/day) (\$\$)		160.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		1,144.26		

INSPECTION

Date of Assignment: 22/06/2020

Date Inspected: 29/06/2020 Inspected At:

Kgc Workshop Pte Ltd (AMK)
14 Ang Mo Kio Street 63, Blk B
Singapore 569116

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	680.00 FL	*485.00 FL
2	2		*REAR BUMPER RETAINER	Serviceable	88.60 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Serviceable	320.80 FL	*- FL
4	2		*REAR TAIL LIGHT REFLECTOR	Serviceable	97.60 FL	*- FL
5	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
6	1		*NO .PLATE WITH CASING	Serviceable	50.00 FS	*- FS
7	1		*SET REVERSE SENSOR	Serviceable	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,487.00	535.00
- List Item Discount on L Items 20.00/20.00% (\$)	237.40	97.00
Total Parts (\$)	1,249.60	438.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE ,REPLACE ,CUT ,WELD ,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PARTS INCLUSIVE OF REPLACEMENT PARTS	New	500.00	200.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS	New	500.00	220.00
3	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME	New	80.00	10.00
4	APPLY RUST PROOFING ON THE ADJACEMENT PANELS	New	80.00	0.00
5	REMOVE AND INSTALL REVERSE SENSOR	New	80.00	50.00
Gross Labour Cost (\$\$)			1,240.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >