

ASS. REC. BY:

REF:

AIG / 20006538/Ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

KGC

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

Aster 11an

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLA 8423m Yr Regn: 03, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra c.c. 1591

Colour:

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

5377P

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM140841CM14U099406

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

J

mm

R/Bal.

J

mm

L/Bal.

J

mm

L/Bal.

J

mm

D.O.A.

19/6/20

D.O.I.

29/6/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/7

@ 918.00

Car burnt

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfaction

Not Withstand
Resurvey After Painting
4 days @ 918.00
2 days

Soong Weng Chung, Jeffrey
14 Ang Mo Kio St 63
Block B
Singapore 569116

TP 200602
Date 22/6/2020
No of Page : 1/2

Registration No : SLA 8423M
Accident Date : 19-Jun-20
Our Ref : TP 200602

Model : Hyundai Elantra 1.6
Chassis No: KHMD841CMHU099406
Engine Capacity : 1591

S/No	Qty	Items	Unit Price	Amount
1	1	Rear bumper <i>485</i>	\$ 680.00	\$ <i>Ben</i> 680.00 ✓
2	2	Rear bumper retainer	\$ 44.30	\$ <i>Ben</i> 88.60 X
3	1	Rear bumper reinforcement	\$ 320.80	\$ <i>Ben</i> 320.80 X
4	2	Rear tail light reflector	\$ 48.80	\$ <i>Ben</i> 97.60 ✓
				\$ 1,187.00
				-20% \$ 237.40
Total for spare parts				\$ 949.60

Special Nett

1	1 set	Rear Bumper Clips	\$ 50.00	\$ <i>Ben</i> 50.00 ✓
2	1	No. Plate with Casing	\$ 50.00	\$ <i>Ben</i> 50.00 X
3	1 set	reverse sensor	\$ 200.00	\$ <i>Ben</i> 200.00 X
Total for SP				\$ 300.00
Sub-Total for Parts :				\$ 1,249.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfaction

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.		500.00 <i>200/</i>
2		To putty and spray paint on all accident damage parts and other accident affected areas		500.00 <i>220/</i>
3		To check wiring system to facilitate repair and refit the same		80.00 <i>10/</i>
4		Apply rust proofing on the adjacent panels		80.00 <i>nn X</i>
5		Remove and install reverse sensor		80.00 <i>50/</i>
			TOTAL AMOUNT :	<u>1,160.00</u>
			OVERALL COST :	<u>2,409.60</u>