Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20006541/EGS3Q2

Date: 26/08/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2020-00003850

Claimant Vehicle No:

SKZ1853G Insured Vehicle No: SLW6144R

Date of Loss: 19/06/2020 ΤP Nature of Claim: Claim No: 1202000018589

DESCRIPTION & IDENTIFICATION OF VEHICLE

SKZ1853G Reg No:

Make & Model: HYUNDAI ELANTRA, 1.6 D/AB 2WD 4DR (A) Engine No: G4FGFU057480

Chassis No: Reg. Date: 13/01/2016 (Man. Year: 2015) KMHDH41CMGU653449

Colour: Odometer: 90200 km Silver

Engine Capacity: 1591 cc Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16 Nexen 5 mm Front Left Side: Rear Left Side: Nexen 5 mm Front Right Side: Rear Right Side: Nexen 5 mm Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,920.80	1,310.00	4,610.80	77.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,680.00	860.00	1,820.00	67.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,600.80	2,170.00	6,430.80	74.77
Approved Total (Overridden) (S\$)		1,750.00		
Nett Amount (S\$)	8,600.80	1,750.00	6,850.80	79.65
+ Car Rental (4.0 x S\$1	00.00/day) (S\$)	400.00		
+ Doc/S	earch Fee (S\$)	7.45		
Ne	tt Liability (S\$)	2,157.45		
Global Sum S	Settlement (S\$)	2,100.00		

INSPECTION

Date of Assignment: 22/06/2020

Date Inspected: 23/06/2020 Inspected At: My Car Consultant Pte Ltd (Ubi)

53 Ubi Ave 1, #01-33, Paya Ubi

Industrial Park Singapore 408934

Estimated Period of Repair: 3.0 days Adjuster Report Page 2 of 4

Adjuster: CHEN TSUE YEE Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Jul 2020)

Parts: 143 HYUNDAI ELANTRA 1.6 D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKZ1853G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented 560.00 FL		*480.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Broken 364.00 Fl		*364.00 FL
3	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Bent	18.00 FL	*18.00 FL
4	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Not Necessary	18.00 FL	*- FL
5	1		*REAR BUMPER LOWER SPOILER	Cut	251.00 FL	*251.00 FL
6	1		*REAR BUMPER REFLECTOR LH	Cut	45.00 FL	*45.00 FL
7	1		*REAR BUMPER REFLECTOR RH	Not Necessary	45.00 FL	*- FL
8	1		*REAR BOOTLID	Not Necessary	1,840.00 FL	*- FL
9	1		*REAR BOOTLID INNER TRIM BOARD	Not Necessary	125.00 FL	*- FL
10	1		*REAR BOOTLID LAMP LH	Not Necessary	299.00 FL	*- FL
11	1		*REAR BOOTLID LAMP RH	Not Necessary	299.00 FL	*- FL
12	1		*REAR BOOTLID EMBLEM ELITE	Not Necessary	68.00 FL	*- FL
13	1		*REAR BOOTLID EMBLEM LOGO	Not Necessary	39.00 FL	*- FL
14	1		*REAR BOOTLID EMBLEM ELANTRA	Not Necessary	48.00 FL	*- FL
15	1		*REAR END PANEL	Repair	455.00 FL	*- FL
16	1		*REAR END PANEL TOP GARNISH	Not Necessary	85.00 FL	*- FL
17	1		*REAR BOOTLID LOCK	Not Necessary	135.00 FL	*- FL
18	1		*REAR TAILLAMP LH	Not Necessary	388.00 FL	*- FL
19	1		*REAR TAILLAMP INNER PANEL LH	Not Necessary	172.00 FL	*- FL
20	1		*REAR TAILLAMP RH	Not Necessary	388.00 FL	*- FL
21	1		*REAR TAILLAMP INNER PANEL RH	Not Necessary	172.00 FL	*- FL
22	1		*REAR WEATHER STRIP	Not Necessary	95.00 FL	*- FL
23	1		*SET REAR REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
24	1		*SET REAR REVERSE CAMERA	Not Necessary	300.00 FS	*-FS
25	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
26	1		*SET REAR BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	80.00 FS	*- FS
27	1		*SET REAR END PANEL GARNISH CLIP	Not Necessary	30.00 FS	*- FS
28	1		*FLOOR PANEL SEALANT	Not Necessary	50.00 FS	*- FS
29	1		*END PANEL SEALANT	Not Necessary	50.00 FS	*-FS
30	1		*MISCELLANEOUS	Not Necessary	200.00 FS	*-FS
31	3		*REAR BUMPER LOWER BRACKET	Broken	84.00 FL	*84.00 FL
32	1		*REAR BUMPER UNDER GARNISH /COVER	Crushed	108.00 FL	*108.00 FL
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	7 141 00	1 580 00

 Sub Total (S\$)
 7,141.00
 1,580.00

 - List Item Discount on L Items 20.00/20.00% (S\$)
 1,220.20
 270.00

Condition

Danairar'a

Total Parts (S\$) 5,920.80 1,310.00

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	TO CHECK ELECTRICAL WIRING	New	80.00	30.00					
2	TO REMOVE AND REFIT REVERSE SENSOR /CAMERA	New	150.00	0.00					
3	CHECK AND TEST FOR WATER LEAKAGE	New	150.00	0.00					
4	REMOVE AND TRANSFER ALL REAR BOOTLID FITTING	New	150.00	0.00					
5	TO RESPRAY UNDERCOATING	New	150.00	0.00					
6	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	30.00					
7	SPRAY PAINTING ON AFFECTED AREAS	New	800.00	400.00					
8	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	400.00					
	Gross Labour Cost (S\$)		2,680.00	860.00					

Report was unsubmitted during this print-out.

< END OF ESTIMATES >