

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006552/KRS3Q2
Date: 08/12/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700057853
Claimant Vehicle No :	SBR7M	Insured Vehicle No :	SCP3939C
Date of Loss:	21/04/2020	Nature of Claim:	TP
		Claim No:	1299053101SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBR7M		
Make & Model:	MERCEDES-BENZ E220, 2.0 (A)	Engine No:	65492080026096
Reg. Date:	28/02/2017 (Man. Year: 2016)	Chassis No:	WDD2130042A046614
Colour:	Metallic Grey	Odometer:	49115 km
Engine Capacity:	1950 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R19	Rear Tyre Size:	275/35 R19
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,945.70	2,528.70	417.00	14.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,120.00	1,130.00	990.00	46.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,065.70	3,658.70	1,407.00	27.78
+ GST 7.00/7.00% (S\$)	354.60	256.11	98.49	27.77

Nett Amount (S\$)	5,420.30	3,914.81	1,505.49	27.78
+ Car Rental (4.0 x S\$140.00/day + 7.00% GST) (S\$)		599.20		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,516.01		
Global Sum Settlement (S\$)		4,500.00		

INSPECTION

Date of Assignment: 23/06/2020

Date Inspected: 23/06/2020

Inspected At:

Chew Goon Motor (AMK)

Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Bent	2,470.00 FL	*2,185.00 FL
2	1		*REAR DOOR WEATHERSTRIP	Necessary	398.00 FL	*318.00 FL
3	1		*REAR DOOR STICKER	Necessary	75.00 FL	*75.00 FL
4	1		*REAR DOOR INNER INSULATION	Necessary	148.50 FS	*60.00 FS
5	1		*REAR DOOR PANEL RIVETS (14 PCS)	Necessary	60.00 FL	*60.00 FL
6	1		*REAR DOOR FRAME RUBBER SEAL	Necessary	105.00 FL	*105.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,256.50	2,803.00
- List Item Discount on L Items 10.00/10.00% (\$)	310.80	274.30
Total Parts (\$)	2,945.70	2,528.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT ELECTRICAL CHECK	New	30.00	20.00
2	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL	New	80.00	0.00
3	TO DISMANTLE /TRANSFER DOOR FITTINGS /ANCILLARY ACCESSORIES	New	160.00	60.00
4	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF REAR FENDER ARCH PANEL ,ROCKER SKIRT ,AND PARTS REPLACEMENT	New	400.00	250.00
5	TO RESPRAY AFFECTED AREAS	New	1,000.00	600.00
6	TO RESEAL PAINT PROTECTION (DIAMONDBRITE) TO SPRAY PAINT AREAS	New	450.00	200.00
Gross Labour Cost (S\$)			2,120.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >