

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/TMI20006554/T1QF3E2

**Date:** 03/07/2020

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MK000857

**Claimant Vehicle No :** SHC7806K

**Insured Vehicle No :** SJS9155J

Date of Loss: 20/06/2020

Nature of Claim: TP

Claim No: M2003085

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC7806K**

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)

Engine No: G4LEKU299953

Reg. Date: 06/08/2019 (Man. Year: 2019)

Chassis No: KMHCH851CVKU165203

Colour: Yellow

Odometer: 0 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

Good

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,313.24	4,000.28	312.96	7.26
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,710.00	1,360.00	350.00	20.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,034.24</b>	<b>5,371.28</b>	<b>662.96</b>	<b>10.99</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>422.40</b>	<b>375.99</b>	<b>46.41</b>	<b>10.99</b>
<b>Nett Amount (S\$)</b>	<b>6,456.64</b>	<b>5,747.27</b>	<b>709.37</b>	<b>10.99</b>

### INSPECTION

Date of Assignment: 23/06/2020 Present Location:

ComfortDelGro Engineering Pte Ltd  
(Loyang)

Date Inspected: 22/06/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jul 2020)
<b>Parts:</b>	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC7806K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER COVER	Deformed	459.40 FL	-	*459.40 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Cracked	451.25 FL	-	*451.25 FL
4	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	55.80 FL	-	*- FL
5	1		*REAR BUMPER MOULDING LOWER	Deformed	155.00 FL	-	*155.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	294.80 FL	-	*294.80 FL
7	1		*REAR BUMPER STAY RH	Not Necessary	138.10 FL	-	*- FL
8	1		*REAR BUMPER TOWING COVER	Not Necessary	98.80 FL	-	*- FL
9	1		*REAR FOG LAMP ASSY	Cracked	201.50 FL	-	*201.50 FL
10	1		*LICENSE PLATE LAMP LH	Distorted	60.40 FL	-	*60.40 FL
11	1		*REAR BOOTLID ASSY	Bent	2,480.40 FL	-	*2,480.40 FL
12	1		*REAR BOOTLID EMBLEM IONIQ	Necessary	31.30 FL	-	*31.30 FL
13	1		*REAR BOOTLID EMBLEM HYBRID	Necessary	24.30 FL	-	*24.30 FL
14	1		*REAR WINDSCREEN MOULDING	Not Necessary	48.50 FL	-	*- FL
15	2		*REAR WINDSCREEN GLASS SEALANT	Necessary	46.00 F	-	*46.00 F
16	1		*REAR BOOTLID ADVERTISEMENT LOGO	Necessary	100.00 F	-	*100.00 F
17	1		*REAR FENDER ADVERTISEMENT LOGO RH	Necessary	100.00 F	-	*100.00 F
18	1		*REAR FENDER ADVERTISEMENT LOGO LH	Necessary	100.00 F	-	*100.00 F
19	1		*REAR BOOTLID APP LOGO	Necessary	40.00 F	-	*20.00 F
20	1		*REAR BOOTLID COMFORTDELGRO & TEL NO STICKER	Necessary	30.00 F	-	*10.00 F
21	1		*REAR NUMBER PLATE WITH TRIM COVER	Cracked	50.00 F	-	*50.00 F
22	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 F	-	*50.00 F
23	1		*REAR BUMPER REVERSE SENSOR	Not Working	180.00 F	-	*180.00 F

F=Franchise part. L=ListItemDisc.

**Sub Total (\$\$)**    **5,217.55**    **4,836.35**  
**- List Item Discount on L Items 20.00/20.00% (\$\$)**    904.31    836.07

**Total Parts (\$\$)**    **4,313.24**    **4,000.28**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	800.00	640.00
2	SPRAY PAINTING CHARGE	New	450.00	450.00
3	WIRING CHARGE	New	50.00	30.00
4	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
5	TUFF KOTE	New	50.00	30.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	240.00	180.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,710.00</b>	<b>1,360.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >