

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6907C**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DEFORMED	1,106.00	1,106.00
1	REAR BUMPER UNDER COVER	CUT	228.00	228.00
1	REAR BUMPER REFLECTOR LH	CRACKED	32.00	32.00
1	TAILLAMP LH	NOT NECESSARY	697.80	-
	LESS 20% DISCOUNT		-412.76	-273.20
			1,651.04	1,092.80
	<b><u>NETT ITEMS</u></b>			
1	REVERSE SENSOR (N)	NOT NECESSARY	135.70	-
	LESS 10% DISCOUNT		-13.57	-
			122.13	-
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BUMPER MAT (SN)	CUT	50.00	50.00
			50.00	50.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		300.00	280.00
	SPRAY PAINT CHARGE.		250.00	200.00
	R/I REVERSE SENSOR.		120.00	30.00
			670.00	510.00
	<b>GRAND TOTAL</b>		<b>2,493.17</b>	<b>1,652.80</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>1,300.00</b>

Report Ref No. NS/INC20006555/T1yf3e2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.